


Components

- Make sure to check the components below before installation.




Before Work

- When installing this product, park the car on a level ground and apply the parking brake.
- When installing this product, be sure not to damage the car body.
- Before installing this product, wipe off any dirt or oil film from the Side Spoiler attachment surface with a soft waste cloth dampened in a neutral detergent. Then, let it dry completely before work.
- The adhesive strength is weakened significantly when the temperature is low.
 In this case, use a dryer to warm up the double-sided tape before attachment.
 (Do not warm excessively as doing so may result in deformation.)
- Be extremely careful not to let this product get wet by washing, etc. for 24 hours after attaching it. Dosing so may cause the product to come off.
- To protect yourself from burns, make sure to stop the engine and let it cool completely before work.
- When jacking up the vehicle, be sure to keep the ground level and a hard place where the jack does not bite, and be sure to support it with a rigid rack before carrying out the work.


▲ Caution

When jacking up the vehicle, be sure to place it on a hard surface where the ground is horizontal and the jack does not bite into it, and be sure to support it with a rigid rack before performing the work.



Installation procedure

1. Removal of Spoiler assy-side



2. Drill holes in the Spoiler assy-side

LH

 $3\text{mm} \rightarrow 7\text{mm}$

/NG;

Spoiler assy-side

2

Bottom view

16/


 $\stackrel{<}{<}$ Detail view a >


Locator center


(The RH also performs the same work.)

(1) Refer to the service manual and remove the Spoiler assy-side from the vehicle.


(1) As shown in Fig. 2, mark the center of the lower surface locator a on the rear end of the Spoiler assy-side with a marking needle or the like. After that, drill a 3mm pilot hole, then a 7mm hole. (1 places each for LH and RH, 2 places in total) Advice After drilling, remove the burrs around the hole. (2) Cover the 7mm hole with masking tape so that it is not mistaken for the 9.5mm hole LH Masking tape JUp 7mm hole Advice To prevent the drill from interfering with other parts when drilling, make a stopper with cloth adhesive tape, etc., at a point about 5 mm from the tip of the drill before working. Drill 5mm cloth adhesive tape








5. Restore the Spoiler assy-side



(6) Fully tighten ③ Bolt on the bottom surface of ① STI Side Under Spoiler with a torque wrench.

(9 places each for LH and RH, 18 places in total)



Reference tightening torque 1.0N · m (0.1kgf · m)

- (7) Finally, check the float of the mounting part, make sure that there are no missing Clips or Bolts, or forget to tighten them, and visually check the condition of ② Wellnut from the back side.
- (1) Refer to the service manual and restore the Spoiler assy-side to the vehicle.

This is the end of the work.

Explanation to customers

- We do not accept warranty repairs such as scratches, discoloration of paint, and peeling that occur during use.
- By installing this product, it is up to 18mm lower than the Spoiler assy-side.
- Because it is easy to come into contact with curbs, ring clasps, steps, etc.
 Be careful not to touch it while driving or parking.
 If it comes in contact with it, it may be scratched, deformed, damaged or dropped, and the spoiler may be damaged accordingly.
- In the case of slight contact, you may not notice the contact, so be sure to perform a pre-operation inspection and check the area around the mounting part in particular.
- Also, running in snow or ruts may damage the spoiler, deform it, drop it off, or damage the vehicle. Damage caused by these or equivalent external forces is not covered by the warranty.
- By installing this product, it is easier to get on and off than the standard Spoiler assy-side. If you get your feet caught, you may get injured. Also, it is scratched, deformed, damaged, dropped or dropped.

Please be careful when getting on and off as it may cause damage to the vehicle.

Revised contents

| | Details of the work | Date |
|----|------------------------|----------------|
| 00 | Newly created document | 6 / Dec / 2022 |
| | | |
| | | |
| | | |

