



PART NUMBER: L101SAN000

OUTBACK TRAILER HITCH

This card should be stored in the vehicle glove box and handed over with the vehicle if sold.

NOTICE:

Electric Trailer Brakes: Customers towing over 1,000 lbs and using a trailer with electric brakes must purchase and install an electric brake controller and harness. The electric brake controller and harness are not available from Subaru.

1. Do not drill, cut, weld or otherwise modify the Trailer Hitch.
2. If Trailer Hitch is removed, a bumper beam **MUST** be reinstalled. Failure to reinstall a bumper beam after removal of the trailer hitch will negatively affect vehicle rear crash performance. Please contact your SUBARU dealer.
3. When a Trailer Hitch is installed, it is not possible to install the rear towing hook.
4. Never exceed the maximum towing capacity and maximum tongue load for the trim level detailed on the trailer hitch and the owner's manual. It could cause personal injury and/or vehicle damage.
5. When towing, total vehicle weight must not exceed the Gross Vehicle Weight Rating (GVWR). Also the load distribution on each axle must not exceed the Gross Axle Weight Rating (GAWR). The GVWR and GAWR for your vehicle can be found on the "Certification label" which is located on the left side center pillar of the vehicle.
6. After the first 600 miles, please consult with Subaru dealer to recheck the tightness of trailer hitch bolts and nuts.
7. For models equipped with BSD (Blind Spot Detection) and RCTA (Rear Cross Traffic Alert) driving support systems, when towing a trailer press BSD/RCTA OFF switch to deactivate the systems. The system may not operate properly due to blocked radar waves. For details about BSD/RCTA OFF switch, refer to the owner's manual "BSD/RCTA OFF switch".
8. For models equipped with RAB (Reverse Automatic Braking) system, please consult with SUBARU dealer when towing a trailer.
9. For further information, read vehicle owner's manual or consult your dealer or dealer's service department.
10. Subaru accepts no liability for product defects caused by incorrect use.