

Technical Service Bulletin (TSB)
Flash: Electronic Shift Module (ESM) Updates

REFERENCE:	TSB: 08-226-26 GROUP: 08 - Electrical	Date:	May 29, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on or before May 26, 2026 (MDH 0526XX) equipped with a Rotary Shifter-Bright (Sales Code C1H) or Rotary Shifter-Jeweled (Sales Code C1N) or Rotary Shifter-Black (Sales Code C1G).			MARKET APPLICABILITY: ☒ NA ☒ MEA ☒ SA ☒ IAP ☒ EE ☐ CH NOTE: This bulletin applies to the North America, Enlarged Europe, Middle East & Africa, India & Asia Pacific and South America markets.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): - P0607-00 - ECU Internal Performance. NOTE: DTC P0607-00 will be stored in the Automatic Gearbox Shifter Module (AGSM)/Electronic Shift Module (ESM). - P1DF3-00 - ECU Not Initialized. NOTE: DTC P1DF3-00 will be stored in the Transmission Control Module (TCM). Customers may also comment on one or more of the following: - Shifter not able to move out of Park with "Service Shifter" message showing on Instrument Panel Cluster (IPC). - PRNDL lights flashing.				
CAUSE:	ESM software				

REPAIR SUMMARY:

This bulletin involves reprogramming the ESM with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-15-9J	Module, Electronic Shift - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or equivalent	-	-

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the ESM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.