

Technical Service Bulletin

Transaction No.:
2081746/1

72-26-02 – Seat Memory Inop, Update Programming DTC B135354 and/or B201000
in Driver Seat Memory Module

Condition

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	PR Number (s)
ID.4	2023-2025	All	All	E8_PC000001	E8_SC018484	3PR + Without NI9

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2081746/1	5/8/2026	72-26-02	Original Publication

NOTICE

Make sure that a suitable 12V battery charger (VAS 5908 or equivalent with 100 amp capability) is connected to support the 12V battery.

NOTICE

DO NOT diagnose or replace components before performing the update function as explained in this bulletin.

NOTICE

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with VHW-22-13 Change Power Options in Windows® 10 (or latest communication). Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160 /X tester in conjunction with a VAS 6154A or 6154B wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

- VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

Technical Background

Model year 2023-2025 ID.4 models will store DTC B135354 and/or B201000 in AW 0036 for seat adjustment motor no basic settings & will cause the seat memory function to become inoperative.

Production Solution

Parameterization improvements to the software which were introduced into production.

Service

Please proceed to the "Update-Programming Procedure:" step below.

Update-Programming Procedure:

Update the Driver Seat Memory Module software using the SVM Unit code as listed in the table below, road test vehicle after software update to confirm seat memory operation.



NOTICE

Basic settings may be lost for all seat axis. If this occurs, please set basic settings.

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
ID.4	ALL	1EB959760H	0562	No Change	No Change	5088

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



NOTICE

When performing a software configuration update, the test plan function must be used.



WARNING

Critical Warning: The battery charger must be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process and should monitor the voltage for the duration of the update.

- The procedure may cancel itself if the hazard warning lights are not switched ON. The hazard warning lights prevent the system from switching to bus sleep mode during the update.
- ODIS-Service tester should be updated to the latest GFF technical version 25.2.1 or higher and SW version 2.55.1 or higher.



CAUTION

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

- Keep hands and all objects away from Radiator Fan(s) during Update Process!

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾						
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To	PR Number(s)
ID.4	2023-2025	All	All	E8_PC000000	E8_SC018484	3PR + Without NI9
SAGA Coding						
Claim Type:	Use applicable Claim Type ¹⁾					
Service Number:	Damage Code	HST			Damage Location (Depends on Service No.)	
7293	0039	--			Use applicable when indicated in Elsa (L/R)	
Parts Manufacturer		ID.4 (MY23-24)		WWO ²⁾		
		ID.4 (MY25)		VOA ²⁾		
Labor Operation ³⁾ : GFF/ Guided functions (including Battery charge)			01500010 = See Elsa for latest time units			
Labor Operation ³⁾ : Update Programming Seat Control Module			See GFF Time expenditure			
Diagnostic Time ⁴⁾						
GFF Time expenditure					YES	

	01500060 = Actual GFF print out with a max of 50TUs	
Road Test	01210002 = see Elsa for latest time units 01210004 = see Elsa for latest time units	NO
Technical Diagnosis	01320000 = 00 TU max.	NO
Claim Comment: Input "As per Technical Bulletin 2081746 in comment section of Warranty Claim.		
1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only. 2) Code per warranty vendor code policy. 3) Labor Time Units (TUs) are subject to change with ELSA updates. 4) Documentation required per Warranty Policies and Procedures Manual.		

Required Parts and Tools

No Special Parts required.

Tool Description	Tool No:
Battery Maintainer	VAS5908 battery maintainer
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X ODIS Service with current online updates

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2026 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.