



HYUNDAI

Technical Service Bulletin


GROUP BODY ELECTRICAL	NUMBER 26-BE-015H
DATE JUNE 2026	MODEL(S) SEE BELOW

SUBJECT: NOISY DRIVER FRONT SEAT MOTOR – TUBE REMOVAL

★ IMPORTANT

This field action requires both a reported condition consistent with the symptoms outlined in this TSB and dealer confirmation of those symptoms before any repair work is performed. If requirements are not met, any submitted claims are subject to debit. 5 / 60,000 New Vehicle Limited Warranty applies. See Warranty Information section for more details.

Description: Some Santa Fe (MX5A) and Santa Fe Hybrid (MX5A HEV) vehicles equipped with power seats with or without Integrated Memory System (IMS) may produce buzz, squeak, rattle noises when the driver's front seat is adjusted forward or backwards due to friction within the motor's tube. This bulletin provides instructions to remove the motor tube.



Applicable Vehicles:

Model Year	Model	Production Dates
2025 – 2026	Santa Fe (MX5A)	03/05/2025 – 11/06/2025
	Santa Fe Hybrid (MX5A HEV)	

SUBJECT:**NOISY DRIVER FRONT SEAT MOTOR – TUBE REMOVAL****Warranty Information:**

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Santa Fe (MX5A)	60DA04R0	Remove Slide Motor Tube (Power)	0.3 M/H	886A1-L1000	Q65	ZZ1
Santa Fe Hybrid (MX5A HEV)	60DA04R1	Remove Slide Motor Tube (IMS)		886A3-L1000		

NOTE 1: Submit a campaign claim on the "Claim Entry/Edit/Submit" screen on WebDCS and attach all required Digital Documentation per TSB to the claim.

NOTE 2: 5 /60,000 New Vehicle Limited Warranty (NVLW) applies to the part(s) and repair procedure(s) outlined in this TSB. Prior to beginning any repair work, ensure the part(s) associated with the repair procedure are within NVLW, observing mileage and Warranty Start Date or date of first use. If the subject part(s) are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 3: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 4: This TSB includes repair justification photos. Op times include VIN, mileage, and repair validation photo(s) as outlined in the Digital Documentation Policy.

NOTE 5: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

Service Procedure:**DIGITAL DOCUMENTATION**

This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.



NOTICE

Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.

1. On the driver front seat, open the front seat track covers (A) then remove 4 bolts under the seat.

Tightening Torque:

lb-ft	42
N.m	57




2. Fold down the second row driver side seat.



3. Disconnect the negative (-) battery terminal (B).

Tightening Torque:


lb-ft	6.5
lb-in	78
N.m	8.8



4. Lean the driver front seat back then disconnect 3 connectors (C) from the bottom of the seat.

***i* Information**

Harness may be secured to the seat with clips (D). Remove clips to unsecure harness from seat.




5. Place the front seat assembly on top of the second-row seat to access the slide motor (E).

NOTICE


Do **NOT** damage the steering wheel and the roofliner when placing the front seat assembly on top of the second row seat.

***i* Information**


Adjust the steering wheel and lower the headrest to the lowest position for space.




6. Disconnect the slide motor connector (F).



7. Remove the 2 slide motor screws (G).



8. Remove the slide motor shaft (H) then remove the slide motor.



9.

**DIGITAL
DOCUMENTATION**


Using the STUI camera function, take a photo of the uninstalled slide motor **WITH** the tube.

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and date of repair on a piece of paper to include in the photo.



10. Remove the motor tube (I).



11. Reinstall slide motor and slide motor shaft.

12. Reinstall all parts in the reverse order of the removal process.

13. Confirm noise is no longer present when operating the seat slide function.

14. The service procedure is now complete.