

 HYUNDAI Technical Service Bulletin	GROUP BODY	NUMBER 26-BD-004H
	DATE JUNE 2026	MODEL(S) SEE BELOW
SUBJECT: LOOSE WINDSHIELD SIDE GARNISH REPLACEMENT		

Description: Some Elantra (CN7), Elantra Hybrid (CN7 HEV), and Elantra N (CN7 N) vehicles may exhibit loose windshield side garnishes. This bulletin provides instructions to replace the windshield side garnishes with improved parts to correct the condition.



Applicable Vehicles:

Model Year	Model	Production Dates	VIN Starts With
2025	Elantra (CN7)	05/25/2025 – 08/22/2025	KMH
	Elantra Hybrid (CN7 HEV)	05/25/2025 – 08/18/2025	
	Elantra N (CN7 N)		

Parts Information:

Model	Part Name	Part Number	Figure	Remarks
Elantra (CN7)	Garnish Assy – W/Shld Gls, Sd, Kit	86130-AA400 QQH		Includes LH & RH Windshield Side Garnish
Elantra Hybrid (CN7 HEV)				
Elantra N (CN7 N)				

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Elantra (CN7)	86130F00	Windshield Side Garnish Replacement (LH & RH)	0.3 M/H	Refer to WEBLTS for applicable part to labor op code combination	A32	ZZ4
Elantra Hybrid (CN7 HEV)						
Elantra N (CN7 N)						

NOTE 1: Normal warranty applies.

NOTE 2: Submit a "Warranty" claim on the "Claim Entry/Edit/Submit" screen on WebDCS and attach all required Digital Documentation per TSB to the claim.

NOTE 3: This TSB includes repair justification photos. Op times include VIN, Mileage, and repair justification photos as outlined in the Digital Documentation Policy.

NOTE 4: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

NOTE 5: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a Prior Approval (PA) Request for goodwill consideration on a case-by-case basis.

Service Procedure:

DIGITAL DOCUMENTATION

This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

Windshield Side Garnish Replacement

1.

DIGITAL DOCUMENTATION

Using the STUI camera function, take a photo(s) of the original damaged/loose windshield side garnish(es).

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and date of repair on a piece of paper to include in the photo(s).



2. Apply masking tape to the edge of the A-pillar next to the windshield side garnish (A).



3. Use plastic trim tools to remove the top of the garnish.

CAUTION

Wear gloves to prevent hand injuries.




4. Gently lift the garnish, then disengage the rest of the clips along the outside edge.

NOTICE


Do **NOT** apply excessive force to the garnish.



5. Move the garnish toward the middle of the windshield and disconnect it from the cowl panel (B).



6. Insert the bottom of the new garnish (C) into the grooves (D) on the cowl panel and press the part into place.



7. Engage the clips from the bottom to the top of the new garnish.

NOTICE

Confirm that all clips are completely engaged.



8. Confirm the bottom of the new garnish is fully engaged and flush with the cowl panel.



9. Remove the masking tape from the A-pillar.
10. Repeat **steps 2 – 9** on the opposite side of the vehicle.
11. The service procedure is now complete.