



TECHNICAL SERVICE BULLETIN

Ambient Air Temperature Sensor Replacement

26-2291
18 June 2026

This bulletin supersedes 26-2006. Reason for update: correct the ambient air temperature sensor service part number

Model:

Ford 2021-2025 Bronco	Built on or before 09-Sep-2025
---------------------------------	--------------------------------

Markets: North America markets only.

Issue: Some vehicles listed in the model statement above may require the replacement of the ambient air temperature sensor for various concerns. DTCs P0071, P0072, and/or P0073 may be present in the PCM.

Action: For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to replace the ambient air temperature sensor, wiring pigtail kit, and update the HVAC module if WSM, Pinpoint Test BB for 2021-2024 vehicles or AZ for 2025 vehicles (The Outside Air Temperature Display Is Inoperative Or Incorrect) leads to the replacement of the ambient air temperature sensor.

Parts

Service Part Number	Claim Quantity	Description
HC3Z-12A647-B	1	Ambient Air Temperature Sensor
PC3Z-14A411-D	1	Wiring Pigtail Kit
3U2Z-14A088-AB	1	Heat Shrink Tube

Claim Quantity refers to the total number of individual pieces required to repair the vehicle. This may differ from the number of service part number packages due to the unit of issue (UOI).

As Needed indicates the part is necessary but amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory. Refer to the Service Procedure to determine the inspection/inclusion criteria.

Warranty Status: Warranty coverage limits and policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

Labor Times

Description	Operation No.	Time
2021-2025 Bronco: Retrieve DTCs And Replace Ambient Air Temperature Sensor And Wiring Pigtail Includes Time To Reprogram The HVAC Module	262291A	0.7 Hrs
2021-2025 Bronco: Additional Time To Align 360 Degree Camera If Equipped (Can Be Claimed With Operation A)	262291B	0.5 Hrs

Repair/Claim Coding

Causal Part:	12A647
Condition Code:	42

Service Procedure

1. Perform Pinpoint Test BB for 2021-2024 vehicles or AZ for 2025 vehicles (The Outside Air Temperature Display Is Inoperative Or Incorrect) in WSM, Section 413-01 outside of this article. Did the Pinpoint Test lead to the

replacement of the ambient air temperature sensor?

1. Yes - proceed to Step 2.
2. No - this article does not apply. Refer to normal diagnostics in WSM, Section 413-01.
2. Remove the left exterior mirror. Refer to the WSM, Section 501-09 Rear View Mirrors > Removal and Installation > Exterior Mirror.
3. Remove and discard the ambient air temperature sensor. Refer to the WSM, Section 412-00.
4. Cut the ambient air temperature sensor wiring harness and connector directly behind the ambient air temperature sensor mating connector. (Figure 1)

Figure 1



E467743

5. Cut the new ambient air temperature sensor wiring pigtail kit 1.57 in (40 mm) back from the connector. (Figure 2)

Figure 2



E467744

6. Splice the new ambient air temperature sensor wiring pigtail kit to the harness using the solder method. Refer to the Wiring Diagram, Cell 005, Pages 5-6.
7. Install a new ambient air temperature sensor. Refer to the WSM, Section 412-00.
8. Reinstall the exterior mirror. Refer to the WSM, Section 501-09.
9. Reset the outside air temperature sensor learned values. Refer to the WSM, Section 412-00 > General Procedures.
10. If equipped, align the 360° cameras. Refer to the WSM, Section 413-13 > Parking Aid - Vehicles With: 360 Degree Camera/Analog Rear View Camera > General Procedures.
11. Reprogram the HVAC module using the latest software level of the FDRS scan tool.

© 2026 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.