

REFERENCE:	TSB: 08-250-26 GROUP: 08 - Electrical	Date:	June 27, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (RU) Chrysler Pacifica / Voyager This bulletin applies to vehicles built on or after January 19, 2026 (MDH 0119XX) and on or before March 09, 2026 (MDH 0309XX) equipped with 7" Full Color TFT Display (Sales Code JAJ), 120 MPH Primary Speedometer (Sales Code JCB), Instrument Panel Parts Module II (Sales Code X8C), and without PHEV Adaptation Components (Sales Code XDQ).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: <ul style="list-style-type: none"> • Speed limit warning chimes while driving. • IPC display message speed warning exceeded. • Speed limit appears on US IPC. Fig. 1 				
CAUSE:	IPC Configuration				




Fig. 1
IPC Display

1 - Speed Limit Indicator

REPAIR SUMMARY:

This bulletin involves reprogramming the IPC configuration.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-47-ER	Module, Instrument Panel Cluster (IPC) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

1. Using the wiTECH scan tool, select the BCM > Misc Functions > Change Country Code, then change the country code from US (United States) to ROW (Rest Of World).
2. Using the Electronic Vehicle Information Center (EVIC) control switch pod located in the left spoke of the steering wheel spoke bezel [Fig. 2](#), pressing up/down to move through the main menu to the Speed Warning menu. Then pressing left/right to move through the submenus to turn OFF the speed warning in the IPC.



Fig. 2
EVIC Switch

3. Using the wiTECH scan tool, select the BCM > Misc Functions > Change Country Code, then change the country code from ROW to US.
4. Clear all DTCs that may have been set in any module due to reprogramming.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.