

E3PA, G3 Pressure Sensor for Leveling System - Implausible Signal

Vehicles Affected

Models	Model Year	Model Type	Vehicle-Specific Equipment
Panamera	2024 - 2026	YAA	
Cayenne	2024 - 2026	9YA, 9YB	1BK, 2MA, 2MB

Revision History

Revision	Date	Change
0	06/16/2026	First Publication

Condition

The customer complains about a yellow chassis error in the Instrument Cluster. **All** the following fault codes and DTCs are stored in the Chassis control unit, **with the same time stamp**:

For Cayenne:

- **C103129 (DTC 31001A)** - "Adaptive suspension pressure sensor, implausible signal"
- **C103129 (DTC 31001B)** - "Adaptive suspension pressure sensor, implausible signal"
- **C103129 (DTC 310018)** - "Adaptive suspension pressure sensor, implausible signal"
- **C103129 (DTC 310019)** - "Adaptive suspension pressure sensor, implausible signal"

For Panamera:

- **C141BF0 (DTC 31001A)** - "Pressure sensor for leveling system - implausible signal"
- **C142CF0 (DTC 31001B)** - "Pressure sensor for leveling system - implausible signal"
- **C142DF0 (DTC 310018)** - "Pressure sensor for leveling system - implausible signal"
- **C142EF0 (DTC 310019)** - "Pressure sensor for leveling system - implausible signal"

Advanced Technical Information

Bulletin #: 2605

Part ID: 4316

4

Technical Background

The above faults can be stored in the Chassis control unit due to a voltage drop (less than 8.5V for >250 ms at the chassis control unit) during engine start. The following fault codes can also be stored:

U140000 – “Function restriction – supply voltage too low”

C10C200 – “Chassis control – function restriction (consequential fault)”

Service Information

Only if all 4 occurrences of fault codes and DTCs are stored with the same exact time stamp (including the seconds) as described above, proceed as follows:

1. Record a Pre-VAL.
2. Replace the 12V battery.
3. Attach any relevant 12V battery documentation to the PCSS job.
4. If the faults persist, continue with other means of diagnosis.
5. Record a Post-VAL.

Advanced Technical Information

Bulletin #: 2605

Part ID: 4316

4

Warranty

For documentation and warranty invoicing, enter the working position und PCSS encryption specified below in the warranty claim.

APOS	Labor Operation	I No.
03350053	On board diagnostic	
27065500	Vehicle electrical system battery replace	
03350063	On board diagnostic	

PCSS encryption:

Location (FES5)	4316	Control unit for Chassis control
Damage type (SA4)	4000	Electrical faults

Search Items

YAA, 9YB, 9YA, Cayenne, Panamera, E3, G3, Chassis, EFP, leveling system, pressure sensor, Chassis control unit, C103129, C141BF0

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.