



Connection offline

Technical Service Bulletin

Transaction No.: **2082342/1**

57 Workshop info: various complaints - DTC P060C00: Internal Control Module Main Processor Performance - in DA 00C5

Release date: Jun 10, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A5, S5 (FU), Q5, Q5 Sportback, SQ5, and SQ5 Sportback	2025 – 2026	All	Not applicable
A6	2026		
A6 Sportback e-tron, and S6 Sportback e-tron, Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron	2025 2027		

Customer states:

Various customer complaints, such as “vehicle does not start or starts with delay”.

Various fault and information messages in instrument cluster.

Workshop findings:

The following event memory entry is logged in the thermal management (diagnostic address 00C5):

- **P060C00** Internal Control Module Main Processor Performance, static or intermittent.

Technical Background

Software issue. Guided Fault Finding does not handle additional entries that may be relevant correctly.

Production Solution

Not applicable.

Service

The event memory entry **“P060C00: Internal Control Module Main Processor Performance, static or intermittent”** in the thermal management (diagnostic address 00C5) is related to a weak or discharged 12V battery or voltage fluctuations in the onboard supply control unit.

You should therefore check whether any event memory entries related to the vehicle voltage are logged in diagnostic address 0009 or 0019:

- Discharged or defective 12V battery
- Undervoltage
- No-load current
- Entries about the voltage converter

- Communication entries about the battery management
- Disruptions to terminal 30

If applicable, also read out the battery history data (read out data for TSC/importer; do not read out raw data) and evaluate it.

If any relevant entries about the vehicle voltage are logged, resolve these issues first and make sure that the vehicle voltage meets the specifications.

If necessary, also refer to TSB 2080517, *27 12V Starter battery discharged or malfunctioning*.

Then erase and read out the event memory for diagnostic addresses 00C5, 0009 and 0019 again.

If the event memory entry **“P060C00: Internal Control Module Main Processor Performance, static or intermittent”** is not logged in the thermal management (diagnostic address 00C5) again, no further work is required for this entry.

In this case, any additional repair suggestions from Guided Fault Finding in ODIS-S are not relevant and should be ignored.

In all other cases, the event memory entry does not influence any functions and can be ignored. Working through it via Guided Fault Finding in ODIS-S would not have any effect in this case.

Warranty

The causes of the weak or discharged 12V battery or voltage fluctuations in the onboard supply control unit must be billed **separately via the corresponding service number for the specific cause**.

It is not possible to bill for fault finding and/or component replacement under warranty via this TPI.

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2082342**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.