

Complaint Regarding the Camera View (Real Top View) in the PCM Central Display (03/26)

Change
Overview:

Revision	Date	Change
0	05/20/2026	▪ First Publication
1	06/30/2026	▪ Update to "Check plug contact of signal line in passenger compartment" work procedure

Model Year: **As of 2020 up to 2026**

Model Line: **Taycan (Y1A / Y1B / Y1C)**

Equipment: **ParkAssist incl. Surround View (M-no. KA6)**

Concerns: **Signal lines and plug contacts for the Real Top View cameras**

Information: **The customer complains that the Real Top View in the central display fails sporadically, partially or completely.**

In rare cases, this fault can be caused by an **outdated** software release of the control unit for assistance systems (ZFAS).

In the event of unfavorable specific component tolerances, a faulty plug contact on the signal lines of the cameras can, in individual cases, cause the fault type even after a software update.

Action: If there is a customer complaint, check the software release of the assistance systems control unit (ZFAS) and, depending on the test result, either

- Re-program the assistance systems control unit (ZFAS) using the Porsche Tester.

or, if the current software is installed on the assistance systems control unit,

- rework the signal lines and plug contacts of the mirror cameras.

Required tools

- Tools:
- **P90999 - Porsche Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g., **VAS 5908 battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging the vehicle electrical system battery'*

Additional tools required for replacing signal lines and connector contacts:

- Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g., **V.A.G 1783 - torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**
- **VAS 6720 - Antenna line repair set**
- Plastic wedge, commercially available
- Cable pull-in aid, commercially available **or** welding wire with bent ends
- PNATI0326 — Measuring adapter

*Measuring Adapter (PNATI0326)***Required parts as necessary****Information**

PNATI0326 has been released as a minimum required tool by Porsche Special Tools & Equipment. Please see **SPTL2605** for auto-shipment information.

Additional units can be ordered through the Special Tools & Equipment Webstore (part no. **PNATI0326**) or through TKR USA (part no. **WEB-KIT-000021**)

Parts
Information:

Part No.	Designation	Number
9J1998045A	⇒ 6m antenna line	1 piece(s)
...*	⇒ Plug contact, female (5 pieces)	1 piece(s)
...*	⇒ Plug contact, male (5 pieces)	1 piece(s)
...	⇒ Spacer / cable holder	2 piece(s)
	– Commercially available	

**Information**

*The plug contacts required for this Technical Information (TI) are currently not yet available via Porsche AG (PAG) (status April 2026). Until availability, the required contacts must be removed from the repair kit **VAS 6720 – repair kit for antenna lines**.

Materials:

Required materials (usually already available in the Porsche Center)

Part No.	Designation	Quantity
...	⇒ Fabric tape, approx. 19 mm wide – e.g. TESA 51026	As required
...	⇒ Cable tie – Commercially available	As required

Check release of the control unit for assistance systems (ZFAS) software

- Work Procedure:
- 1 Connect and switch on the battery charger.
⇒ *Workshop Manual '270689A4 Charge battery and vehicle electrical system'*
 - 2 Place original remote control in emergency start tray.
 - 3 Connect **P90999 - Porsche Tester 4**, establish readiness for operation and start the diagnostic application.
 - 4 Check release of assistance systems control unit software.
 - 4.1 In the '**Overview**', select the '**Assistance Systems**' control unit and confirm with **F12** ("Next").
 - 4.2 Select the '**Extended identifications**' tab and check the software release.

Assessment	Action
The software release is " 0385 " (Taycan model year 2020 – 2024) or " 0511 " (Taycan model year 2025 – 2026).	The software release is up-to-date. Install new signal lines and rework plug contacts at the door connection points if necessary. Continue with: ⇒ <i>Technical Information '270689A4 Install new signal lines and rework the plug contacts at the door connection points if necessary'</i>
The software release is not " 0385 " (Taycan model year 2020 – 2024) or " 0511 " (Taycan model year 2025 – 2026).	The software release does not match the current version. Re-program control unit for assistance systems (ZFAS) Check whether campaigns for reprogramming assistance systems are available for the respective affected vehicle and carry them out if necessary. If the affected vehicle is not impacted by a campaign, continue with: ⇒ <i>Technical Information '270689A4 Failure of one or more cameras (Real Top View) in the PCM central display (34/25)'</i> End of action.




Information

If the affected vehicle (Taycan model year **2020 – 2024**) has not yet installed software release **0385** and this is not provided either via the Technical Information (TI) **34/25** or via a campaign, this TI **cannot** be used. Software release **0385** (Taycan model year **2020 – 2024**) is the prerequisite for the implementation of this TI. Performing the repair without this software release is **not effective**.

Install new signal lines and rework the plug contacts at the door connection points if necessary**Information**


The rework of the signal lines is described on the front right door as an example. The rework on the front left door is almost identical.

- Work Procedure:
- 1 Loosen the earth strap for the vehicle electrical system battery.
⇒ *Workshop Manual '978519A1 Removing and installing earth strap for battery'*
 - 2 Remove front loudspeaker, right door trim panel).
⇒ *Workshop Manual '914119 Removing and installing front loudspeaker, door trim panel'*
 - 3 Loosen, release and disconnect signal line on door control unit ⇒ *Front door signal line connection point -1-* and electric plug connection ⇒ *Front door signal line connection point -2-*.




Front door signal line connection point

- 4 **Replace the plug contact on the mirror wire harness.**
 Replace plug contact ⇒ *Plug contact on mirror side*
 -1- of the signal line ⇒ *Plug contact on mirror side -2-*
 (coming from the rear-view mirror camera).
 For work procedure, see: ⇒ *Workshop Manual*
'912841C8 Repairing antenna cable'




Plug contact on mirror side

- 5 Expose the electric wire harness ⇒ *Electric wire harness of the door connection point to the rear-view mirror camera connection point -1-* from the door connection point ⇒ *Electric wire harness of the door connection point to the rear-view mirror camera connection point -2-* to the connection point of the rear-view mirror camera signal line ⇒ *Electric wire harness of the door connection point to the rear-view mirror camera connection point -3-*.
 For work procedure, see: ⇒ *Workshop Manual*
'973219B2 Removing and installing front door wire harness (bodyshell)'




Electric wire harness of the door connection point to the rear-view mirror camera connection point

- 6 Remove fabric tape from the grommets ⇒ *Electric door wire harness, front -1-*.



Electric door wire harness, front

- 7 Disconnect grommet ⇒ *Electric plug connection at the door connection point (door side) -1-* from electric plug connection at the door connection point ⇒ *Electric plug connection at the door connection point (door side) -2-* and ⇒ *Electric plug connection at the door connection point (door side) -3-* loosen the cable tie.



Electric plug connection at the door connection point (door side)


- 8 Cut the **new** signal line $\Rightarrow$ *New signal line on electric wire harness -1-* to approx. **1.5 m / 4.92 ft** and route it along the electric wire harness from the connection point of the rear-view mirror camera $\Rightarrow$ *New signal line on electric wire harness -2-* to the plug at the door connection point $\Rightarrow$ *New signal line on electric wire harness -3-*.



Information

Make sure that the plug contact fitted on the signal line is at the rear-view mirror camera connection point.

The existing plug contact must not be fitted on the door connection point plug.




New signal line on electric wire harness

- 9 Release connector housing for door connection point $\Rightarrow$ *Connector housing for door connection point -1-* in $\Rightarrow$ *Connector housing for door connection point -Arrow direction-* and pull it out of the mounting housing $\Rightarrow$ *Connector housing for door connection point -2-*.



Connector housing for door connection point

- 10 Disassemble connector housing and pull it out of the ⇒ *Signal line in connector for door connection point -3-* plug contact of the signal line.
- 10.1 Open outer section ⇒ *Signal line in connector for door connection point -1-* of connector housing slightly in ⇒ *Signal line in connector for door connection point -Arrow direction-*.
- 10.2 Push out inner section ⇒ *Signal line in connector for door connection point -2-* of connector housing.
- 10.3 Pull out plug contact ⇒ *Signal line in connector for door connection point -3-* of the signal line.
- 11 Cut off **new** signal line (on door connection point connector housing side) to sufficient length and crimp **new** plug contact.
For work procedure, see: ⇒ *Workshop Manual '912841C8 Repairing antenna cable'*




Signal line in connector for door connection point



Information

When crimping and routing the new signal line, ensure that the line is installed without tension and without mechanical preloads.

- 12 Fasten connector housing for door connection point in the mounting housing using a **new** plug contact ⇒ *Electric plug connection at the door connection point (door side) -2-*. Fit **new** cable tie ⇒ *Electric plug connection at the door connection point (door side) -3-*.
- 13 Disconnect the previous signal line at a suitable point and connect it to the electric wire harness.



Electric plug connection at the door connection point (door side)




Information

If fabric tape has been opened or removed from the electric wire harness in the area below the grommet, re-attach it.
⇒ *Fabric tape*



Fabric tape

- 14 Open cable holder ⇒ *Electric door wire harness, front -1-* and wrap the signal line tightly around the wire harness using fabric tape. Then wrap the grommets tightly with ⇒ *Electric door wire harness, front -2-* fabric tape again to the wire harness and ⇒ *Electric door wire harness, front -1-* fit the cable holder. Ensure that no moisture can penetrate into the wire harness.
- 15 Install electric wire harness on front door (bodyshell). For work procedure, see: ⇒ *Workshop Manual '973219B2 Removing and installing front door wire harness (bodyshell)'*
- 16 Perform the described action (action steps ⇒ 2 to ⇒ 15) also on the front left door. Then continue with: ⇒ *Technical Information '973219B2 Check plug contact at the door connection point on the vehicle side'*



Electric door wire harness, front

Checking plug contact at the door connection point on the vehicle side




Information

The measurement is performed from the left door connection point **through the vehicle** to the right door connection point. This means that one measuring cable must be connected to the **left door connection point** and the other to the **right door connection point**.

- Work Procedure: 1 Secure the **measuring adapter** to the signal lines
 ⇒ *Resistance measurement on vehicle-side door connection points -1-* of the vehicle-side door connection points on the left and right and perform a resistance measurement through the vehicle using the **P90999 - Porsche Tester 4**.

**Information**

The measured resistance values must always be documented and attached to the process in PCSS.



Resistance measurement on vehicle-side door connection points

Assessment	Action
Resistance is 200 mΩ or less .	The resistance of the signal lines is OK. Plug in and lock electric plug connection on door connection point. Install front door panel loudspeakers and door trim panels. ⇒ <i>Workshop Manual '914119 Removing and installing front loudspeaker, door trim panel'</i> Then connect earth strap for battery. ⇒ <i>Workshop Manual '978519A1 Removing and installing earth strap for battery'</i> End of action.
The resistance value is greater than 200 mΩ .	The resistance of the signal lines is not OK. Replace the plug contact of a signal line at the vehicle-side door connection points. Continue with Step ⇒ 2.


- 2 Detach the fuse box in the right footwell.
 ⇒ *Workshop Manual '978409A4 Loosening and securing fuse box in footwell'*

- 3 Loosen electric plug connection ⇒ *Electric plug connection at door connection point (vehicle-side) -1-* for the vehicle-side door connection point.

- 3.1 Release locking lug ⇒ *Electric plug connection at door connection point (vehicle-side) -2-* in ⇒ *Electric plug connection at door connection point (vehicle-side) -Arrow direction A-* and insert electric plug connection for door connection point ⇒ *Electric plug connection at door connection point (vehicle-side) -1-* in ⇒ *Electric plug connection at door connection point (vehicle-side) -Arrow direction B-*.

- 3.2 Guide electric plug connection for the door connection point ⇒ *Electric plug connection at door connection point (vehicle-side) -1-* out of the inner A-pillar.

- 3.3 Loosen connector housing ⇒ *Electric plug connection at door connection point (vehicle-side) -3-* and remove it in ⇒ *Electric plug connection at door connection point (vehicle-side) -Arrow direction-*.



Electric plug connection at door connection point (vehicle-side)

- 4 Release plug contact of the signal line ⇒ *Signal line for door connection point -1-*, pull ⇒ *Signal line for door connection point -2-* it out of the connector housing and replace it with a **new** plug contact.
For work procedure, see: ⇒ *Workshop Manual '912841C8 Repairing antenna cable'*
- 5 Install electric plug connection for vehicle-side door connection point.




Signal line for door connection point

- 6 Secure the **measuring adapter** to the signal lines
 ⇒ *Resistance measurement on vehicle-side door connection points -1-* of the vehicle-side door connection points on the left and right and perform another resistance measurement using the **P90999 - Porsche Tester 4**.

**Information**

The measured resistance values must always be documented and attached to the process in PCSS.



Resistance measurement on vehicle-side door connection points

Assessment	Action
Resistance is 200 mΩ or less.	The resistance of the signal lines is OK. Plug in and lock electric plug connection on door connection point. Install front door panel loudspeakers and door trim panels. ⇒ <i>Workshop Manual '914119 Removing and installing front loudspeaker, door trim panel'</i> Then connect earth strap for battery. ⇒ <i>Workshop Manual '978519A1 Removing and installing earth strap for battery'</i> End of action.
The resistance value is still greater than 200 mΩ .	The resistance of the signal lines is not OK. Replace the plug contact of the signal line at the vehicle-side front left door connection point. Repeat steps ⇒ 2 to ⇒ 5 on the left-hand side and then perform another resistance measurement. Install front door panel loudspeakers and door trim panels. ⇒ <i>Workshop Manual '914119 Removing and installing front loudspeaker, door trim panel'</i> Then connect earth strap for battery. ⇒ <i>Workshop Manual '978519A1 Removing and installing earth strap for battery'</i> End of action.



Information

If the resistance reading is still too high after replacing **both plug contacts** in the passenger compartment, create a **Warranty / Campaigns PRMS ticket** with priority "B" and the title (brief description) "**TI 03/26 - Support**", attach the measurement results of the individual measurements and a brief description of the work performed.

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
91020140	Check release of assistance systems control unit software	
91284940	Install new door signal lines	
91284941	Install new door signal lines and rework the plug contact at a door connection point	
91284942	Install new door signal lines and rework the plug contacts at both door connection points	

PCSS encryption:

Location (FES5)	97321	Front door wire harness
Damage type (SA4)	1057	Crimp faulty

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.