

Complaint Regarding the Camera View (Real Top View) in the PCM Central Display (03/26)

Change
Overview:

Revision	Date	Change
0	05/20/2026	▪ First Publication
1	06/30/2026	▪ Update to "Check plug contact of signal line in passenger compartment" work procedure

Model Year: **As of 2025**

Model line: **911 (992 II)**

Equipment: **ParkAssist incl. Surround View (M-no. KA6)**

Concerns: **Signal lines and plug contacts for the Real Top View cameras**

Situation: **The customer complains that the Real Top View in the central display fails sporadically, partially or completely.**

In rare cases, this fault can be caused by an **outdated** software release of the control unit for assistance systems (ZFAS).

In the event of unfavorable specific component tolerances, a faulty plug contact on the signal lines of the cameras can, in individual cases, cause the fault type even after a software update.

Action: If there is a customer complaint, check the software release of the assistance systems control unit (ZFAS) and, depending on the test result, either

- Re-program the assistance systems control unit (ZFAS) using the Porsche Tester.

or, if the current software is installed on the assistance systems control unit,

- rework the signal lines and plug contacts of the mirror cameras.

Required tools

- Tools:
- **P90999 - Porsche Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g., **VAS 5908 battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging the vehicle electrical system battery'*

Additional tools required for replacing signal lines and connector contacts:

- Torque wrench, 0.4-2 Nm (0.3-1.5 ftlb.), e.g. **VAS 6253A - Torque wrench, 0.4-2 Nm (0.3-1.5 ftlb.)**
- Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g., **V.A.G 1783 - torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**
- **VAS 6720 - Antenna line repair set**
- Plastic wedge, commercially available
- PNATI0326 — Measuring adapter

*Measuring Adapter (PNATI0326)***Required parts as necessary****Information**

PNATI0326 has been released as a minimum required tool by Porsche Special Tools & Equipment. Please see **SPTL2605** for auto-shipment information.

Additional units can be ordered through the Special Tools & Equipment Webstore (part no. **PNATI0326**) or through TKR USA (part no. **WEB-KIT-000021**)

Parts
Information:

Part No.	Designation	Number
...*	⇒ Plug contact, female (5 pieces)	1 piece(s)
...*	⇒ Plug contact, male (5 pieces)	1 piece(s)
N 90824902	⇒ Lens panel screw	8 piece(s)
N 90953004	⇒ Internal hexagon round oval-head screw	2 piece(s)

**Information**

*The plug contacts required for this Technical Information (TI) are currently not yet available via Porsche AG (PAG) (status April 2026). Until availability, the required contacts must be removed from the repair kit **VAS 6720 – repair kit for antenna lines**.

Materials:

Required materials (usually already available in the Porsche Center)

Part No.	Designation	Quantity
...	⇒ Fabric tape, approx. 19 mm wide – e.g. TESA 51026	As required
...	⇒ Cable tie – Commercially available	As required

Check release of the control unit for assistance systems (ZFAS) software

- Work Procedure:
- 1 Connect and switch on the battery charger.
⇒ *Workshop Manual '270689A4 Charge battery and vehicle electrical system'*
 - 2 Place original remote control in emergency start tray.
 - 3 Connect **P90999 - Porsche Tester 4**, establish readiness for operation and start the diagnostic application.
 - 4 Check release of assistance systems control unit software.
 - 4.1 In the '**Overview**', select the '**Assistance Systems**' control unit and confirm with **F12** ("Next").
 - 4.2 Select the '**Extended identifications**' tab and check the software release.

Assessment	Action
If the software release is "0511" .	The software release is up-to-date. Replace signal lines and replace plug contacts in the passenger compartment Continue with: ⇒ <i>Technical Information '270689A4 Rework signal lines and replace plug contacts in the passenger compartment'</i>
Software release is not "0511" :	The software release does not match the current version. Re-program control unit for assistance systems (ZFAS) Check whether campaigns for reprogramming assistance systems are available for the respective affected vehicle and carry them out if necessary. If the affected vehicle is not impacted by a campaign, continue with: ⇒ <i>Technical Information '270689A4 Failure of one or more cameras (Real Top View) in the PCM central display (34/25)'</i> End of action.


Rework signal lines and replace plug contacts in the passenger compartment**Information**

Reworking is only required if the assistance systems control unit has already been programmed in the past with the software **0511** and the complaint has occurred again. Otherwise, it is only necessary to programme the control unit for assistance systems.

**Information**


The rework of the signal lines is described on the front left door as an example. The rework on the front right door is almost identical.

- Work Procedure:
- 1 Loosen the earth strap for the vehicle electrical system battery.
⇒ *Workshop Manual '978509A1 Loosen and secure earth strap for battery'*
 - 2 Remove front left door trim panel.
⇒ *Workshop Manual '705919A3 Removing and installing the front door trim panel'*
 - 3 Loosen, release and disconnect signal line on door control unit ⇒ *Front door signal line connection point -1-* and electric plug connection ⇒ *Front door signal line connection point -2-*.




Front door signal line connection point

- 4 Replace ⇒ *Plug contacts for signal lines -1-* plug contacts of the signal lines.
For work procedure, see: ⇒ *Workshop Manual '912841 Repairing antenna line'*
- 5 Remove the front side section trim panel at the left.
⇒ *Workshop Manual '702419A1 Removing and installing front side section trim panel'*




Plug contacts for signal lines

- 6 Unclip cable attachment clip, ⇒ *Signal line connection point in the passenger compartment -1-* release and disconnect electric plug connection ⇒ *Signal line connection point in the passenger compartment -2-*.



Signal line connection point in the passenger compartment


- 7 Replace plug contact ⇒ *Plug contacts for signal lines in the passenger compartment -1- of the signal line (coming from front door).*
For work procedure, see: ⇒ *Workshop Manual '912841 Repairing antenna line'*
- 8 Perform the action described (action steps ⇒ 2 to ⇒ 7) also on the front right door.
Then continue with: ⇒ *Technical Information '912841 Check plug contact at the door connection point on the vehicle side'*



Plug contacts for signal lines in the passenger compartment

Check plug contact of signal line in passenger compartment.

- Work Procedure: 1 Fasten the **measuring adapter** to the signal lines ⇒ *Resistance measurement of the signal lines in the passenger compartment -1- in the passenger compartment on the left and right and perform a resistance measurement through the vehicle using the **P90999 - Porsche Tester 4**.*



Resistance measurement of the signal lines in the passenger compartment



Information

The measurement is performed from the left door connection point **through the vehicle** to the right door connection point. This means that one measuring cable must be connected to the **left door connection point** and the other to the **right door connection point**.




Information

The measured resistance values must always be documented and attached to the process in PCSS.


Assessment	Action
Resistance is 335 mΩ or less.	The resistance of the signal lines is OK. Connect electric plug connections until connector locks perceptibly. Install front side section and door trim panel ⇒ Workshop Manual '702419A1 Removing and installing front side section trim panel' ⇒ Workshop Manual '705919A3 Removing and installing the front door trim panel' Then connect earth strap for battery.

	⇒ Workshop Manual '978509A1 Loosen and secure earth strap for battery'
	End of action.
The resistance value is greater than 335 mΩ .	The resistance of the signal lines is not OK. Replace plug contact of a signal line in the passenger compartment. Continue with Step ⇒ 2.

- 2 Replace plug contact ⇒ *Plug contact for signal line in passenger compartment -1-* of the signal line in the passenger compartment on the left.
For work procedure, see: ⇒ Workshop Manual '912841 Repairing antenna line'
- 3 Fasten the **measuring adapter** to the signal lines
⇒ *Resistance measurement of the signal lines in the passenger compartment -1-* in the passenger compartment on the left and right and perform another resistance measurement using the **P90999 - Porsche Tester 4**.



Plug contact for signal line in passenger compartment



Resistance measurement of the signal lines in the passenger compartment



Information

The measured resistance values must always be documented and attached to the process in PCSS.

Assessment	Action
Resistance is 335 mΩ or less .	The resistance of the signal lines is OK. Connect electric plug connections until connector locks perceptibly. Install front side section and door trim panel ⇒ Workshop Manual '702419A1 Removing and installing front side section trim panel' ⇒ Workshop Manual '705919A3 Removing and installing the front door trim panel' Then connect earth strap for battery. ⇒ Workshop Manual '978509A1 Loosen and secure earth strap for battery' End of action.
The resistance value is still greater than 335 mΩ .	The resistance of the signal lines is not OK. Replace plug contact of the signal line in the passenger compartment on the right.

Repeat step ⇒ 2 on the right-hand side and then perform another resistance measurement.

Install front side section and door trim panel
⇒ Workshop Manual '702419A1 Removing and installing front side section trim panel'

⇒ Workshop Manual '705919A3 Removing and installing the front door trim panel'

Then connect earth strap for battery.

⇒ Workshop Manual '978509A1 Loosen and secure earth strap for battery'

End of action.



Information

If the resistance reading is still too high after replacing **both plug contacts** in the passenger compartment, create a **Warranty / Campaigns PRMS ticket** with priority "B" and the title (brief description) "**TI 03/26 - Support**", attach the measurement results of the individual measurements and a brief description of the work performed.

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
91020140	Check release of assistance systems control unit software	
91284940	Replace plug contacts for front door signal lines	
91284941	Replace plug contacts for front door and signal line in passenger compartment on the left	
91284942	Replace plug contacts for front door and signal lines in passenger compartment on the left and right	

PCSS encryption:

Location (FES5)	97321	Front door wire harness
Damage type (SA4)	1057	Crimp faulty

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.