

|                    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |       |              |                                                                                                                                                                                                                                                                                                                   |           |
|--------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| REFERENCE:         | TSB: 18-061-26 REV. A<br>GROUP: 18 - Vehicle Performance                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Date: | July 1, 2026 | REVISION:                                                                                                                                                                                                                                                                                                         | 18-061-26 |
| VEHICLES AFFECTED: | <b>**2026** (D2) RAM 3500 Pickup</b><br><b>**2026** (DJ) RAM 2500 Pickup</b><br>This bulletin applies to vehicles built on or before June 20, 2026 (MDH 0620XX) equipped with the 6.7L I6 Cummins HO Turbo Diesel Eng (Sales Code ETM) and Euro Stage 6B Emissions (Sales Code NB6).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |       |              | <b>MARKET APPLICABILITY:</b><br><div><input type="checkbox"/> NA<input type="checkbox"/> MEA</div> <div><input checked="" type="checkbox"/> SA<input type="checkbox"/> IAP</div> <div><input type="checkbox"/> EE<input type="checkbox"/> CH</div><br><b>NOTE:</b> This bulletin applies to South America market. |           |
| CUSTOMER SYMPTOM:  | <b>Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):</b> <ul style="list-style-type: none"><li>• **P0088-00 - Fuel Rail Pressure Too High - Bank 1.**</li><li>• P0263-00 - Cylinder 1 Contribution/Balance.</li><li>• P0266-00 - Cylinder 2 Contribution/Balance.</li><li>• P0269-00 - Cylinder 3 Contribution/Balance.</li><li>• P0272-00 - Cylinder 4 Contribution/Balance.</li><li>• P0275-00 - Cylinder 5 Contribution/Balance.</li><li>• P0278-00 - Cylinder 6 Contribution/Balance.</li></ul> <b>Customers may also comment one or more of the following:</b> <ul style="list-style-type: none"><li>• The engine runs rough and exhibits stumbling and shaking.</li><li>• Loss of power.</li></ul><br><b>NOTE:</b> The perceived loss of power is due to an insufficient injector/torque response. |       |              |                                                                                                                                                                                                                                                                                                                   |           |
| CAUSE:             | PCM Software                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |       |              |                                                                                                                                                                                                                                                                                                                   |           |

This bulletin supersedes Technical Service Bulletin (TSB) 18-061-26, date of issue June 19, 2026, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include updated Vehicles Affected, new Repair Procedure notes and an additional DTC added to Customer Symptoms.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-114, date of issue June 19, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

#### REPAIR SUMMARY:

This bulletin involves inspecting and possibly reprogramming the PCM with the latest available software.

**CLAIMS DATA:**

| Labor Operation No: | Labor Description                                                          | Skill Category                    | Labor Time |
|---------------------|----------------------------------------------------------------------------|-----------------------------------|------------|
| 18-19-06-3R         | Engine Control Module (ECM) - Inspect Software Level<br>(0 - Introduction) | 1 - Engine Repair And Performance | 0.2 Hrs.   |
| 18-19-06-3S         | Engine Control Module (ECM) - Inspect And Reprogram<br>(0 - Introduction)  | 1 - Engine Repair And Performance | 0.2 Hrs.   |
| Failure Code        | RF                                                                         | Required Flash                    |            |
|                     | CC                                                                         | Customer Concern                  |            |

**The dealer must choose which failure code to use depending on if this is a Rapid Service Update (RSU) or Technical Service Bulletin.**

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code “RF” (Required Flash) can no longer be used on Technical Service Bulletin flashes. The “RF” failure code must be used on an RSU.
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

**SPECIAL TOOLS/EQUIPMENT:**

| Description          | Ref. No. | Notes |
|----------------------|----------|-------|
| wiTECH or Equivalent | —        | —     |

**REPAIR PROCEDURE:**

**NOTE:** Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

**NOTE:** If this flash process is interrupted/aborted, the flash should be restarted.

**IMPORTANT! \*\*Save only the pages of the Vehicle Scan Report (Scan Report) that show the software version present in the vehicle's PCM module, both before and after this adjustment.\*\***

1. Is the vehicle on the RSU VIN list?
  - YES>>> Proceed to [Step 2](#).
  - NO>>> Proceed to [Step 3](#).
2. Is the PCM software updated to the latest version?
  - YES>>> This bulletin has been completed, use Inspect LOP (18-19-06-3R) to close the active RSU.
  - NO>>> Proceed to [Step 3](#).
3. Reprogram the PCM with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.

**IMPORTANT! \*\*After the PCM software update, the odometer will start flashing and you will need to perform the PROXI alignment. It is essential to follow the key cycle as indicated by wiTECH.\*\***

4. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.**

#### **POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*