



TECHNICAL SERVICE BULLETIN

Ambient Air Temperature Sensor Replacement

26-2372

11 August
2026

This bulletin supersedes 26-2301. Reason for update: update the Pinpoint Tests referenced in Step 1

Model:

Ford 2024-2026 Ranger	Built on or before 12-Jan-2026
--------------------------	--------------------------------

Markets: North American markets only

Issue: Some of the vehicles listed in the Model statement above may require the replacement of the ambient air temperature sensor for various concerns. DTCs P0071, P0072, and/or P0073 may be present in the PCM.

Action: For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to replace the ambient air temperature sensor, wiring pigtail kit, and ambient air temperature sensor bezel, if WSM Pinpoint Test (The Outside Air Temperature Display Is Inoperative Or Incorrect) leads to replacement of the ambient air temperature sensor.

Parts

Service Part Number	Claim Quantity	Description	Note
HC3Z-12A647-A	1	Ambient Air Temperature Sensor	
PC3Z-14A411-D	1	Wiring Pigtail Kit	
S1WZ-17A703-A	1	Ambient Air Temperature Sensor Bezel	
3U2Z-14A088-AB	1	Heat Shrink Tube	
NAI837X	As Needed	Coroplast Electrical Wire Harness Tape Or Equivalent	Rotunda part number

Claim Quantity refers to the total number of individual pieces required to repair the vehicle. This may differ from the number of service part number packages due to the unit of issue (UOI).

As Needed indicates the part is necessary but amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory. Refer to the Service Procedure to determine the inspection/inclusion criteria.

Labor Times

Description	Operation No.	Time
2024-2026 Ranger: Replace The Ambient Air Temperature Sensor And Bezel, Includes Time To Splice Wires And Reset Temperature Sensor Learned Values Following The Service Procedure	262372A	0.4 Hrs

Repair/Claim Coding


Causal Part:	12A647
Condition Code:	42

Service Procedure

1. Perform Pinpoint Test (The Outside Air Temperature Display Is Inoperative Or Incorrect) in WSM, Section 413-01 outside of this article. Did Pinpoint Test lead to the replacement of the ambient air temperature sensor?

- (1). Yes - proceed to Step 2.
- (2). No - this article does not apply. Refer to WSM, Section 413-01 for normal diagnostics.
2. Remove the ambient air temperature sensor and bezel. Refer to WSM, Section 412-00 Climate Control System > Climate Control System - General Information > Removal and Installation > Ambient Air Temperature Sensor.
3. Cut the ambient air temperature sensor wiring harness as close to connector C650 as possible. (Figure 1)

Figure 1



E469073

4. Cut the new ambient air temperature sensor wiring pigtail kit 3 5/32 in. (80 mm) back from the connector. (Figure 2)

Figure 2



E469074

5. Splice the new ambient air temperature sensor wiring pigtail kit to the harness using the solder method. Refer to Wiring Diagram, Cell 005, Pages 5-6.
6. Wrap the new section of wiring (including the heat shrink tube) with Coroplast™ electrical wire harness tape or equivalent. (Figure 3)

Figure 3



E469075

7. Install the ambient air temperature sensor and bezel. Refer to WSM, Section 412-00 Climate Control System > Climate Control System - General Information > Removal and Installation > Ambient Air Temperature Sensor.
8. Reset the outside air temperature sensor learned values. Refer to WSM, Section 412-00 Climate Control System > Climate Control System - General Information > General Procedures.

© 2026 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.