

 HYUNDAI
Technical Service Bulletin


GROUP BODY ELECTRICAL SYSTEM	NUMBER 26-BE-021H
DATE SEPTEMBER 2026	MODEL(S) VENUE (QX)

SUBJECT: INOPERATIVE HORN ASSEMBLY REPLACEMENT

*** IMPORTANT**

This field action requires both a reported condition consistent with the symptoms outlined in this TSB and dealer confirmation of those symptoms before any repair work is performed. If requirements are not met, any submitted claims are subject to debit. 5 / 60,000 New Vehicle Limited Warranty applies. See Warranty Information section for more details.

Description: Some Venue (QX) vehicles may have an inoperative horn due to insufficient internal soldering of the horn assembly. This bulletin provides instructions to replace the horn assembly.



Applicable Vehicles:

Model Year	Model	Production Dates
2025 – 2026	Venue (QX)	10/01/2024 – 11/24/2025

SUBJECT:**INOPERATIVE HORN ASSEMBLY REPLACEMENT****Parts Information:**

Model	Part Name	Part Number	Figure	Remarks
Venue (QX)	Horn Assy	96641-K2100QQH		Qty: 1

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Venue (QX)	60D131R0	Horn Assembly Replacement	0.5 M/H	96641-K2100	I11	ZZ3

NOTE 1: Submit a campaign claim on the "Claim Entry/Edit/Submit" screen on WebDCS and attach all required Digital Documentation per TSB to the claim.

NOTE 2: 5 / 60,000 New Vehicle Limited Warranty (NVLW) applies to the part(s) and repair procedure(s) outlined in this TSB. Prior to beginning any repair work, ensure the part(s) associated with the repair procedure are within NVLW, observing mileage and Warranty Start Date or date of first use. If the subject part(s) are out of warranty coverage, the dealer has the option to submit a Prior Approval (PA) Request for goodwill consideration on a case-by-case basis.

NOTE 3: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 4: This TSB includes repair justification photos. Op times include VIN, mileage, and repair justification photo(s) as outlined in the Digital Documentation Policy.

NOTE 5: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. Claim is subject to debit if the part is not returned.

Service Procedure:


DIGITAL DOCUMENTATION

This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.


NOTICE

Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.


1. Disconnect the negative (–) battery terminal (A).



2. Remove the front bumper cover (B) by referring to the shop manual:
 - **Body (Interior and Exterior) > Front Bumper > Front Bumper Cover > Repair procedures**



3. Remove the horn (C) by referring to the shop manual:
 - **Body Electrical System > Horn > Repair procedures**



4. Install the new horn in the reverse order of the removal process.

NOTICE

The horn can **ONLY** be mounted vertically.

- 5.

**DIGITAL
DOCUMENTATION**

Using the STUI camera function, take a photo of the original horn's production stamp.

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and date of repair on a piece of paper to include in the photo.



6. Reinstall all parts in the reverse order of the removal process.
7. Confirm the proper operation of the new horn.
8. The service procedure is now complete.