



INSTRUCTION TO SERVICE

ITS: 6777	
SECTION:	219 ENGINE & TRANSMISSION
WRITTEN BY:	Curtis Matthews
SUBJECT:	Driveshaft P/N: (540795) Inspection and Replacement

ITS6777

THIS DOCUMENT AND THE CONTENTS DISCUSSED HEREIN ARE THE CONFIDENTIAL AND PROPRIETARY INFORMATION OF NEW FLYER INDUSTRIES CANADA ULC AND NEW FLYER OF AMERICA INC. AND ARE DISCLOSED BY NEW FLYER IN CONFIDENCE. THIS DOCUMENT AND THE CONTENTS HEREIN ARE NOT TO BE DISCLOSED BY THE INTENDED RECIPIENT WITHOUT THE PRIOR WRITTEN AUTHORIZATION OF NEW FLYER. ANY UNAUTHORIZED DISCLOSURE, REPRODUCTION OR OTHER DISTRIBUTION OF THIS DOCUMENT OR INFORMATION IS STRICTLY PROHIBITED AND MAY RESULT IN ACTION BEING TAKEN AGAINST THE PARTY MAKING THE UNAUTHORIZED DISCLOSURE. THIS DOCUMENT AND ALL COPIES HEREOF MUST BE RETURNED TO NEW FLYER UPON REQUEST.

PART 1 – INSPECT DRIVESHAFT:

1. Turn the main battery disconnect switch to the “OFF” position.
2. Raise bus in accordance with the New Flyer Service Manual.
3. Locate the driveshaft under the bus between the rear axle and the traction motor in figure 1.




Figure 1: Rear underside of bus

4. Complete the Inspection sheet which can be found at the end of this Instruction while reading steps 5 through 8. Driveshafts that are **APPROVED** do not need to be replaced and driveshafts that are **NOT APPROVED** will need to be replaced.



NEW FLYER

5. Check for metal dust caps.

- Ways to identify if the cap is metal:
 - Tack welds on the top of the cap. See figures 2 and 3.
 - There are no raised letters on the top of the cap.
 - The cap attracts a magnet.
- If the cap is metal, then the driveshaft is **APPROVED**. Record that the cap is metal on the inspection sheet and proceed to step nine of this instruction.
- If the cap is plastic, proceed to step six.




Figure 2: Top view of metal cap with tack welds



Figure 3: Side view of metal cap with tack welds



NEW FLYER

6. If plastic cap is present, visually check for style of yoke and record on inspection sheet. Replace the driveshaft when materials are available.
- Style A – Plastic dust cap with balancing lugs. **NOT APPROVED**




Figure 4: Style A driveshaft

- Style B – Plastic Dust Cap and extended cutaway. **NOT APPROVED**




Figure 5: Style B driveshaft



NEW FLYER

- Style C – Plastic dust cap, and U-shaped yoke. **NOT APPROVED**




Figure 6: Style C driveshaft

- Style D – Plastic dust cap and shallow cutaway. **APPROVED**




Figure 7: Style D driveshaft

- Style E – Plastic dust cap and horizontal cutaway. **APPROVED**




Figure 8: Style E driveshaft

- Style F – Plastic dust cap and oval cutaway. **APPROVED**




Figure 9: Style F driveshaft

- Record the date code and work order (W/O) number seen in figures 10 and 11 (if legible).



Figure 10: Date code sticker




Figure 11: Close-up of date code sticker

8. If the driveshaft is **NOT APPROVED**, inspect the slip yoke for cracks at the center of the U-joint as seen figure 12.




Figure 12: Driveshaft area of concern for cracks

- NOTE:** If the driveshaft is **NOT APPROVED** but has no visible crack, it can continue to be used in service until a replacement driveshaft is available. If it is visibly cracked, the bus is to be held from service until a replacement driveshaft can be installed.
9. When the attached inspection sheet has been completed, forward it to your New Flyer Regional Support Manager to arrange for replacement parts and return shipping.
10. If the driveshaft is **APPROVED**, proceed to Part 3 – Return Bus to Service. If the driveshaft is not approved, proceed to Part 2 – Remove and Replace Driveshaft.



NEW FLYER

PART 2 – REMOVE AND REPLACE DRIVESHAFT:

1. Raise bus in accordance with the New Flyer Service Manual.
2. Support the driveshaft weight with ratchet straps to the bus frame as indicated in figure 13.

⚠ WARNING: For safety, two technicians are required anytime a driveshaft is being suspended or lifted.




Figure 13: Original driveshaft underside

3. Refer to figure 14 for driveshaft part identification.




Figure 14: Exploded view of driveshaft parts

4. Remove hardware that fastens the driveshaft flanges to the traction motor and the rear axle. Rotate pinion for better visibility of hardware on driveshaft. See figure 15.
 - a) Remove 4 screws P/N: (6312877) from the rear axle flange on slip yoke side.
 - b) Remove 4 bolts P/N: (541213) and 4 nuts P/N: (539023) from traction motor flange on yoke shaft side.
5. Safely lower the driveshaft.
6. Discard old driveshaft hardware and tag/paint the old driveshaft.




Figure 15: Original driveshaft

7. Support the weight of the new driveshaft using ratchet straps similar to note 2 and figure 13.

⚠ WARNING: For safety, two technicians are required anytime a driveshaft is being suspended or lifted.

8. Position the new driveshaft such that the mounting holes of the driveshaft flanges are lined up with the holes of the traction motor and rear axle flanges. Assure that the flange on the slip yoke side is aligned to the rear axle side rear axle flange.)

9. Mount driveshaft flanges to the traction motor flange and the rear axle flange. Rotate axle for better visibility of hardware. See figure 16.

a) Fasten the slip yoke to the rear axle with 4 screws P/N: (6312877). Torque screws to 81 ± 3 FT-LBS, DRY.

b) Fasten the yoke shaft flange to the traction motor flange with 4 bolts P/N: (541213) and 4 nuts P/N: (539023). Apply Loctite P/N: (081034) to bolt threads and torque bolts to 53 ± 5 FT-LBS, WET.




Figure 16: New installed driveshaft on Bus# 1252

10. Lubricate the slip joint and universal joints of the driveshaft using grease P/N: (507257) in accordance with the New Flyer Service Manual.



NEW FLYER

PART – 3 RETURN BUS TO SERVICE:

11. Ensure the inspection sheet has been completed and forward to the New Flyer Regional Product Support Manager to arrange replacement parts and return shipping.
12. Lower bus in accordance with the New Flyer Service Manual.
13. Remove all tools and debris and return the bus to service condition.
14. Turn the main battery disconnect switch to the “ON” position.



NEW FLYER

LABOUR ESTIMATE

	Operation	Men	Hours	Labour Time M X HR
1	PART 1 and 3 – Inspect driveshaft.	1	0.5	0.5
2	PART 2 - Remove and replace driveshaft (if required).	2	1	2.0

PARTS REQUIRED

Item	Part Number	Description	Qty. per Coach	Units	Notes
1	581738	KIT-LOCKPLATE HARDWARE	1	EA	
2	6312877	SCREW-LOCK M12 X 40 MM LG	4	EA	
3	541213	BOLT-M14 X 2.0 X 50MM	4	EA	
4	539023	NUT-M14X2.0	4	EA	
5	507257	GREASE-MOBILUX EP-111	1	EA	
6	081034	LOCTITE-243 MEDIUM 10ML	0.01	EA	
7	540795	DRIVESHAFT – XDE60 BAE	1	EA	

SPECIAL TOOLS REQUIRED

Item	Part Number	Description	Qty. per Coach	Units	Notes
1	NPN	Magnet	1	EA	



Driveshaft Inspection Sheet

Bus Number: _____
SR: _____

Date: _____
Technician: _____

Item	Inspection Item	Result
1.	Dust cap material. See figures 2 and 3.	Metal - APPROVED <input type="checkbox"/>
		Plastic - Go to item 2 <input type="checkbox"/>
2.	Driveshaft style. (See figures 4 through 9. Caps are not approved only if they are plastic)	Style A - NOT APPROVED <input type="checkbox"/>
		Style B - NOT APPROVED <input type="checkbox"/>
		Style C - NOT APPROVED <input type="checkbox"/>
		Style D - APPROVED <input type="checkbox"/>
		Style E - APPROVED <input type="checkbox"/>
		Style F - APPROVED <input type="checkbox"/>
3.	Date code from sticker (If legible). See figure 10 and 11.	Date Code: WO#:
4.	Inspect the yokes for cracks, see figure 12. Are cracks visible?	Yes <input type="checkbox"/> No <input type="checkbox"/>

NOTE: When this inspection sheet is complete, please forward to your Regional Product Support Manager to arrange replacement parts and return shipping.