



Dear Dealer,

Pagani Automobili decided that on certain Huayra BC and Huayra Roadster there is the possibility that the engine cannot be started or that the engine stops when idling.

This issue is caused by a software bug in the battery management system of the lithium battery.

The solution identified is to replace the battery with an updated one supplied by Pagani.

This updated component (Pagani p/n 007148) can be ordered starting from April 18th on the Dealer Portal.

Please mark properly the defective component and isolate it from other Pagani spare parts.

In the case that any lithium battery is in your stock please inform your Pagani Aftersales Area Manager that will manage with you its replacement or firmware update.

The VIN(s) affected by the campaign can be checked using the Upgrade section of the Dealer Portal (Campaign code: CB#216-2018)

This campaign is specific to the VIN. Failure to verify in Dealer Portal may result in an improper repair.

SPARE PARTS / TOOL:

In order to carry out the upgrade you will need to order through the Dealer Portal the following spare parts:

Part No.	Description	Qty.
007148	Lithium Battery 50Ah RCE	1

(Please order the part before the entry of the car in the workshop to minimize the recall lead time)

CLAIM INFO:

Warranty claims must be submitted through the Dealer Portal using the Job type "Upgrade" with description " CB#216 - 2018 SAFETY RECALL CAMPAIGN - Lithium Battery".

Once this upgrade has been carried out please mark it as "Done" in the related CAR section of Dealer Portal.

Please attach to the Case copy of eventual vehicle towing invoice

Claimable hours: 0.5h

Aftersales
- Pagani Automobili SpA -

San Cesario sul Panaro, March 30th 2018

