OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-236

Manufacturer Name: Newmar Corporation

Submission Date: APR 13, 2018
NHTSA Recall No.: 18V-236
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Newmar Corporation

Address: 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone: 574-773-7791

Population:

Number of potentially involved : 653 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2018-2018 Newmar Bay Star Sport Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, there may be a loose electrical connection in the breaker box

that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as

necessary.

Production Dates: JUN 02, 2017 - OCT 12, 2017

VIN Range 1 : Begin : NR End : NR

■ Not sequential

Vehicle 2: 2018-2018 Newmar Bay Star

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, there may be a loose electrical connection in the breaker box

that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as

necessary.

Production Dates: JUN 02, 2018 - OCT 12, 2018

Vehicle 3: 2018-2018 Newmar Canyon Star

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, there may be a loose electrical connection in the breaker box

Descriptive Information :	that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as necessary.						
Production Dates:	JUN 02, 2017 - OCT 12, 2017						
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential			
Vehicle 4 : Vehicle Type : Body Style : Power Train :		wmar Ventana	a LE				
·	On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as necessary.						
Production Dates : VIN Range 1 :		OCT 12, 2017 NR	End: NR	☐ Not sequential			
	, 208						
Vehicle 5 : Vehicle Type : Body Style :		wmar Ventana	a .				
Power Train :	: NR						
Descriptive Information :	On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as necessary.						
Production Dates:	JUN 02, 2017 -	OCT 12, 2017					
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential			
Vehicle Type : Body Style :		wmar Dutch S	tar				
Power Train :							
Descriptive Information :	On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as necessary.						
Production Dates:	JUN 02, 2017 -	OCT 12, 2017					
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential			
Vehicle 7: 2018-2018 Newmar New Aire							

Vehicle Type :						
Body Style :						
Power Train :	NR					
Descriptive Information :	that was not pro heat at the conr	operly tightened nection, increasi	d. A loose ng the ri	loose electrical connection e power connection may ca sk of overheating or a fire. In the breaker box and perfo	nuse a buildup of Correction: Dealers	
Production Dates:	JUN 02, 2017 - 0	OCT 12, 2017				
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential	
	2018-2018 Nev	vmar Mountain	Aire			
Vehicle Type :						
Body Style :						
Power Train :						
Descriptive Information :	that was not pro heat at the conr	operly tightened nection, increasi	d. A loose ng the ri	loose electrical connection e power connection may cask of overheating or a fire. In the breaker box and perfo	nuse a buildup of Correction: Dealers	
Production Dates :	JUN 02, 2017 - (OCT 12, 2017				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
	2018-2018 Nev	vmar London Ai	re			
Vehicle Type :						
Body Style :						
Power Train :	NR					
Descriptive Information :	On certain motorhomes, there may be a loose electrical connection in the breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as necessary.					
Production Dates:	JUN 02, 2017 - 0	OCT 12, 2017				
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential	
W.L.J. 10	0010 0010 N	F				
Vehicle 10: Vehicle Type : Body Style : Power Train :		vmar Essex				
Descriptive Information :		orhomes there	mav be a	loose electrical connection	n in the breaker boy	
2 oscipare mornadon.	that was not pro heat at the conr	operly tightened nection, increasi	d. A loose ng the ri	e power connection may ca sk of overheating or a fire. In the breaker box and perfo	ause a buildup of Correction: Dealers	

Production Dates:	IIIM 02	2017	OCT 12	2017
Production Dates:	JUN UZ.	2U17 ·	- UCI 12.	~U1/

Vehicle 11: 2018-2018 Newmar King Aire

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: On certain motorhomes, there may be a loose electrical connection in the breaker box

that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker box and perform repairs as

necessary.

Production Dates: JUN 02, 2017 - OCT 12, 2017

VIN Range 1: Begin: NR End: NR \square Not sequential

Description of Defect:

Description of the Defect: On certain motorhomes, there may be a loose electrical connection in the

breaker box that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections in the breaker

box and perform repairs as necessary.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A loose power connection may cause a buildup of heat at the connection,

increasing the risk of overheating or a fire.

Description of the Cause: A loose power connection may cause a buildup of heat at the connection,

increasing the risk of overheating or a fire.

Identification of Any Warning Breaker box connections could produce heat.

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Newmar Corporation Address: 355 N Delaware St.

Nappanee INDIANA 46550

Country: United States

Chronology:

On 4/6/2018 Newmar was made aware of a possible defect, on 4/10/2018 Newmar made a decessionn to file a recall. On 4/13/2008, Newmar is giving notice of a recall.

Description of Remedy:

Description of Remedy Program: tightening loose connections to the correct spec.

How Remedy Component Differs NR from Recalled Component :

Identify How/When Recall Condition 4/6/2018 an additional check/audit to electrical connections was started

was Corrected in Production : in production line.

Recall Schedule:

Description of Recall Schedule: On or before 6/12/2018, customer and dealer letters will begin mailing

out.

Planned Dealer Notification Date : JUN 12, 2018 - JUN 12, 2018 Planned Owner Notification Date : JUN 12, 2018 - JUN 12, 2018

^{*} NR - Not Reported