

September 13, 2018

Version 3

Safety Recall: 2017-18 NSX Fuel Tank

Supersedes 18-053, dated September 12, 2018, to revise the information highlighted in yellow

AFFECTED VEHICLES

| Year | Model | Trim | VIN Range |
|---------|-------|------|--|
| 2017-18 | NSX | ALL | Check the iN VIN status for eligibility. |

REVISION SUMMARY

Under WARRANTY CLAIM INFORMATION, information was added about claiming alignment shims.

Under TOOL INFORMATION, a tool was added.

Under REPAIR PROCEDURE, additional steps were added.

BACKGROUND

The welds in the fuel tank for the crossover pipe are improperly sealed. Clients may notice a strong fuel smell.

California residents only: This safety recall also affects emissions. Have the service consultant give the certificate to the client as proof that the recall was completed.

CLIENT NOTIFICATION

Owners of affected vehicles will be sent a notification of this campaign.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Some vehicles affected by this campaign may be in your used vehicle inventory.

Failure to repair a vehicle subject to a recall or campaign may subject your dealership to claims or lawsuits from the client or anyone else harmed as a result of such failure. To see if a vehicle in inventory is affected by this safety recall, do a VIN status inquiry before selling it.

CORRECTIVE ACTION

Replace the fuel tanks.

CLIENT INFORMATION:The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.

PARTS INFORMATION

| Part Name | Part Number | Quantity |
|-------------------------------------|---------------|----------|
| Fuel Tank Assembly Repair Parts Kit | 06170-T6N-305 | 1 |
| Left Fuel Tank | 17044-T6N-A01 | 1 |
| Right Fuel Tank | 17044-T6N-A13 | 1 |

REQUIRED MATERIALS

| Part Name | Part Number | Quantity |
|---|-------------|----------|
| Acura Long-Life Antifreeze/Coolant Type 2 | OL999-9011A | 4 |
| Acura Gear Oil GO-Type | 08200-9018A | 2 |

TOOL INFORMATION

| Part Name | Tool Number | Quantity |
|----------------------------------|---------------|----------|
| Tank Removal Adapter | 07AAK-T6NA300 | 1 |
| Arm Holder | 07AAB-T6NA400 | 1 |
| Brake Disc Covers (set of 4) | 07AAZ-T6NA800 | 1 |
| Hose Plug Set | 07AAZ-T6NA600 | 1 |
| Fender Covers | 07AAZ-T6NA200 | 1 |
| Lug Nut Cap Removal Tool | 07AAC-T6NA100 | 1 |
| Fuel Tank Unit Locknut | 07AAA-SNAA100 | 1 |
| Fuel Pump Module Locknut Wrench | 070AA-T0AA100 | 1 |
| Wheel Stud Guide Pins (set of 2) | 07AAB-T6NA200 | 1 |

WARRANTY CLAIM INFORMATION

Fuel Tank Replacement

To file a warranty claim for fuel reimbursement, you must do the following:

- Select **O1** from the **Sublet Code** drop-down.
- Enter the total MILES driven for refueling (ex. 15MILE) in the Work Description field.
- Enter the fuel receipt, invoice, transaction, or sequence etc. number in the Invoice No. field.
- Enter the amount in the Sublet Amount field
- Upload a image of the fuel receipt (required).

| | Sublet Informa | tion | 1 | | |
|--------------------------|------------------|------|-------------|-------------|---------------|
| Sublet Code | Work Description | | Invoice No. | Rental Days | Sublet Amount |
| 01 🗸 | 15MILE × | | 764646464 | | 14.00 |
| << SELECT >> V | | | | | |
| Upload files | File Attachme | nts | | | |
| Uploaded JPG/PDF Files 0 | (Maximum 10) | | | | |
| Fuel Receipt | Browse | | Brindew | Opford | |


Alignment shims maybe needed to properly do the alignment, the shims were added under the material reimbursement section in the template.

| Operation Number | Description | Flat Rate Time | Defect Code | Symptom Code | Template ID | Failed Part Number |
|--|-------------------------------|-------------------|----------------|-----------------|----------------|--------------------|
| Replace the right and left side fuel tanks (includes alignment, VSA sensor neutral position procedure, fluid drain/refill and test drive). | | 10.3 hrs | 6ТК00 | U2900 | B18053A | 17044-T6N-A01 |
| Only use the te | mplates below if fuel fill-up | is required. | | | | |
| В | Travel 1-10 miles for fuel | 0.2 hr | 6TK00 | U2900 | B18053B | 17044-T6N-A01 |
| С | Travel 11-20 miles for fuel | 0.4 hr | 6TK00 | U2900 | B18053C | 17044-T6N-A01 |
| D | Travel 21-30 miles for fuel | 0.6 hr | 6ТК00 | U2900 | B18053D | 17044-T6N-A01 |


Skill Level: Repair Technician

REPAIR PROCEDURE

- 1. Set the vehicle on the lift. Refer to the service information.
- 2. Protect and cover the body panels surrounding the engine compartment.
- 3. Remove the engine room covers. Refer to the service information.
- 4. Remove the driver's side air cleaner assembly. Refer to the service information.
- 5. Drain the fuel from both fuel tanks.
 - 5.1. Remove the PGM-FI main relay 3 (UNDER HOOD).
 - 5.2. Remove the PGM-FI main relay 2 (CABIN).
 - 5.3. In Maintenance Mode do the Forced PI Idling Mode, then let the engine idle until it stalls.
 - 5.4. Remove the fuel return hose from the fuel pressure regulator, and add an extension tube to an empty fuel container.




5.5. Jump the PGM-FI main relay 3 (UNDER HOOD) 4-pin connector terminal No.1 and No. 2 with a jumper wire, and turn the ignition to ON.



5.6. Wait until all the fuel is drained.

6. Disconnect the fuel vapor line (located below the removed driver's air cleaner assembly).



- 7. Turn off the IMA service plug.
 - 7.1. Move the driver's seat all the way forward.
 - 7.2. Remove the lower portion of driver's door seal. Refer to the service information.




Do not completely remove the driver's door seal.

7.3. Remove the driver's C-pillar trim.


NOTE

To avoid damage when removing the C-pillar trim make sure you detach it from the outer edge near the rear glass and not at the seat belt webbing pocket.



Do not pull on the seat belt webbing pocket.

- 7.4. Remove the driver's rear side trim panel. Refer to the service information.
- 7.5. Pull the rear bulkhead carpet up to access and remove the service plug cover.




- 7.6. Remove the service plug. Refer to the service information.
- 8. Disconnect the 12-volt terminals to the battery. Refer to the service information.
- 9. Raise the vehicle.
- 10. Remove the rear wheels.

NOTE


Protect the brake disk from damage and install the brake disk cover.

11. Remove both left and right inner fender liners. Refer to the service information.

12. On the passenger side rear wheel well, disconnect the following:




- OVR tube (next to frame beam)
- Lower intercooler hose (Unclamp and move.)
- PI fuel feed pipe
- Fuel tank unit connector
- Clip harness tab for the OVR
- Clip harness tab for the fuel line return




13. On the driver's side rear wheel well, do the following:





- Unclamp and move the intercooler hose.
- Remove the black bracket holding the fuel tank (top side fasteners).
- Disconnect the two electrical connectors.
- Disconnect the fuel filler neck.
- Disconnect the PI fuel feed pipe to the fuel pump.
- Unhook the tube clamp on the firewall side.



- 14. Remove the engine undercover. Refer to the service information.
- 15. Remove the (rear) center tunnel reinforcement. Refer to the service information.

- 16. Remove the two gear oil thermostat housing fasteners.
- 17. Remove the (front) rear subframe. Refer to the service information.


NOTE

Pay attention to the bolt length and locations.

18. Drain the engine coolant only from the water pipe underneath the vehicle.


NOTE

After the coolant has drained, reinstall the drain bolts with new washers included in the kit.



- 19. Disconnect the water hoses from the center pipes and cap off the ends.
- 20. Disconnect the two gear oil pipes in the center tunnel. Refer to the service information.
- 21. Disconnect the coolant heater hose and cap off.
- 22. Disconnect the rear motor power cable. Refer to the service information.
- 23. Remove the rear bulkhead upper brace, rear bulkhead lower brace, and fuel pipe separator bracket. Refer to the service information.
- 24. Remove the crossover pipe bracket bolts. Refer to the service information.
- 25. Remove the fuel tank separator braces. Refer to the service information.
- 26. Place the tank removal adapter and the powertrain lift table under the fuel tank assembly. Refer to the service information.
- 27. Remove the fuel tank strap bolts.
- 28. Slightly lower the fuel tank assembly, On the passenger side tank, reach over and disconnect the fuel return tube.
- 29. Completely lower the fuel tank assembly, making sure none of the remaining hardlines and hoses get snagged.


30. Install the fuel tank damper (suppled with the new fuel tanks) as shown.



- 31. Refer to the service information, and transfer the following to the new fuel tank assembly:
 - Fuel sending units (left and right)
 - Fuel tank protectors
 - Fuel transfer tubes
 - Vapor transfer tube
 - Cross over pipe and tubes

NOTE

Install the supplied tape around the fuel tube spacer as shown.



- 32. Install the new fuel tank assembly in to the vehicle, and install the parts in the reverse order of removal.
- 33. Top off the transmission fluid. Refer to the service information.
- 34. Fill the coolant, and air bleed the system. Refer to the service information.
- 35. Refuel the vehicle.

NOTE

Make sure to note the mileage driven to refuel the vehicle; it is required for warranty reimbursement.

36. Do an alignment check, and make adjustments as needed.

NOTE

The fuel tanks must be fully fueled when doing an alignment. Also, be sure to follow the pre-alignment checks. Refer to the service information.

37. California residents only: Fill out a Vehicle Emissions Recall – Proof of Correction certificate, and use Z28 as the recall number. Have the service consultant give the certificate to your client, and advise him or her to keep it as proof that the recall was completed. Your client will need to submit this certificate to the DMV only if the DMV requests it. If you need more certificates, use reorder number Y0657.

| icense Number | Make | Year Model | Body Type | Vehicle Identification Number |
|---------------|-----------|----------------|------------------|---|
| M | lanufacti | urer | | Recall Number Z28 |
| device | | t applicable C | | red, modified and/or equipation to the new omission control on Control Laws. Address, City, State and Zip |
| Date | | | iership's Author | ized Signature |
| Date | | X Dea | ership's Author | ized Signature |

END