

Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision:

September 2018, DTNA received a report of a brake caliper with low torque on a vehicle at the Mt Holly manufacturing plant. The axle assembly plant was audited. The audit revealed that on certain vehicles, the specified process to fully torque fasteners may not have been followed, so proper torque cannot be guaranteed. October 2018, out of an abundance of caution, DTNA decided to initiate a voluntary safety recall for specific vehicles equipped with air disc brakes where the brake caliper mounting bolts may be incorrectly torqued.

Identify the Remedy

Describe the defect/noncompliance remedy program, including the manufacture's plan for reimbursement.

Potentially affected vehicles will be inspected and repaired as necessary. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.

Identify the Recall Schedule

Describe the recall schedule for notifications:

Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Begin Date:	<i>12/03/2018</i>
Planned Dealer Notification End Date:	<i>12/03/2018</i>
Planned Owner Notification Begin Date:	<i>12/03/2018</i>
Planned Owner Notification End Date:	<i>12/03/2018</i>

Manufacture's identification code for this recall (if applicable): *FL-794*

DTNA Representative;



Andy Jones
Manager
Compliance and Regulatory Affairs