CONDITION OF CONCERN

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the driver's and/or passenger's frontal air bag inflator to explode in the event of a crash. An air bag inflator explosion could result in metal fragments striking the driver or other vehicle occupants, resulting in serious injury or death. It is extremely important to schedule this repair as soon as possible, to ensure your safety and the safety of your passengers.

The vehicle may have had temporary air bag inflators installed under Safety Recalls 9116A and/or 8315F. However, both the driver and passenger PERMANENT remedy inflators must be replaced on all customer vehicles at the same time.

These are the same vehicles subject to Safety Recall 1817L.

SUBJECT VEHICLES

Model	VIN range	Build Date Range
2004-2006 B-Series Truck	ALL (except vehicles included in 2218A)	April 17, 2003 through May 2, 2006

MANDATORY AIR BAG INFLATOR RETURN

All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions are provided in Attachment IV, and can also be found on MGSS and the Dealer Assistance Group website. Failure to return the original inflator will result in a Warranty Claim Debit.

OWNER NOTIFICATION

Mazda will notify U.S. owners on January 17, 2018.

PARTS INFORMATION

A web page to order parts for this recall is available in MXConnect. A complete VIN is needed to process the order.

Description	Part Number	Quantity	Notes
Driver Frontal Air Bag Inflator	1FT1-57-K00	1	Permanent Repair
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

WARRANTY CLAIM PROCESSING INFORMATION

Recall 2218A – DAB "Permanent" Repair	Replacement of Driver Frontal Air Bag Inflator
Applicable Model	B-Series
Warranty Type	R
Process Number	J1801A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K00 / 1 pc
Labor Operation Number	YY792XRX
Labor Hours	0.4 hrs.
Sublet Code K1 – Towing	See Note below. DSM Authorization required

Note: For K1 Sublet – we are allowing towing charges to be claimed to the dealer. Please keep in mind, warranty towing claim guidelines will apply and DSM Authorization required. If customer is due a refund from towing costs, a dealer refund check copy is required to be attached, please use attachment ID D40 if used.

RENTAL CAR INFORMATION

Mazda encourages all dealers to utilize MCVP vehicles for any alternate transport requests. We are requesting dealer understanding and partnership regarding rental and MCVP utilization. Please make every effort to utilize MCVP vehicles in place of rental use. Rental is covered if customer has no alternative means of transportation.

Rental Car Warranty Claim Information

Please submit rentals on a separate claim problem number as follows:

	MCVP Vehicle Preferred	Rental Agency Vehicle
Warranty Type Code		А
Symptom Code		99
Damage Code		99
Part Number Main Cause	N/A	5555-19-17LR
Part Quantity	MCVP does not require claim	0
Labor Operation Code	submission	MM024XRX
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or
		Dealer
		Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day
		for the number of days
		customer had rental
Sublet Text		Number of days rental
		car was supplied to

Rental expenses exceeding the two-day limit will require prior DSM Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy. **NOTE: Please make every effort to accommodate the vehicle owner with this critical recall.**