

# Part 573 Safety Recall Report

## 19E-029

**Manufacturer Name :** Triumph Motorcycles America, LTD

**Submission Date :** APR 15, 2019

**NHTSA Recall No. :** 19E-029

**Manufacturer Recall No. :** 0033



### Manufacturer Information :

**Manufacturer Name :** Triumph Motorcycles America, LTD

**Address :** 100 Hartsfield Centre Parkway  
Suite 200 Atlanta GA 30354

**Company phone :** 678-854-2010

### Population :

**Number of potentially involved :** 500

**Estimated percentage with defect :** 3 %

### Equipment Information :

**Brand / Trade 1 :** Triumph

**Model :** Thruxton 1200

**Part No. :** A9708301

**Size :** NR

**Function :** NR

**Descriptive Information :** The recall population was determined from factory production records. The front fairing kit contains two conduits used to conceal electrical wiring. The remedy component include larger apertures in the conduit than the recalled component.

**Production Dates :** APR 14, 2016 - APR 05, 2019

**Brand / Trade 2 :** Triumph

**Model :** Thruxton 1200 R

**Part No. :** A9708412

**Size :** NR

**Function :** NR

**Descriptive Information :** As A9708301

**Production Dates :** APR 06, 2016 - APR 05, 2019

### Description of Defect :

**Description of the Defect :** The 2 conduits used to contain electrical wiring in these aftermarket fairing kits have insufficient clearance and may cause damage to the wiring.

**FMVSS 1 :** 123 - Motorcycle controls and displays

**FMVSS 2 :** NR

Description of the Safety Risk : Damaged wiring may lead to an engine stall or loss of the headlight or turn signals, increasing the risk of a crash.

Description of the Cause : In designing the conduit apertures to accommodate the wiring, insufficient clearance was specified.

Identification of Any Warning that can Occur : None

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

April 2019 - Whilst preparing components for a future model, Triumph's Accessories Department identified a potential concern with the fairing and advised Triumph's Quality Department. The Quality Department undertook testing to better understand the concern.

April 5th 2019. A Meeting was convened to review results of testing and a meeting of the Recall Committee was arranged to consider the effect on rider safety.

April 9th 2019. Triumphs Recall Committee decided to conduct a safety recall to address this issue. There have been no reports of accidents or injuries related to this concern.

## Description of Remedy :

Description of Remedy Program : 1. Dealers with unsold kits in their inventory will be asked to quarantine and scrap the conduit components and order replacement conduits. Dealers will also be asked to use their internal records to identify and notify affected owners (using a NHTSA-approved owner letter supplied by Triumph) and to arrange for replacement conduits to be supplied and, where installed on a customer motorcycle, fitted free of charge as soon as possible.

How Remedy Component Differs from Recalled Component : The remedy component (Part No. A9708524 (Thruxton) and A9708522 (Thruxton R)) includes larger apertures than the recalled component.

Identify How/When Recall Condition was Corrected in Production : not applicable

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : APR 19, 2019 - APR 26, 2019

Planned Owner Notification Date : APR 26, 2019 - APR 30, 2019

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported