

Part 573 Safety Recall Report

19E-051

Manufacturer Name : MORryde International, Inc.

Submission Date : JUL 31, 2019

NHTSA Recall No. : 19E-051

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : MORryde International, Inc.

Address : 1966 Sterling Avenue
Elkhart IN 46516

Company phone : (574) 293-1581

Population :

Number of potentially involved : 187

Estimated percentage with defect : 100 %

Equipment Information :

Brand / Trade 1 : F550 Battery Tray

Model : F550 Battery Tray

Part No. : Multiple, see notes

Size : NR

Function : NR

Descriptive Information : • Production run on a specific line during from 1/25/2019 – the date the change order was put through production. This is specific to the F550 chassis and this specific battery tray model. Identify the number of affected products related to this specific .

Production Dates : JAN 25, 2019 - JUL 10, 2019

Description of Defect :

Description of the Defect : The battery tray that is welded onto the frame of F550 chassis could be compromised due to inadequate welds.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The inadequate welds have a potential of failing causing the battery tray to break free from the chassis and allowing the content of the tray to discharge potentially causing personal injury or property damage.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

6/20/2019 – MORryde was notified by OEM that there was an incident where the battery tray broke off on one side. MORryde worked with OEM for further details. 7/15/2019 – MORryde notified of 2nd failure and received pictures of the failure. The pictures indicated a weld failure. MORryde worked with OEM for list of VIN's before and after failed VIN for preparation for inspection. MORryde went on site to inspect battery trays the week of 7/22/2019. 7/26/2019 – MORryde reviewed results and agreed that this is a safety recall.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : Provide Angle for additional weld area on both sides of the battery tray. Angle will be welded onto to tray and tray to add additional support.

Identify How/When Recall Condition was Corrected in Production : an Engineering Change Notice was put though to provide additional weld area for the battery tray and was effective with production starting 7/10/2019.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported