OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-100

Manufacturer Name: New Flyer of America Inc.

NHTSA Recall No.: 19V-100

Manufacturer Recall No.: R19-002



Manufacturer Information:

Manufacturer Name: New Flyer of America Inc.

Address: 711 Kernaghan Avenue

Winnipeg, MB Canada 00 R2C3T4

Company phone: 204-224-6706

Population:

Number of potentially involved : 172 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2018-2018 New Flyer XD40

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: Specifically equipped diesel 40 foot heavy duty urban transit buses. Effected vehicles

have a roof emergency escape hatch with an optional tempered glass panel.

Production Dates: APR 10, 2018 - APR 27, 2018

Vehicle 2: 2018-2018 New Flyer XDE60

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER

Power Train: HYBRID ELECTRIC

Descriptive Information: Specifically equipped diesel-electric 60 foot heavy duty urban transit buses. Effected

vehicles have a roof emergency escape hatch with an optional tempered glass panel.

Production Dates: MAY 10, 2018 - JUL 23, 2018

VIN Range 1: Begin: 5FYH8YU10JF055012 End: 5FYH8YU15JF055023 Not sequential

Vehicle 3: 2019-2019 New Flyer XE60

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER

Power Train: HYBRID ELECTRIC

Descriptive Information: Specifically equipped battery-electric 60 foot heavy duty urban transit buses. Effected

vehicles have a roof emergency escape hatch with an optional tempered glass panel.

Production Dates: OCT 31, 2018 - OCT 31, 2018

Vehicle 4: 2018-2019 New Flyer XN40

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: CNG/LPG

Descriptive Information: Specifically equipped compressed natural gas 40 foot heavy duty urban transit buses.

Effected vehicles have a roof emergency escape hatch with an optional tempered

glass panel.

Production Dates: OCT 16, 2017 - JAN 11, 2019

VIN Range 1: Begin: 5FYC8FB1XJF053432 End: 5FYC8FB17KC071230 ✓ Not sequential

Description of Defect:

Description of the Defect: The optional AS-3 tempered glass panel in rooftop emergency escape hatch

may shatter if subjected to extreme cold temperature conditions due to micro-

fractures forming at the unfinished surface edge of the glazing material.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: It the roof hatch tempered glazing shatters, glass particles could fall down

onto bus passengers, creating a potential for injury.

Description of the Cause: Failures are believed to stem from an unfinished edging treatment of glazing

material which was subject to extreme cold temperatures (-60 degrees F) during vehicle production. There have been no reports of failures on consumer

vehicles.

Identification of Any Warning None.

that can Occur:

Supplier Identification:

Component Manufacturer

Name : Safe Fleet - Bus & Rail Address : 13501 South Ridge Dr.

Charlotte NORTH CAROLINA 28273

Country: United States

Chronology:

In mid December of 2018 the glazing material on a roof hatch failed on a vehicle in production at out Crookston, MN facility after the bus was parked outside for an extended period.

On 2 January 2019 a second failure occurred, again on a bus parked outside for an extended period.

On 3 January the supplier, Safe Fleet, was contacted, failed parts were returned and an analysis was conducted. Analysis determined the presence of micro-fractures stemming from the unfinished edges of the glazing

material. It is believed that extended exposure to cold temperatures exacerbates the appearance of the micro-

On 1 February, a proposed solution was presented by the supplier (Safe Fleet) to provide new glazing material with increased thickness and a machine finished edging.

On February 6th the issue was put before the New Flyer Safety Committee for review and discussion.

On February 8th the Committee voted to declare a Safety Recall with the NHTSA ODI.

Description of Remedy:

Description of Remedy Program: New thicker glazing material will be supplied which has a machined

surface edge, and will be replaced/installed at no cost to the consumer. The time it takes to replace the glazing material on one roof hatch is 15

minutes.

How Remedy Component Differs The old product has a DOT glazing mark which is readable from inside the from Recalled Component: bus and has the glazing manufactures name and logo. The new product is thicker and has a DOT glazing mark which is readable from outside the bus

and has the glazing manufactures name, but no manufactures logo.

was Corrected in Production: 13 February 2019.

Identify How/When Recall Condition New Flyer began installing hatches with the improved glazing material on

Recall Schedule:

Description of Recall Schedule: New Flyer has no Dealers. No dealer notification letters will be created.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: FEB 28, 2019 - MAR 04, 2019

^{*} NR - Not Reported