OMB Control No.: 2127-0004

Not sequential

# Part 573 Safety Recall Report

# 19V-184

**Manufacturer Name:** General Motors LLC

**Submission Date:** APR 01, 2019 NHTSA Recall No.: 19V-184 Manufacturer Recall No.: N192209550



#### **Manufacturer Information:**

Manufacturer Name: General Motors LLC

Address: 29427 Louis Chevrolet Road

MAIL CODE 480-210-2V WARREN MI

48093

Company phone: 586-596-1733

## **Population:**

Number of potentially involved: 120 Estimated percentage with defect: 1 %

#### **Vehicle Information:**

Vehicle 1: 2019-2019 Chevrolet Equinox

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: Manufacturing records were used to identify vehicles that may have been built with

insufficient welds on the head-restraint bracket of the rear right seat. 58 Chevrolet

Equinox vehicles are affected by this recall.

Production Dates: JAN 11, 2019 - JAN 11, 2019

VIN Range 1: Begin: End: NR

Vehicle 2: 2019-2019 GMC Terrain

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: Manufacturing records were used to identify vehicles that may have been built with

insufficient welds on the head-restraint bracket of the rear right seat. 62 GMC Terrain

vehicles are affected by this recall.

Production Dates: JAN 11, 2019 - JAN 16, 2019

VIN Range 1: Begin: End: NR Not sequential

#### **Description of Defect:**

Description of the Defect: General Motors has decided that a defect which relates to motor vehicle safety

exists in certain 2019 model year Chevrolet Equinox and GMC Terrain vehicles. These vehicles may have insufficient welds on the head-restraint bracket of the

rear right seat.

FMVSS 1: NR

FMVSS 2: NR

Description of the Safety Risk: Insufficient welds at the head-restraint bracket may degrade management of

occupant loads in a crash, increasing the risk of injury in a crash for occupants

seated in the rear right position.

Description of the Cause: A weld tool at the tier-2 seat frame supplier was not properly cooled, resulting

in some insufficient spot welds.

Identification of Any Warning NR

that can Occur:

#### **Supplier Identification:**

# **Component Manufacturer**

Name: Amvian

Address: Oscar Flores Tapia 1305, Huerta del Cura

Ramos Arizpe, Coahuila FOREIGN STATES

Country: Mexico

### **Chronology:**

On January 12, 2019, the condition was discovered on a seat during a functional check performed at GM's San Luis Potosi assembly plant. Between January 12 and 15, GM's assembly plant and the seat-structure supplier conducted a component teardown of the seat and identified three spot weld separations on the upper flange of the head-restraint bracket. On January 15, the seat-structure supplier initiated containment actions. That same day, this issue was reported to GM's Speak Up For Safety program, and on January 22, 2019, GM opened an investigation into the suspect welds.

Working with the seat-structure supplier, GM determined that the suspect welds were all produced by a specific weld tool at the seat-structure supplier between January 4 and January 12, 2019. The weld tool was not properly cooled, which could result in some insufficient welds, also known as "cold welds." These potential cold welds would be located on the head-restraint bracket on the rear right seat. Over the next several weeks, GM analyzed the effect of the condition and determined that the presence of cold welds could decrease performance of the rear right head-restraint in certain rear-impact crashes.

The investigation was reviewed in GM's Open Investigation Review on February 25, 2019. On February 28, 2019, GM's Safety Field Action Decision Authority decided to conduct a safety recall.

#### **Description of Remedy:**

Description of Remedy Program: Dealers will replace the rear-right seatback frame. Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty so reimbursement is not offered.

The information contained in this report was submitted pursuant to 49 CFR §573

How Remedy Component Differs Replacement seatback frames were produced outside of the suspect

from Recalled Component: manufacturing window.

Recalled Component Name: PANEL ASM-R/SEAT BK

Recalled Component Description: Second Row (40%) Seatback Structure

Recalled Component Part Number: 84398377 Recalled Component Country of Origin: Mexico

Identify How/When Recall Condition Vehicles built with suspect seat frames were quarantined at the plant on

was Corrected in Production: January 16, 2019. The supplier initiated inspection containment on

January 12, 2019 and implemented corrective measures to the weld tool

on January 15, 2019.

#### **Recall Schedule:**

Description of Recall Schedule: General Motors will notify dealers on March 7, 2019. Owner letter

mailing is planned for April 15, 2019.

Planned Dealer Notification Date: MAR 07, 2019 - MAR 07, 2019 Planned Owner Notification Date: APR 15, 2019 - APR 15, 2019

\* NR - Not Reported