OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-260

Manufacturer Name: Labrie Enviroquip Group

Submission Date: APR 01, 2019 NHTSA Recall No.: 19V-260 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Labrie Enviroquip Group

Address: 175-b marie-victorin

LEVIS 00 G7A 2T3

Company phone: 418-831-8250

Population:

Number of potentially involved: Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2017-2018 Labrie Enviroquip group Au and EX (Cng tailgate)

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: CNG/LPG

Descriptive Information: Labrie installed 34 luxfer tanks (G2781-B03 MPVE-250) on 17 units (Canada and US).

These tanks add a recall on the shutoff valve.

VIN Range 1: Begin: 5VCACRLEOHH223601 End: 5VCACRLE4HH223603

Production Dates: OCT 06, 2017 - MAR 03, 2019

VIN Range 2: Begin: 1H9ACAAF8H1674514 End: 1H9ACAAFXH1674515 VIN Range 3: Begin: 1H9AADAD7J1674810 End: 1H9AADAD2J1674813 VIN Range 4: Begin: 5VCACRLEOHH223601 End: 5VCACRLE4HH223603 VIN Range 5: Begin: 1H9ACAAF8H1674514 End: 1H9ACAAFXH1674515 VIN Range 6: Begin: 1H9AADAD7J1674810 End: 1H9AADAD2J1674813 VIN Range 7: Begin: 5VCACDLE3JC226868 End: 5VCACDLE5JC226869 VIN Range 8: Begin: 5VCACRLEOHH223601 End: 5VCACRLE4HH223603

VIN Range 9: Begin: 1H9ACAAF8H1674514 End: 1H9ACAAFXH1674515 VIN Range 10: Begin: 1H9AADAD7J1674810 End: 1H9AADAD2J1674813

VIN Range 11: Begin: 5VCACDLE3JC226868 End: 5VCACDLE5JC226869

☐ Not sequential ■ Not sequential Not sequential Not sequential Not sequential

Not sequential

Not sequential Not sequential

Not sequential

Not sequential Not sequential

Description of Defect:

Description of the Defect: Using tools to

rotate the knob can severely over-torque the valve. The valve's snap ring

prevents rotation of the valve's knob more than "one-turn." Severe

overtorqueing

can potentially damage the valve's snap ring and its gland.

FMVSS 1: NR

FMVSS 2: NR

Description of the Safety Risk: The stem can become a projectile due to the rapid depressurization of the

CNG fuel system, presenting a risk of bodily harm from impact. In addition, this unintended/inadvertent release of CNG, especially in an enclosed space,

presents a risk of fire or explosion if exposed to an ignition source.

Description of the Cause: Misuse of the valve by severe over-torqueing with tools.

Identification of Any Warning The knob may be much more difficult to turn than on an undamaged valve.

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Luxfer Cylinder

Address: 4410-46 Avenue SE

Calgary FOREIGN STATES T2B 3N7

Country: Canada

Chronology:

Due to the character linitation in this electronic form, Luxfer, the manufacturer of the valve, has attached its complete answer to this inquiry as "attachement A to ammended section 573 report".

Description of Remedy:

Description of Remedy Program: Luxfer will supply an Upgrade Kit for each valve, and credit vehicle

manufacturers \$100 for each valve upgraded, up to a limit of \$250 per vehicle for those vehicles with multiple valves. The upgrade kit is field

installable by an appropriately skilled technician.

How Remedy Component Differs The Upgrade Kit, which includes "No tools" decals, knob and a backup ring

from Recalled Component: and nut, which doubles the valve's over-torque resistance.

Identify How/When Recall Condition Luxfer produced a new variant MPVE-250-2 One-Turn Valve,

was Corrected in Production: incorporating components similar to the Upgrade Kit, intended to mitigate

over-torqueing.

Recall Schedule:

Description of Recall Schedule: Our service departement is in contact with the distibutors to plan the

modification. At this moment Luxfer has repaired all the valve for GFI

Edmonton (3 trucks).

Part 573 Safety Recall Report

19V-260

Page 3

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573