Part 573 Safety Recall Report

Manufacturer Name :Volkswagen Group of America, Inc.Submission Date :JUN 06, 2019NHTSA Recall No. :19V-389Manufacturer Recall No. :94L9



19V-389

Manufacturer Information :

Manufacturer Name :Volkswagen Group of America, Inc.Address :3800 Hamlin RoadAuburn Hills MI 48326Auburn Hills MI 48326Company phone :1-800-893-5298

Population :

Number of potentially involved : 662,185 Estimated percentage with defect : 7 %

Vehicle Information :

| Vehicle 1 : Vehicle Type : Body Style : | 2016-2019 Volkswagen Passat (GP) |
|---|--|
| Power Train : | NR |
| | Vehicles included in this recall (built during a certain time period) may not have had the required caps installed to disable the headlight horizontal aim as required by Federal Regulations. Vehicles not included in this recall were built with the required headlight caps installed. Passat (GP) vehicle count: 122222 |
| | APR 20, 2015 - JAN 14, 2019 Begin : 1VWAS7A39GC000438 End : 1VWLA7A35KC014664 V Not sequential |
| Vehicle 2 : Vehicle Type : Body Style : | 2020-2020 Volkswagen Passat (PA2) |
| Power Train : | NR |
| Descriptive Information : | Vehicles included in this recall (built during a certain time period) may not have had the required caps installed to disable the headlight horizontal aim as required by Federal Regulations. Vehicles not included in this recall were built with the required headlight caps installed. Passat (PA2) vehicle count: 15 |
| Production Dates : | OCT 17, 2018 - DEC 19, 2018 |
| Vehicle 3 : Vehicle Type : Body Style : | 2018-2019 Volkswagen Atlas |
| The ir | nformation contained in this report was submitted pursuant to 49 CFR §573 |

Part 573 Safety Recall Report

19V-389

| Page | 2 |
|------|---|
|------|---|

| | NR |
|---|---|
| Descriptive Information : | Vehicles included in this recall (built during a certain time period) may not have had the required caps installed to disable the headlight horizontal aim as required by Federal Regulations. Vehicles not included in this recall were built with the required headlight caps installed. Atlas vehicle count: 116055 |
| | NOV 17, 2016 - FEB 12, 2019 Begin : 1V2NR2CA2JC500090 End : 1V2UR2CA6KC540850 ✓ Not sequential |
| Vehicle 4: | 2012-2015 Volkswagen Passat |
| Vehicle Type : | 0 |
| Body Style : | |
| Power Train : | NR |
| Descriptive Information : | Vehicles included in this recall (built during a certain time period) may not have had the required caps installed to disable the headlight horizontal aim as required by Federal Regulations. Vehicles not included in this recall were built with the required headlight caps installed. Passat vehicle count: 423893 |
| Production Dates : | DEC 23, 2010 - OCT 02, 2015 |
| | |
| Description of Noncomplia | ince : |
| Description of | According to Federal Motor Vehicle Safety Standard (FMVSS) 108, the headlight is not permitted to have a horizontal adjustment. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not have the required cap installed. |
| Description of Noncompliand FMVSS | According to Federal Motor Vehicle Safety Standard (FMVSS) 108, the headlight is not permitted to have a horizontal adjustment. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not |
| Description of Noncompliand FMVSS FMVSS | According to Federal Motor Vehicle Safety Standard (FMVSS) 108, the headlight is not permitted to have a horizontal adjustment. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not have the required cap installed. 1: 108 - Lamps, reflective devices, and assoc. Equipment |
| Description of Noncompliand FMVSS FMVSS Description of the Safety Ris | According to Federal Motor Vehicle Safety Standard (FMVSS) 108, the headlight is not permitted to have a horizontal adjustment. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not have the required cap installed. 1: 108 - Lamps, reflective devices, and assoc. Equipment 2: NR sk : Incorrectly adjusted headlights may result in reduced visibility (for the driver |

The information contained in this report was submitted pursuant to 49 CFR \$573

Supplier Identification :

Component Manufacturer

Name : Volkswagen Group of America, Inc. Address : 3800 Hamlin Road Auburn Hills MICHIGAN 48326 Country : United States

Chronology:

Late January 2019: Process analysis at the factory identifies missing instructions in the Standard Work Process and missing and incorrect Instructions in the Product Detail Montage (PDM), relating to the installation of headlight adjuster caps.

February 2019: Work instructions corrected and inspection of Atlas and Passat headlights at CP8 (Chattanooga factory grounds), external yards, and auction center to determine impact of missing instructions.

March and April 2019: Discussion with supplier and internal clarification of regulatory requirements, affected population, and countermeasures.

May 06, 2019: Topic was presented in the Product Safety Committee pre-clearing.

May 10, 2019: Further analysis and clarification by the factory and VWAG, including testing of whether, and to what extent, horizontal adjustment is possible and the impact on compliance with thresholds in FMVSS 108. May 15, 2019: Topic was presented to the Volkswagen Product Safety Committee and a non-compliance was determined for both Atlas and Passat vehicles.

Description of Remedy :

| Description of Remedy Program : | Inspect the left and right headlight for presence of blocking cap on horizontal adjuster. If a cap is missing, the adjustment mechanism will be blocked. A repair method is under evaluation. The recall repair will be performed free of charge to customers. Volkswagen will not offer a reimbursement program under this recall. |
|---------------------------------|---|
| | The recalled part number of the blocking cap is 4E0 941 041. For the recall remedy, the adjustment mechanism will be blocked with an component/procedure (currently under evaluation). |
| 0 | 04/02/2019: Worker instructions were revised to include cap installation at the headlight alignment station. |

Recall Schedule :

Ι

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

19V-389

Page 4

| Description of Recall Schedule : | Dealers: On or before 06/12/2019 Owners: On or before 07/19/2019 | |
|---|---|--|
| Planned Dealer Notification Date : Planned Owner Notification Date : | | |

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573