OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-421

Manufacturer Name: Jaguar Land Rover North America, LLC

Submission Date: JUN 06, 2019 NHTSA Recall No.: 19V-421 Manufacturer Recall No.: N341



Manufacturer Information:

Population:

Manufacturer Name: Jaguar Land Rover North America, LLC

Number of potentially involved: 2,200

Address: 100 Jaguar Land Rover Way

Estimated percentage with defect: 100 %

Mahwah NJ 07495

Company phone: 8188500

Vehicle Information:

Vehicle 1: 2020-2020 LAND ROVER RANGE ROVER EVOQUE

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: NR

Descriptive Information: Certain 2020 Model Year Range Rover Evoque vehicles where the fuse in the Engine

Junction Box (EJB) for the front or rear windshield washer system may fail should the system be operated in freezing or blocked conditions. An interpretation related SAE J942 from 1972 makes clear the requirement for washers to operate following a

frozen state operation.

Production Dates: NOV 02, 2018 - APR 04, 2019

☐ Not sequential VIN Range 1: Begin: SALZM2GX5LH000181 End: SALZP2FX0LH019195

Description of Noncompliance:

Description of the A concern has been identified on certain 2020 Model Year Range Rover Evoque

Noncompliance: vehicles where the fuse in the Engine Junction Box (EJB) for the front or rear

windshield washer system may fail should the system be operated in freezing or blocked conditions. An interpretation related SAE J942 from 1972 makes

clear the requirement for washers to operate following a frozen state

operation.

FMVSS 1: 104 - Windshield wiping and washing systems

FMVSS 2: NR

Description of the Safety Risk: Vehicles in this condition do not meet the requirements of Federal Motor

Vehicle Safety Standards (FMVSS) 104, Windshield Wiping and Washing Systems. This could reduce the driver's visibility increasing the risk of a

crash.

Description of the Cause: NR

Identification of Any Warning NR that can Occur:

Supplier Identification:

Component Manufacturer

Name: Jaguar Land Rover Limited

Address: Abbey Road

Whitley, Coventry FOREIGN STATES CV3 4LF

Country: United Kingdom

Chronology:

A Product Safety and Compliance Committee (PSCC) investigation was opened on March 26, 2019, following failures of the windshield washer pump, noted during vehicle cold weather testing on prototype vehicles in Sweden.

PSCC reviewed the relevant FMVSS regulation 104 and SAE J942 testing procedure with associated interpretations in April, 2019. Testing by the engineering teams through April and May 2019 confirmed the repair required replacement of the 15A fuse with a 25A fuse in the EJB.

The investigation was again reviewed at the PSCC on May 28, 2019, and concluded the issue should be progressed to the Jaguar Land Rover Recall Determination Committee (RDC).

The RDC reviewed all information on May 30, 2019 and the committee determined that the condition represented a compliance concern and that a non-compliance recall be conducted.

There have been no reported accidents, injuries or fires as a result of this concern.

Description of Remedy:

Description of Remedy Program: Land Rover will notify owners, and authorized repairers will replace the

15A fuses with 25A fuses for the front and rear washer systems. The Engine Junction Box lid will also be replaced so the vehicle fuse amperage

schematic embossed on the lid displays the correct fuse rating. A handbook supplement will also be printed and inserted into the owner

handbook

How Remedy Component Differs NR from Recalled Component:

Part 573 Safety Recall Report

19V-421

Page 3

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: Distribution of owner notification letters will occur on or before August

2, 2019. Notifications to dealers will occur on July 8, 2019.

Planned Dealer Notification Date : JUL 08, 2019 - JUL 08, 2019 Planned Owner Notification Date : AUG 02, 2019 - AUG 02, 2019

* NR - Not Reported