Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



## **IMPORTANT SAFETY RECALL**

October 2019

This notice applies to your vehicle, VIN:

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Isuzu Motors Limited has decided that a defect, which relates to motor vehicle safety, exists in certain 2017-2019 model year Chevrolet Low Cab Forward 3500/4500/6500XD medium duty vehicles. These vehicles are manufactured by Isuzu. As a result, GM is conducting a safety recall.

We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

	<ul><li>Your vehicle is involveneet.</li><li>Schedule an appoint</li></ul>	<b>I P O R T A N T</b> red in GM safety recall N ment with your GM deale erformed for you at <b>no c</b>	er.			
Why is your ve being recalled′	hicle In some of the affected been properly tightened melting of the power wi lead to an engine stall.	vehicles, the power supp during harness production re and/or a loss of electri	bly bolt in the relay box may on at the supplier. This may cal power to the vehicle, wh ehicle could lose electrical p	/ lead to ich can		
What will we d	During the inspection, the excess insulation. If the excess insulation will be appropriate specification repaired or replaced. The of service scheduling replaced than the actual in the actual integration of the service scheduling replaced than the actual integration.	Your GM dealer will inspect and torque the power supply bolt in all affected vehicles. During the inspection, the harness and relay box will be checked for damage and any excess insulation. If there is any excessive insulation, the bolt will be removed, the excess insulation will be trimmed away, and the bolt will then be torqued to the appropriate specification. If the harness or relay box is found to be damaged it will be repaired or replaced. This service will be performed for you at <b>no charge</b> . Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual inspection and service correction time of approximately 48 minutes, but additional time may be necessary.				
What should yo do?	You should contact you possible.	You should contact your GM dealer to arrange a service appointment as soon as possible.				
Do you have questions?				se contact		
	Division	Number	Text Telephones (TTY)	]		
	Puerto Rico – Enalish	1-800-496-9992				

Division	Number	Text Telephones (TTY)
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	
GM Medium Duty Truck	1-800-862-4389	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 19V647.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Maryann L. Combs Vice President Global Vehicle Safety

## GM Recall: N192263741