

Part 573 Safety Recall Report

19V-705

Manufacturer Name : Jayco, Inc.**Submission Date :** OCT 14, 2019**NHTSA Recall No. :** 19V-705**Manufacturer Recall No. :** 9903440**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 1,660

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2014-2018 Class C motorhome Precept

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Production records on all Precepts produced prior to date when heat shields were installed on the Ford F53 chassis. - Complete list of affected units uploaded on excel worksheet

Precept Models affected UL, UP UT US UU UV

2014 Precept E1UL0051-0258

2015 Precept F1UL0051-0356 UP0051-0086

2016 Precept G1UL0051-0395 UP0051-0082

2017 Precept H1UL0051-0210 UP0051-0061 UT 0051-0053

2018 Precept j1UL0051-0288 US0051-0154 UT0051-0168 UU0051-0176 UV
0051-0146

Production Dates : JAN 03, 2013 - MAR 01, 2018

VIN Range 1 : Begin : NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Incorrect routing of hydraulic line - too close to exhaust and heat shield was omitted during production as required per Ford Emissions Certification Manufactures are responsible for providing thermal protection (e.g. underbody heat shields) for any structure and/or equipment added to the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Incorrect routing of the hydraulic line increases risk of line melting from exhaust, creating a fire hazard to occupants.

Description of the Cause : NR
Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

8-12-19 VOQ#11242053 received noting a missing heat shield on a 2017 Precept resulted in the plastic storage bin above the catalytic converter started to melt. Engineering, Production and Compliance teams started research into matter. In depth Research found incident rates as high as 6% on some Precept models - All Precepts produced prior to 9-2-2016 are at risk . Heat shields were installed starting 9-2-2016 In addition, Incident was reported on a Precept that the hydraulic lines were too close to the exhaust and melted the line. 9-18-19 CPAC reviewed analysis of research and agreed to escalate to Safety Committee recommending a recall 9-26-19 Safety Committee reviewed analysis and agreed recall required.

Description of Remedy :

Description of Remedy Program : Inspect hydraulic lines for correct routing, - away from exhaust and Install heat shield. - replace damaged lines
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Upon completion of remedy instructions to install the heat shield and parts procurement, Jayco will release recall to current owner on record. ,
Planned Dealer Notification Date : NOV 15, 2019 - NOV 15, 2019
Planned Owner Notification Date : NOV 15, 2019 - NOV 15, 2019

* NR - Not Reported