

Part 573 Safety Recall Report

19V-756

Manufacturer Name : Volvo Trucks North America**Submission Date :** OCT 24, 2019**NHTSA Recall No. :** 19V-756**Manufacturer Recall No. :** RVXX1906**Manufacturer Information :**

Manufacturer Name : Volvo Trucks North America

Address : 7900 National Service Road
Greensboro NC 27409

Company phone : 800 528 6586

Population :

Number of potentially involved : 2,287

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2020-2020 Volvo VNL VNM

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : The recall population is based on available facts at the time of this report. These facts include (1) reports of the issue are limited to new Volvo brand vehicles manufactured in 2019 with Sheppard Steering Gear (part number 22803500) HD 94 Gear Variant, and (2) Torque loss of steering gear mounting fasteners in vehicles with Sheppard HD94 Gear variant. Further investigation/ collaboration between Sheppard and Volvo is proceeding to confirm root cause and scope.

Production Dates : JAN 01, 2019 - OCT 17, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : On certain vehicles, torque loss of steering gear mounting fasteners may occur on vehicles manufactured with a Sheppard HD94 Steering Gear.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Torque loss can result in loosening of the steering gear, which may result in loss of vehicle control under certain conditions.

Volvo has not received any reports of vehicle crashes as a result of this defect. Volvo is taking the proactive measure to conduct a voluntary safety recall to protect our customers and other road users from the potential risk related to the defect.

Description of the Cause : Cause is being investigated.

Identification of Any Warning Loose fasteners are detectable during visual inspection, Also, reports of

that can Occur : alignment and handling concerns received, suggests that the driver may be able to discern that there is an issue through the steering/ handling "feel" .

Supplier Identification :

Component Manufacturer

Name : R.H. Sheppard
Address : 101 Philadelphia Street
Hanover PENNSYLVANIA 17331
Country : United States

Chronology :

September 6, 2019 Report received of a loose steering gear. Investigation opened
September 9, 2019 Customer visit to review vehicle. Parts collected for laboratory analysis
September 10, 2019 Review of production processes
September 12, 2019 Weekly meetings established to review progress/ findings
September 19, 2019 Preliminary findings (#of reports, torque record review, etc.) discussed
October 10, 2019 Third party analysis report received that identifies casting surface anomalies
October 16, 2019 Product Safety Committee meeting called
October 17, 2019 Volvo Product Safety Committee determines a safety-related defect exists.
October 23, 2019 Volvo submits defect report to NHTSA and informs that a voluntary safety recall will be released to address the potential issue.

Description of Remedy :

Description of Remedy Program : Pre-notification repairs will be addressed according to Volvo's processes associated with reimbursement for repairs made prior to the recall repairs being made available.

The affected vehicles will be inspected and repaired if required. The program may require a two step recall. First step would be an inspection, and re-torque to a higher value. Under the first step, loose gears that are found will be documented in the recall claim including the casting number and the gear serial number. This may be the final solution. Second step, if required, may require resplasing certain steering gears if needed. Testing is being performed to evaluate whether torquing to the higher value will sustain the clamp load on gears with torque retention issues.

How Remedy Component Differs Testing is being performed to determine whether torquing at higher

from Recalled Component : values will stay tight even with the casting anomalies. The part number of the steering gear in question is 22803500.

Identify How/When Recall Condition was Corrected in Production : On October 17, 2019, Steering Gears were inspected and any suspect gears was removed for further analysis. Inspection was made by Sheppard.

Recall Schedule :

Description of Recall Schedule : Dealers will be notified by a recall alert on October 25, 2019. Owner letters will be mailed by November 15, 2019.

Planned Dealer Notification Date : OCT 25, 2019 - OCT 25, 2019

Planned Owner Notification Date : NOV 15, 2019 - NOV 15, 2019

* NR - Not Reported