#### OMB Control No.: 2127-0004

■ Not sequential

# Part 573 Safety Recall Report

## 19V-814

**Manufacturer Name:** General Motors LLC

**Submission Date:** NOV 27, 2019 NHTSA Recall No.: 19V-814 Manufacturer Recall No.: N192270600



#### **Manufacturer Information:**

Manufacturer Name: General Motors LLC

Address: 29427 Louis Chevrolet Road

MAIL CODE 480-210-2V WARREN MI

48093

Company phone: 586-596-1733

### **Population:**

Number of potentially involved: 556,399 Estimated percentage with defect: 1 %

### **Vehicle Information:**

Vehicle 1: 2019-2020 Chevrolet Silverado 1500

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: Manufacturing records were used to identify the affected vehicles. Affected vehicles

are those built with carpet floor covering (RPO B30) and prior to the correction being implemented in production. The corrections were implemented at different times depending on the plant: October 1, 2019 for Silao plant; October 28, 2019 for Fort Wayne plant. Vehicles built with vinyl floor covering (RPO BG9) are not included. In addition, not all 2019 model-year vehicles are impacted; 2019 models from the previous generation truck platform (i.e., those not marketed as "All-New") are not

included in this recall.

There are 355,878 Chevrolet Silverado 1500 vehicles involved in this recall.

Production Dates: MAR 02, 2018 - OCT 28, 2019

VIN Range 1: Begin: End: NR

Vehicle 2: 2020-2020 Chevrolet Silverado 2500/3500

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: Manufacturing records were used to identify the affected vehicles. Affected vehicles

are those built with carpet floor covering (RPO B30) and prior to the correction being implemented in production on October 31, 2019. Vehicles built with vinyl floor

covering (RPO BG9) are not included.

There are 31,423 Chevrolet Silverado 2500/3500 vehicles involved in this recall.

Production Dates: JAN 18, 2019 - OCT 31, 2019

VIN Range 1 : Begin : ☐ Not sequential NR End: NR

Vehicle 3:	2019-2020 GM	C Sierra 150	0		
Vehicle Type :					
Body Style :					
Power Train :	NR				
Descriptive Information :	Manufacturing records were used to identify the affected vehicles. Affected vehicles are those built with carpet floor covering (RPO B30) and prior to the correction being implemented in production. The corrections were implemented at different times depending on the plant: October 1, 2019 for Silao plant; October 28, 2019 for Fort Wayne plant. Vehicles built with vinyl floor covering (RPO BG9) are not included. In addition, not all 2019 model-year vehicles are impacted; 2019 models from the previous generation truck platform (i.e., those marketed as "Limited") are not included in this recall.				
	There are 151,	427 GMC Sie	rra 1500 vehicles	involved in this recall.	
<b>Production Dates:</b>	MAR 02, 2018	-OCT 28, 20	19		
VIN Range 1:	Begin :	NR	End: NR		] Not sequential
Vehicle Type :     Body Style :     Power Train : Descriptive Information :	NR  Manufacturing records were used to identify the affected vehicles. Affected vehicles are those built with carpet floor covering (RPO B30) and prior to the correction being implemented in production on October 31, 2019. Vehicles built with vinyl floor covering (RPO BG9) are not included.  There are 17,671 GMC Sierra 2500/3500 vehicles involved in this recall.				
Production Dates: JAN 18, 2019 - OCT 31, 2019					
VIN Range 1:	Begin :	NR	End: NR		] Not sequential
	<u> </u>		<u> </u>		

#### **Description of Defect:**

Description of the Defect: General Motors has decided that a defect which relates to motor vehicle safety

exists in certain 2019 – 2020 model-year Chevrolet Silverado and GMC Sierra 1500 vehicles and in certain 2020 model-year Chevrolet Silverado and GMC Sierra 2500/3500 vehicles built with carpet floor covering (RPO B30). In certain crashes that cause the front seatbelt pretensioners to deploy, the exhaust from the deployed pretensioner may be diverted through an opening in the pretensioner bracket and ignite cotton fibers in the carpet floor near the

B-pillar.

FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk: Following a crash that causes the seatbelt pretensioner to deploy, a fire may

develop in the area near the B-pillar, which may increase the risk of injury.

Description of the Cause: There is a small opening in the pretensioner bracket that can allow gasses

expelled from a pretensioner during deployment to come into contact with cotton material in the carpet floor. This opening was intended as a locator hole

for assembly but was never utilized. It was not a part of the pretensioner

system performance design.

Identification of Any Warning Following a crash that causes the seatbelt pretensioners to deploy, smoke or a

that can Occur: burning odor from the area at the base of the B-pillar may be noticeable before

a fire propagates sufficiently to be visible.

#### **Involved Components:**

Component Name 1: NR

Component Description: NR

Component Part Number: NR

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: ZF

Address: 12001 Tech Center Drive,

Livonia MICHIGAN 48150

**Country: United States** 

#### **Chronology:**

On July 25, 2019, GM was notified that a vehicle experienced a fire potentially originating in the area around a front seatbelt pretensioner following deployment of the pretensioner. On July 30, 2019, GM reviewed the case with internal fire experts and determined that the issue could be related to a previous fire case involving the subject vehicles. GM reported the issue as a potential safety issue through GM's Speak Up For Safety program and requested that the vehicle be sent to GM's technical center for further analysis. On September 3, 2019, GM opened a product investigation. Between September 3 and September 24, GM received the vehicle involved in the second fire incident and completed its initial review.

Parts from this review and additional parts obtained on September 30, 2019 were given to the supplier for further analysis. A review of field data including warranty, TREAD, and VOQs was completed on October 9 and confirmed that there were no accidents or injuries related to this condition. On October 16, GM's investigator

met with internal fire experts and the supplier to review the results of the component analysis. Component analysis confirmed that both pretensioners had deployed and appeared to function normally. The analysis also showed that fire damage to the components and to the vehicle was consistent with the theory that carpet fibers may have been ignited by the driver-side pretensioner exhaust. Further analysis indicated that an opening in the pretensioner bracket may, in the event of a pretensioner deployment, allow hot gas to vent through the opening and ignite cotton fibers in the carpet.

The results of the investigation were reviewed by GM's Open Investigation Review board on November 4, 2019. On November 7, 2019, GM's Safety and Field Action Decision Authority decided to conduct a safety recall.

#### **Description of Remedy:**

Description of Remedy Program: Dealers will install a feature that will close off the opening in the

pretensioner bracket so that exhaust gasses vent away from carpet material as designed. Pursuant to 577.11, GM will provide reimbursement

to owners for repairs according to the plan submitted on May 19, 2019.

from Recalled Component: into carpet material.

How Remedy Component Differs Countermeasures prevent pretensioner exhaust from expelling directly

Recalled Component Name: TENSIONER KIT, F/SEAT BELT ANC PLT

Recalled Component Description: Seatbelt Lap Pretensioner

Recalled Component Part Number: 84512894, 84512895, 84512897,

84512898, 84603135, 84603136, 84603138, 84603139

Recalled Component Country of Origin: Mexico

Identify How/When Recall Condition In October 2019, GM's assembly plants began installing seatbelt lap was Corrected in Production: pretensioners that have a feature that prevents the pretensioner exhaust from contacting the carpet. This was implemented at GM's Silao assembly plant on October 1, 2019, at GM's Ft. Wayne plant on October 28, 2019,

and at GM's Flint plant on October 31, 2019.

#### **Recall Schedule:**

Description of Recall Schedule: Dealers will be notified on November 14, 2019. General Motors plans to

start mailing owner notification letters on December 12, 2019.

Planned Dealer Notification Date: NOV 14, 2019 - NOV 14, 2019 Planned Owner Notification Date: DEC 12, 2019 - DEC 27, 2019

\* NR - Not Reported