

# Part 573 Safety Recall Report

# 19V-901

**Manufacturer Name :** MORryde International, Inc.**Submission Date :** DEC 18, 2019**NHTSA Recall No. :** 19V-901**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : MORryde International, Inc.

Address : 1966 Sterling Avenue  
Elkhart IN 46516

Company phone : (574) 293-1581

**Population :**

Number of potentially involved : 219

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2020-2020 Forest River Georgetown &amp; FR3

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

**Descriptive Information :** The basis for the recall population is still being determined. The recall encompasses all units that had the hitch installed by MORryde during the recall time period. The number of affected units is still being determined.

Production Dates : AUG 09, 2019 - NOV 22, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

**Description of the Defect :** The hitch is attached to the chassis using 6 bolts that are recommended to be torqued to 80 ft/lb. Some of the bolts are not torqued to the recommended ft/lb.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Loose hitch bolts could cause the hitch to come unfastened from the chassis if the RV owner is using the hitch to tow a vehicle or trailer.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :**

**Component Manufacturer**

Name : NR  
Address : NR  
NR  
Country : NR

**Chronology :**

On 11/21/19, a MORryde inspector noticed that the bolts securing the hitch to the chassis were not torqued to the recommended ft/lb. After inspection of the completed units on site at MORryde and inspection of the units on site at Forest River, it was found that the impact wrench being used was faulty and was not torqueing to the recommended 80 ft/lb. The faulty equipment was changed out on 11/25/19 before production started.

**Description of Remedy :**

Description of Remedy Program :	Re-torque all 6 bolts connected the hitch to the chassis to the recommended 80 ft/lb.
How Remedy Component Differs from Recalled Component :	No difference in part number, name or description. The remedied hitch bolts are torqued to the recommended ft/lb
Identify How/When Recall Condition was Corrected in Production :	On 11/22/19 all production was corrected on campus with a torque wrench as the impact wrenches were still under torqueing hitches. On 11/25/19, the impact wrenches were replaced.

**Recall Schedule :**

Description of Recall Schedule :	Notified Forest River of safety recall on 12/9/2019
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

\* NR - Not Reported