OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-135

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date: MAR 06, 2020 NHTSA Recall No.: 20V-135 Manufacturer Recall No.: 47P8



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc. Address: 3800 Hamlin Road

Auburn Hills MI 48326

Company phone: 1-800-893-5298

Population:

Number of potentially involved: 732 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2019-2019 Volkswagen Arteon

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: Vehicles affected by this recall were manufactured during a certain time peroid with

an potentially incorrectly installed electronic brake booster input rod. Vehicles outside the scope of this recall were manufactured with a correctly installed

electronic brake booster input rod.

Arteon vehicle count: 732

Production Dates: MAY 16, 2019 - JUL 04, 2019

VIN Range 1: Begin: WVWTR7AN8KE025482 End: WVWAR7AN3KE031522 ✓ Not sequential

Description of Defect:

Description of the Defect: Due to a possible manufacturing error, the electronic brake booster pressure

input rod may not be correctly attached to the brake pedal. This may lead to a reduced pedal ratio and to a increased actuating force or to a disconnection of the pressure input rod. Additionally, in the event of a failure of the 12V power supply, the brake performance may be impaired due to the reduced pedal ratio

and the resulting increased actuation force.

FMVSS 1: 135 - Light vehicle brake systems

FMVSS 2: NR

Description of the Safety Risk: An increased actuating force or a disconnected input rod may lead to

abnormal brake behavior and may increase the risk for a crash.

Description of the Cause: Incorrectly installed pressure input rod.

Identification of Any Warning NONE that can Occur:

Supplier Identification:

Component Manufacturer

Name: Volkswagen AG

Address: NR

Wolfsburg FOREIGN STATES

Country: Germany

Chronology:

02/25/2019: One pre-series vehicle with not OK brake pedal performance identified at internal testing, Quality analysis started.

06/18/2019: A second vehicle with not OK brake pedal performance identified during internal testing, more in depth analysis started, internal analysis tests initiated.

07/04/2019: Immediate measures in production implemented to avoid incorrect installation of brake booster pressure rod.

July 2019 - November 2019: Further analyis conducted in order to identify scope, root cause and consequence of this issue.

11/28/2019: The topic was presented in the Volkswagen AG Pre-Product Safety committee; more detail/analysis was requested.

02/05/2020: The topic was presented in the Volkswagen AG Product Safety committee; further details were requested.

02/28/2020: The topic was presented in the Volkswagen AG Product Safety committee and the decision to conduct a recall was made.

Description of Remedy:

Description of Remedy Program: At no cost to customers, dealers will inspect and, if necessary, replace the

electronic brake booster and mounting of the pressure rod OR the mounting of the pressure rod only, depending of the inspection results. Volkswagen will not offer a reimbursement plan under this recall.

Volkswagen will not offer a reimbursement plan under this recall.

How Remedy Component Differs The remedy part number for the electronic brake booster is: 3Q1.614.105. from Recalled Component: AM (recalled part number 3Q1.614.105.AJ)

The remedy part number for the mounting of the pressure rod is:

500.721.165.C

The remedy part will be correctly installed.

Identify How/When Recall Condition 07/04/2019: immediate measures in production were implemented to was Corrected in Production: avoid incorrect installation of brake booster pressure rod.

Recall Schedule:

Description of Recall Schedule: Dealers and owners - on or before May 05, 2020

Planned Dealer Notification Date : MAY 05, 2020 - MAY 05, 2020 Planned Owner Notification Date : MAY 05, 2020 - MAY 05, 2020

* NR - Not Reported