

Part 573 Safety Recall Report

20V-171

Manufacturer Name : Newmar Corporation**Submission Date :** MAR 20, 2020**NHTSA Recall No. :** 20V-171**Manufacturer Recall No. :** #20V-127**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 129

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2020 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary. Newmar Essex 2019-2020 Total= 9

Production Dates : OCT 03, 2018 - MAY 22, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2019-2020 Newmar London Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary. Newmar London Aire 2019-2020 Total=26

Production Dates : OCT 03, 2018 - MAY 22, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2019-2019 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary. Newmar Mountain Aire 2019 Total=12

Production Dates : OCT 03, 2018 - MAY 22, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2019-2019 Newmar Ventana LE

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary. Newmar Ventana LE 2019 Total=36

Production Dates : OCT 03, 2018 - MAY 22, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2019-2019 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary. Newmar Ventana 2019 Total=45

Production Dates : OCT 03, 2018 - MAY 22, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 6 : 2020-2020 Newmar Kountry Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary. Newmar Kountry Star 2020
Total=1

Production Dates : OCT 03, 2018 - MAY 22, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On Tuesday, March 17, 2020 Daimler Trucks North America LLC notified Newmar of a potential defect on

Freightliner Chassis. Today, March 20, 2020 Newmar is giving notice to NHTSA.

Description of Remedy :

Description of Remedy Program : Daimler Trucks North America authorized service facilities will inspect and repair as necessary.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 05/19/2020, customer & dealer letters will begin to mail out.

Planned Dealer Notification Date : MAY 19, 2020 - MAY 19, 2020

Planned Owner Notification Date : MAY 19, 2020 - MAY 19, 2020

* NR - Not Reported