

TECHNICAL INSTRUCTIONS

FOR

SAFETY RECALL 20TA10

HYBRID SYSTEM SOFTWARE UPDATE

CERTAIN 2013 - 2015 PRIUS


Prius V Technical Instructions are in a separate document

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently hold at least one of the following certification levels:

- Expert Technician (Hybrid)
- Master Technician
- Master Diagnostic Technician

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

1. CHECK VEHICLE FOR CAMPAIGN ELIGIBILITY

- Compare the vehicles VIN to the VIN listed on the Repair Order to ensure they match.
- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Campaign, and that it has not already been completed.

Note: TMNA warranty will not reimburse dealers for repairs completed on vehicles that are not affected or were previously completed, even by another dealer.

III. PREPARATION

1. PARTS

Part Number	Part Description	Quantity
00451-00001-LBL*	Authorized Modification Label	1


*Labels can be ordered in packs of 25 from the MDC through the Dealer Daily Website

2. TOOLS, SUPPLIES & EQUIPMENT

- Standard Hand Tools
- Techstream 2.0 / Techstream Lite with software version 13.30 or greater installed
- GR8 Battery Diagnostic Station
- T-SB-0134-16

SST – These Special Service Tools required for this repair:

Part Number	Tool Name	Quantity
09891-47020	Inverter Case Separator	1
Campaign tool	Joint Fuse removal tool	1



The fuse removal tools were shipped to the dealers for a previous campaign.

IV. BACKGROUND

The involved vehicles were designed to enter a failsafe driving mode in response to certain hybrid system faults. Toyota has found that in rare situations, the vehicle may not enter a fail-safe driving mode as intended. If this occurs, the vehicle could lose power and stall. While power steering and braking would remain operational, a vehicle stall while driving at higher speeds could increase the risk of a crash.

V. INSPECT INVERTER CONDITION

1. Verify Techstream Configuration

- From the menu at the top of the screen, select: Setup / Techstream Configuration.
- Continue to the third setup screen: Required Information.
- Verify that "US Dealer 1" is selected as the User Type.

Please input the following information.

Required Information

This Information is used for error report follow up.

Dealer Name

Dealer Code

Dealer Phone

Dealer Country /Region

This selection is used to configure Techstream network settings.

User Type

Example:
TOYOTA/LEXUS/SCION Dealers in the U.S. for one.tis.toyota.com upgrade




2. PERFORM HEALTH CHECK

- Using a Techstream, perform a Health Check.



If any hybrid DTC's are found that indicate a safety risk at performing this repair, do not proceed until they have been resolved.

Note: This Safety Recall covers only the specified ECU updates and Inverter repairs, as detailed in these instructions. It does not cover the diagnosis or replacement of any other parts on the vehicle, including the hybrid system.



VI. REPAIR INVERTER ASSEMBLY

Note: Repairing the inverter is required only if DTC's P0A94, P324E, P3004 or P0A1A are present. If these DTC's are not present, skip to section VII. Inspect for Prius V Inverter on page 7.

1. DETERMINE REPAIR COMPONENTS BASED ON DTC DETAIL CODE

- If multiple DTCs are present, save the freeze frame data.
- After saving the freeze frame data, clear codes and confirm what DTCs reset.
- If multiple codes return, follow the repair manual diagnosis procedure for the DTC with Freeze Frame Data Occurrence Order value of "1".
- Use the correct table on the following pages to identify the parts required for repair, the correct parts are listed in the bottom row of each table.

DTC	DTC DETAIL CODE	• IPM	• MG-ECU	• MG-ECU • IPM	• MG-ECU • CURRENT SENSOR • IPM	• INVERTER ASSY
P0A94	127			X		
	172	X				
	442			X		
	547		X			
	548				X	
	549		X			
	550			X		
	553	X				
	554		X			
	555				X	
	556		X			
	557	X				
	564			X		
	585			X		
	587			X		
589			X			
590			X			
P324E	788				X	
P0A1A	151				X	
	155		X			
	156		X			
	166		X			
	200		X			
	658		X			
	659		X			
	791		X			
	792		X			
793		X				
P3004	131					X
	132					X
	800	X				
	801	X				
PARTS & QUANTIT Y (QTY)		04899-47021 (1) 08887-02809 (2) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1)	G920H-47150 (1) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1)	04899-47021 (1) 08887-02809 (2) G920H-47150 (1) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1)	04899-47021 (1) 08887-02809 (2) G920H-47150 (1) G920J-52010 (1) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1)	ORDER INVERTER BY VIN



Thermal grease for IPM replacement is NOT interchangeable. Only grease specified for the Prius inverter can be used. Grease for the Highlander IPM replacement will result in inverter failure if used.

2. TO REPAIR THE INVERTER, CLICK ON THE RELEVANT LINK BELOW:

[2013 Prius: Intelligent Power Module Transistor Removal](#)

[2014 Prius: Intelligent Power Module Transistor Removal](#)

[2015 Prius: Intelligent Power Module Transistor Removal](#)

3. ONCE THE INVERTER REPAIR IS COMPLETED, CONTINUE TO THE NEXT SECTION.

VII. INSPECT FOR PRIUS V INVERTER

1. INSPECTION OF HYBRID CONTROL CID'S #3 & #4

- Identify the Hybrid Control CID #3 & #4 from the Stored Data tab.
- Determine if the last digit of CID #3 & #4 is a "0" or a "1".

For example: CID 89884470820⁰, has the last digit of "0".

CID 89884470820¹, has the last digit of "1".

Note: The actual CID's will vary, and may not be the same CID as the example.

Techstream (Ver 13.00.022) - 11433

File Function Settings User Help

System Selection **Stored Data**

2014 Prius
2ZR.FXE

Tire Pressure / Threshold Value [psi(gau)]

Sensor 1: 30.1 / 27.5 Sensor 2:
Sensor 3: 29.7 / 28.3 Sensor 4:
Sensor 5: N/A / N/A

Health Check Results

- Health Check does not display live data.
- Changes in vehicle condition will not update au
- To update Health Check, click the Refresh butto


Enhanced | Generic |

System	RoB	Calibration	Update
Engine and ECI	-	34754000	No
		A4701000	No
		896B34747100	Yes
		896B57602000	No
Hybrid Control	-	898844708200	No
		898844709200	No
Cruise Control	-	-	-
Tire Pressure Monitor	-	-	-
ABS/SC/TRAC	-	F152647216	No
EMPS	-	JCU315F0	No
Transmission Control	-	-	-

Campaign Status: Y
PERMANENT: NO

Sort
Expand>>
TIS Search
Print
Back

3309-06 | Default User | DLC 3



2. CID's ENDING IN "1"

It may be necessary to determine if a Prius has been incorrectly repaired with a Prius V inverter or Motor Generator (MG) ECU in the past. This condition may be identified by reviewing the Hybrid Control System CIDs #3 & #4. If the #3 and #4 CIDs end in a "1" instead of a "0", this may indicate that Prius V components were installed in a Prius vehicle.

This mismatch of CID's will create an error message when performing 20TA10 and will prevent its completion. To address this situation, the vehicle must be repaired using parts that are correct for a Prius.

If the vehicle requires replacement of the Inverter or MG ECU because Prius V parts are installed, it will be necessary to contact Quality Compliance for direction.

Please check Toyota National Service History (NSH) to determine if the Prius V inverter or MG ECU was installed at a Toyota dealership. The following part numbers would confirm the issue:

- G9200-49056 Prius V Inverter Assembly
- G920H-47040 Prius V Motor Generator ECU

Email Quality Compliance with the following information to determine the repair direction:

Email address: quality_compliance@toyota.com

Email subject: 20TA10 Inverter/MG ECU Request

Email contents:

- VIN #
- Screenshot of Hybrid Control CID's
- RO# and date of previous Inverter or MG ECU replacement in NSH (if found).
- Part number of Inverter or MG ECU replacement in NSH (if found).
- Technicians Name and contact number.


VIII. DETERMINE CID STATUS

1. DETERMINE STATUS of HYBRID CONTROL SYSTEM CID's

- Locate the Update column for the Hybrid Control System in the Stored Data tab.
- Determine the status of the **CID #1** for the Hybrid Control ECU; indicated by a **YES** or **NO** in the Update column.

The screenshot shows the Techstream interface for a 2014 Prius. The 'Stored Data' tab is selected. The 'Hybrid Control' system is highlighted in the left sidebar. A table in the main window shows update status for various ECUs. The 'Update' column for CID #1 (896B34747100) is circled in red and labeled 'Status of available Update'. The CID #1 is also labeled with a red arrow.

System	RoB	Calibration	Update
Engine and ECT	-	34754000	No
	-	A4701000	No
	-	896B34747100	Yes
	-	896B57602000	No
	-	898844708200	No
	-	898844709200	No
	-	-	-
	-	F152647216	No
	-	JCU315F0	No
	-	-	-



If the Update Column listed “No” in the location specified above, no further action is necessary. The campaign is now completed. The vehicle can be returned to the customer.

IX. VEHICLE PREPARATION

The ECU reprogramming procedure is detailed in [T-SB-0134-16](#). Reference this Bulletin for additional detailed procedures and information.

3. VEHICLE BASICS

a. Confirm the following conditions:

- Vehicle in the IG position (engine off).
- Transaxle in Park.
- Parking brake engaged.
- Turn off all electrical accessories (i.e. Headlights, wipers, climate control, audio system, etc.)

4. CONNECT THE 12v BATTERY TO A POWER SUPPLY

- a. Connect the DCA-800, GR8 or other type of a power supply (not a battery charger) to the 12v battery.
- b. Activate the Power Supply Mode.



A power supply *MUST* be used during reprogramming. ECU damage will occur if the battery voltage is not properly maintained during this re-flash procedure.

Note: A power supply must be connected directly to the 12v battery terminals and NOT the remote jump posts under the hood (if equipped).

5. VERIFY TECHSTREAM SETUP

a. Verify that the Techstream meets the following conditions:

- Current version of software is installed (reference TIS for latest software version).
- The Techstream battery is fully charged. If not, connect the Techstream to a 120v source.
- The DLCIII cable is in good condition.




The Techstream battery must be maintained during the update procedure. If necessary, plug the Techstream into a 120v outlet to ensure that a failure does not occur.

Note: If the Techstream communication with the vehicle fails during the re-flash procedure, the ECU will be damaged and must be replaced.

6. MAINTAIN BRAKE SYSTEM PRESSURE

a. Depress the brake pedal fully 2 times within 2 seconds.

Note: You may hear the hydro-boost pump run for a few seconds when completing these steps. This procedure will prevent the pump from running during the calibration update procedure.




7. REMOVE JOINT FUSE FROM ENGINE ROOM FUSE BOX
 - a. Confirm the joint fuse orientation before removal because the fuse can be installed in either direction.
 - b. Using the fuse puller remove the joint fuse that encases the CDS (30A), RDI (30A) and HTR (50A).

Permanent damage to the ECU's can happen if these fuses are not removed.


Removing these fuses will stop the vehicle from performing onboard diagnostic tests during the update, which could cause the update to fail and damage the ECU.

X. CUWC APPLICATION

1. INSTALL CUWC FILE INSTALLER (Only required once for each Techstream)
 - a. In TIS, select the following:
 - TIS / Diagnostics / Reprogramming




- b. On the right side of the screen, select the following from the Reference Documents:
 - CUWC Reprogramming Installer
 - Follow the on-screen instructions to complete the installation.



Note: The installation of the CUWC Reprogramming Installer will only need to be completed one time for each Techstream.

(cont. on next page)

	<p><u>Permanent damage to the ECU's will occur if the following actions are attempted during the CID update procedure:</u></p> <ul style="list-style-type: none">• Attempt to close the CUWC installer• Attempt to close the Calibration Wizard• Turning off the vehicle's ignition• Turning off the Techstream Unit• Unplugging the Techstream from the vehicle while programming is in process
---	---

The following message will appear when the CUWC installation application is running. This image cannot be closed manually. **When the installation of all necessary CID's is complete, the image will close.**

Message displayed during CID update process:

**CUWC is starting...
Lancement de CUWC...
CUWC esta iniciando...**

 **<Caution>**

- Do not operate Techstream
- When the CUWC application or PC Stop unexpectedly, please recover ECU from CUW application.

<Attention>

- Ne pas utiliser Techstream.
- Lorsque l' application CUWC ou le PC s' arrete inopinement, veuillez restaurer l' ECU depuis l' application CUWC.

<Cuidado>

- No opere Techstream.
- Si la aplicacion CUWC o la PC se detienen inesperadamente, por favor recupere ECU de la aplicacion CUW.

XI. CID INSTALLATION

1. INSTALLATION OF CID'S

Note: Since there are multiple CID groups available, it will be necessary to identify the correct group by referencing CID's #3 & #4.

- Identify the Hybrid Control CID #3 & #4 from the Stored Data tab.
- Referencing the correct model year in the chart's below, identify the chart that has the correct CID #3 & #4.
- Select the Group # link (blue text) to begin the update process.
- Follow the instruction on the screen to complete the installation.

Techstream (Ver 13.00.022) - 11433

File Function Settings TIS User Help

System Selection **Stored Data**

2014 Prius
2ZR-FXE

Tire Pressure / Threshold Value [psi/gauge]

Sensor 1: 30.1 / 27.5 Sensor 2:
Sensor 3: 29.7 / 28.3 Sensor 4:
Sensor 5: N/A / N/A

Health Check Results

- Health Check does not display live data.
- Changes in vehicle condition will not update automatically.
- To update Health Check, click the Refresh button.

Enhanced | Generic |

System	RoB	Calibration	Update
Engine and ECT	-	34754000	No
		A4701000	No
		896B34747100	Yes
		896B57602000	No
Hybrid Control	-	898844708200	No
		898844709200	No
Cruise Control	-	-	-
Tire Pressure Monitor	-	-	-
ABS/VSC/TRAC	-	F152647216	No
EMPS	-	JCU315F0	No
Transmission Control	-	-	-

Campaign Status: Y
PERMANENT: NO

Sort
Expand>>
TIS Search
Print
Back

DTC
KMC
Refresh

6309-06 Default User DLC 3

CID #3 & #4

Year	CID#	Original	Current
2013 Prius	CID #1	896B34736000	<u>2013 Prius #1</u> CID #1: 896B34736400 CID #2: 896B57602000 CID #3: 898844701400 CID #4: 898844702300
		896B34736100	
		896B34736200	
		896B34736300	
2013 Prius	CID #2	896B57602000	
		89884470 1200	
		89884470 1300	
		89884470 1400	
2013 Prius	CID #3	89884470 2100	
		89884470 2200	
		89884470 2300	
		89884470 2300	

2013 Prius	CID #1	896B34736000	<u>2013 Prius #2</u> CID #1: 896B34736400 CID #2: 896B57602000 CID #3: 898844708200 CID #4: 898844709200
		896B34736100	
		896B34736200	
		896B34736300	
2013 Prius	CID #2	896B57602000	
		89884470 8000	
		89884470 8100	
		89884470 8200	
2013 Prius	CID #3	89884470 9000	
		89884470 9100	
		89884470 9200	
		89884470 9200	

Prius V Technical Instructions are in a separate document


(cont. on next page)

Year	CID#	Original	Current
2014 - 2015 Prius	CID #1	896B34747000	<u>2014-2015 Prius #1</u> CID #1: 896B34747300 CID #2: 896B57602000 CID #3: 898844701400 CID #4: 898844702300
		896B34747100	
	896B34747200		
	CID #2	896B57602000	
CID #3	89884470 1200	89884470 1300	
	89884470 1400		
CID #4	89884470 2100	89884470 2200	
	89884470 2300		

2014 - 2015 Prius	CID #1	896B34747000	<u>2014-2015 Prius #2</u> CID #1: 896B34747300 CID #2: 896B57602000 CID #3: 898844708200 CID #4: 898844709200
		896B34747100	
	896B34747200		
	CID #2	896B57602000	
CID #3	89884470 8000	89884470 8100	
	89884470 8200		
CID #4	89884470 9000	89884470 9100	
	89884470 9200		

Prius V Technical Instructions are in a separate document

XII. COMPLETE UPDATE



1. **REINSTALL JOINT FUSE INTO ENGINE ROOM FUSE BOX**
 - a. Confirm the joint fuse orientation before reinstalling because the joint fuse can be installed in either direction.
 - b. Reinstall the joint fuse that encases the CDS (30A), RDI (30A) and HTR (50A).



BE SURE TO ORIENT THE FUSE AS SHOWN ON THE FUSE BLOCK COVER.



2. PERFORM VERIFICATION HEALTH CHECK

- a. Using a Techstream, perform a Health Check.
- c. Clear DTC's that may have set during the re-flash procedure.
- d. **Re-run the Health Check to confirm that no DTC's reappear.**



THIS VERIFICATION HEALTH CHECK IS NECESSARY to update the results and CID's to the National database.

3. CONFIRM CID UPDATE

- a. On the Stored Data tab, confirm the following for the Hybrid Control System:
 - The Update column lists "No" for CID #1

Techstream (Ver 13.00.022) - 11433

File Function Setup TIS User Help

System Select **Stored Data**

2014 Prius
2ZR-FXE

Tire Pressure / Threshold Value [psi(gau

Sensor 1: 30.1 / 27.5 Sensor 2:
Sensor 3: 29.7 / 28.3 Sensor 4:
Sensor 5: N/A / N/A

Campaign Status: N
PERMANENT: NO

Health Check Results

- Health Check does not display live data.
- Changes in vehicle condition will not update au
- To update Health Check, click the Refresh butto

Enhanced | Generic |

System	RoB	Calibration	Update
Engine and ECT	-	34754000	No
	-	A4701000	No
	-	896B34747100	No
	-	896B57602000	No
	-	898844708200	No
Cruise Control	-	-	-
	-	-	-
	-	-	-
Tire Pressure Monitor	-	-	-
ABS/VSC/TRAC	-	F152647216	No
EMPS	-	JCU315F0	No
Transmission Control	-	-	-

Sort
Expand>>
TIS Search
Print
Back

S309-06 | Default User | DLC 3

CID #1 (points to 896B34747100)


MUST say "NO" (points to the 'No' in the Update column for CID #1)




It is recommended to have this step verified by someone other than the individual who performed the update.

4. PRINT CUSTOMER HEALTH CHECK REPORT


- a. From the Stored Data tab, select the Customer Health Check Report button (TIS will launch when button is pressed).



- b. Log in to TIS.
- c. Input Vehicle Mileage and Repair Order number.
- d. Check the "Performed" campaign button for campaign 20TA08.
- e. Select the Report button.




- f. Confirm Customer Health Check Report information is correct.



- g. Print Customer Health Check Report from TIS.
- h. Sign and provide to the customer.

5. ATTACH THE AUTHORIZED VEHICLE MODIFICATION LABEL

- a. Fill out the label.
- b. Affix the label to the under-side of the hood.



1	Hybrid Control System
2	(Calibration ID's)
3	(Dealer Code)
4	(Date Completed)
5	Safety Recall 20TA10

Calibration ID's listed for the Hybrid Control System after completing the final Health Check. The CID's will vary for car to car.

Hybrid Control	896B34747100
	896B57602000
	898844708200
	898844709200

◀ VERIFY REPAIR QUALITY ▶

- Confirm all ECM Calibration has been updated successfully to the NEW CID's.
- Confirm that the Authorized Modification Label has been installed.

If you have any questions regarding this Safety Recall, please contact your regional representative

XIII. APPENDIX

A. PARTS DISPOSAL

As required by Federal Regulations, please make sure all recalled parts (original parts) removed from the vehicle are disposed of in a manner in which they will not be reused, ***unless requested for parts recovery return.***

B. CAMPAIGN DESIGNATION DECORDER

