#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 20V-394

**Manufacturer Name:** Daimler Coaches North America

**Submission Date:** JUL 03, 2020 NHTSA Recall No.: 20V-394

**Manufacturer Recall No.:** 75.00U20104A



#### **Manufacturer Information:**

Manufacturer Name: Daimler Coaches North America

Address: 2477 Deerfield Drive

Fort Mill SC 29715

Company phone: 800-206-9728

## **Population:**

Number of potentially involved : 55 Estimated percentage with defect : 100%

## **Vehicle Information:**

Vehicle 1: 2018-2019 Setra S407

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: The recall population was based on manufacturing records. The VIN range reflects all

possible vehicles that could potentially experience the problem.

2018 S407 = 6 affected vehicles 2019 S407 = 5 affected vehicles 2019 S417 = 31 affected vehicles 2020 S417 = 13 affected vehicles

Production Dates: FEB 01, 2018 - JAN 31, 2019

Vehicle 2: 2019-2020 Setra S417

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: The recall population was based on manufacturing records. The VIN range reflects all

possible vehicles that could potentially experience the problem.

2018 S407 = 6 affected vehicles 2019 S407 = 5 affected vehicles 2019 S417 = 31 affected vehicles 2020 S417 = 13 affected vehicles

Production Dates: MAY 01, 2019 - JAN 31, 2020

VIN Range 1:Begin: WKKA574H7K3010310 End: WKKA574H1L3010353 Not sequential

## **Description of Defect:**

Description of the Defect: A change to the outer frame of the engine compartment flap required an

additional weld seam on the hinges. In some instances, this additional weld was not applied. The absence of individual welding seams on the hinge compartment flap can reduce the strength and stability. This could lead to a failure of the connections to the hinge, which could overload other hinge connections. If the second hinge connection fails, there is the risk that the

engine compartment flap could become detached from the vehicle.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The engine compartment flap could become detached from the vehicle.

Description of the Cause: A change to the outer frame of the engine compartment flap required an

additional weld seam on the hinges. In some instances, this additional weld

was not applied.

Identification of Any Warning If a close inspection of the engine compartment flap hinges were undertaken,

that can Occur: cracking could be observed but otherwise there is no advance warning.

## **Involved Components:**

Component Name 1: NR

Component Description: NR

Component Part Number: NR

## **Supplier Identification:**

## **Component Manufacturer**

Name: NR

ivaliic. Ivi

Address: NR

NR

Country: NR

#### **Chronology:**

February 10, 2020: Discovery of missing welds on the engine compartment flap hinges during an internal quality check in production.

March to June 2020: Internal analysis to determine the cause of the missing welds. Investigation of possible affected markets and number of units by market.

June 29, 2018 EvoBus GmbH determined a safety defect existed in certain Setra motorcoaches

## **Description of Remedy:**

Description of Remedy Program: Check the welding seams on the hinge mountings of the engine

compartment flap and, if necessary, re-weld or replace the engine

compartment flap.

from Recalled Component:

How Remedy Component Differs The welding scope is completely carried out.

Identify How/When Recall Condition The additional welded seam was reflected in production documentation was Corrected in Production: and added to the production weld inspections and checks in February

2020.

### **Recall Schedule:**

Description of Recall Schedule: The repair procedure and customer notification will be mailed to affected

Setra customers by August 28, 2020.

Planned Dealer Notification Date: AUG 28, 2020 - AUG 28, 2020 Planned Owner Notification Date: AUG 28, 2020 - AUG 28, 2020

\* NR - Not Reported