

Part 573 Safety Recall Report

20V-426

Manufacturer Name : Daimler Vans USA, LLC

Submission Date : JUL 27, 2020

NHTSA Recall No. : 20V-426

Manufacturer Recall No. : VS3LEFSPRI



Manufacturer Information :

Manufacturer Name : Daimler Vans USA, LLC

Address : One Mercedes-Benz Drive
Sandy Springs GA 30328

Company phone : 854-888-3374

Population :

Number of potentially involved : 26

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 FREIGHTLINER SPRINTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : NR

Descriptive Information : Based on the determination of a production error and on the analysis of the production information, the affected population was determined to be Sprinter vehicles (VS30, Platform 907) produced from May 16, 2019 to June 4, 2019. Vehicles outside of the scope of the determined population were delivered with the leaf spring shim as specified.

Production Dates : MAY 16, 2019 - JUN 04, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2019-2019 MERCEDES BENZ SPRINTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : NR

Descriptive Information : Based on the determination of a production error and on the analysis of the production information, the affected population was determined to be Sprinter vehicles (VS30, Platform 907) produced from May 16, 2019 to June 4, 2019. Vehicles outside of the scope of the determined population were delivered with the leaf spring shim as specified.

Production Dates : MAY 16, 2019 - JUN 04, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Noncompliance :

Description of the Noncompliance :	Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain Mercedes-Benz Sprinter vehicles of the platform 907 (VS30), an incorrect leaf spring shim was installed on the left and right sides between the rear axle and the leaf springs.
FMVSS 1 :	126 - Electronic stability control systems
FMVSS 2 :	NR
Description of the Safety Risk :	For the affected vehicles with the incorrect leaf spring shim mounted, it cannot be completely ruled out that there could be negative effects on the driving behavior in highly dynamic driving situations. In a worst-case scenario, this could increase the risk of a crash.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	NR

Involved Components :

Component Name 1 :	LEAF SPRING SHIM
Component Description :	LEAF SPRING SHIM
Component Part Number :	A9073240400

Supplier Identification :

Component Manufacturer

Name :	NR
Address :	NR
	NR
Country :	NR

Chronology :

PLEASE SEE ATTACHED DOCUMENT

Description of Remedy :

Description of Remedy Program : An authorized Mercedes-Benz or Freightliner Sprinter dealer will replace the leaf spring shims on both sides, renew the spring brackets and its screwing, check the rubber buffers for wear, renew them if necessary and then adjust the headlamps to the new zero position.

Pursuant to 49 C.F.R. § 577.11(e), Daimler Vans does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : An authorized Mercedes-Benz or Freightliner Sprinter dealer will replace the leaf spring shims on both the left and right sides, renew the spring brackets and its screwing, check the rubber buffers for wear, replace them if necessary, and then adjust the headlamps to the new zero position.

Identify How/When Recall Condition was Corrected in Production : Upon identification of the issue, the load carrier marking was corrected already in May 2019.

Recall Schedule :

Description of Recall Schedule : N/A

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported