Manufacturer Name :	Forest River, Inc.
Submission Date :	JUN 30, 2021
NHTSA Recall No. :	20V-488
Manufacturer Recall No. :	51-1203

Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Vehicle Information :

Vehicle Type : Body Style : Power Train :	BUSES, MED OTHER NR Per DTNA's I receiving ins From campa	IUM & HEAVY Recall # 20V4 pection only : ign FL-788. Fe	04: Chassis equipped with repairs orest River received affecte	
Due duestieur Desteer		Model Listing		
Production Dates : VIN Range 1 :		NR	End: NR	☐ Not sequential
Vehicle Type : Body Style : Power Train :	LSA38C-340 BUSES, MED OTHER NR Per DTNA's I receiving ins From campa	IUM & HEAVY Recall # 20V4 pection only :	VEHICLES 04: Chassis equipped with repairs orest River received affecte	LSA34A-340,LSA360RB-340, a certain PDM and chassis ed vehicle population from DTNA.
Production Dates :				
VIN Range 1:	Degiii.	NR	End: NR	☐ Not sequential



Number of potentially involved : 1,547 Estimated percentage with defect : 100 %

Population :

20V-488

20V-488

Page 2

	2017-2017	Coachmen Cro	ss Country CCA404RB,CCA	405FK,CCA407FW
Vehicle Type :	BUSES, MED	DIUM & HEAVY	VEHICLES	
Body Style :				
Power Train :	NR			
Descriptive Information :	receiving ins From campa	spection only i	orest River received affecte	a certain PDM and chassis ed vehicle population from DTNA
Production Dates :	APR 29, 201	6 - AUG 04, 20	16	
VIN Range 1:	Begin :	NR	End: NR	☐ Not sequential
Vehicle 4 : Vehicle Type : Body Style :	BE40B-380, BEA37A-380 BEA40C-380 BUSES, MED	, BE40BH-380, 0,BEA38A-360 0,BEA40D-380	,BEA43B-450,BEA43C-450	
Power Train :				
Descriptive Information :	receiving ins From campa	spection only i	orest River received affecte	a certain PDM and chassis ed vehicle population from DTNA
Production Dates :	MAY 27, 201	16 - MAY 09, 20	019	
Production Dates : VIN Range 1 :		16 - MAY 09, 20 NR	End: NR	☐ Not sequential
VIN Range 1:	Begin : 2017-2020 S1A404RB,S S1A409BG-3 BUSES, MED OTHER	NR Coachmen Spo 51A404RB-360 360	End: NR rtscoach S1A339DS,S1A36 9,S1A407FW,S1A407FW-36	☐ Not sequential 0DL,S1A364TS,S1A365RB, 60,S1A408DB,S1A408DB-360,
VIN Range 1 : Vehicle 5 : Vehicle Type : Body Style : Power Train :	Begin : 2017-2020 (S1A404RB,S S1A409BG-3 BUSES, MED OTHER NR Per DTNA's receiving ins From campa	NR Coachmen Spo 51A404RB-360 360 DIUM & HEAVY Recall # 20V4 spection only 1	End: NR rtscoach S1A339DS,S1A36 0,S1A407FW,S1A407FW-36 7 VEHICLES 04: Chassis equipped with repairs orest River received affected	30DL,S1A364TS,S1A365RB, 30,S1A408DB,S1A408DB-360, a certain PDM and chassis
VIN Range 1 : Vehicle 5 : Vehicle Type : Body Style : Power Train :	Begin : 2017-2020 (S1A404RB,S S1A409BG-3 BUSES, MED OTHER NR Per DTNA's receiving ins From campa See attached	NR Coachmen Spo S1A404RB-360 360 DIUM & HEAVY Recall # 20V4 spection only p aign FL-788. Fo d Model Listing	End : NR rtscoach S1A339DS,S1A36 9,S1A407FW,S1A407FW-36 7 VEHICLES 04: Chassis equipped with repairs prest River received affecter 5	60,S1A408DB,S1A408DB-360,

20V-488

Page 3

Description of Defect :

Description of the Defect :	Per DTNA's recall 20V404 - On certain FCCC XB and XC chassis; during manufacturing of the rear mounted Power Distribution Module (PDM), which is a PDM unique to these chassis. The internal circuit board may be inadvertently subject to bending stresses which may, after a period of vehicle use, lead to intermittent open circuits, in which the rear marker, brake lights or left turn signal lights may not function
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Brake lights not working correctly may not notify motorists of a braking event which may lead to an increase crash risk.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	

Involved Components :

Power Distribution Module
NR
A66-05172-000

Component Name 2:	Power Distribution Module
Component Description :	NR
Component Part Number :	A66-05172-001

Component Name 3:	Power Distribution Module
Component Description :	NR
Component Part Number :	A66-05172-002

Component Name 4 :Power Distribution ModuleComponent Description :NR

Component Part Number : A66-05172-004

The information contained in this report was submitted pursuant to 49 CFR \$573

Component Name 5 :	Power Distribution Module
Component Description :	NR
Component Part Number :	A66-05172-005
Component Name 6:	Power Distribution Module
Component Description :	NR
Component Part Number :	A66-05172-006
Component Name 7:	Power Distribution Module
Component Description :	NR
Component Part Number :	A66-05172-008
Component Name 8:	Power Distribution Module
Component Description :	NR
Component Part Number :	A66-05172-009

Component Manufacturer

Name: Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue Portland Oregon 97217-3849

Country: United States

Chronology :

Per DTNA's recall 20V404, June 18, 2020, NHTSA notified DTNA of one vehicle owner questionnaire (VOQ) and two field complaints that may be related to FL-788. DTNA opened an investigation to reevaluate the scope of FL-788. Complaint reviews, study of changes to supplier manufacturing and inspection processes revealed additional vehicles manufactured after the FL-788 population bookend June 29, 2018. Further, the voltage test used for a portion of the recall FL-788 population may not be adequate in identifying a failed PDM. July 7, 2020, DTNA, with an abundance of caution, decided to initiate a voluntary recall to campaign vehicles that received an inspection only remedy and campaign vehicles not initially captured in the original FL-788 population. August 7, 2020, DTNA has removed additional suspect vehicles that received a PDM replacement.

The information contained in this report was submitted pursuant to 49 CFR §573

Page 5

On 7/20/2020, Forest River received a notice of recall from DTNA. The recall is pertaining to a recall filed by DTNA FL-788, Forest Rivers recall was 19V191. This recall did not have a remedy. DTNA now has a remedy. Forest River was able to identify vehicles affected by the recall. ON 8/17/2020, Forest River filed a pass through recall.

Forest River will be notifying owners. DTNA will be providing quarterly reporting.

A1 - On 9.8.2020 after reviewing the scope sent it was found that 1 vehicle was listed under Canada population when it is in fact US population. We also found that 4 US units were shown to be on-site at Forest River when in fact they had been sold. Amending recall to reflect new population. US 1108 Canada 53

A2 – On 12.3.2020 Forest River received additional VINS from DTNA that are affected by this recall On 12.7.2020 Forest Rivers Office of Corporate Compliance filed an amendment - US 1153 Canada 56 – All owners will be notified.

A3 – On 5/28/2021 Forest River's Office of Corporate Compliance received additional VINs from DTNA Vehicle Population increased in the US and Canada.

Description of Remedy :

Description of Remedy Program :	WHAT IS DTNA GOING TO DO Vehicles will receive a new rear Power Distribution Module (PDM). Repairs will be performed by Daimler Trucks North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter. What DTNA's Customer Service Phone Number? (800) 547-0712
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

The information contained in this report was submitted pursuant to 49 CFR §573

20V-488

Planned Dealer Notification Date : JAN 18, 2021 - JAN 18, 2021 Planned Owner Notification Date : JAN 18, 2021 - JAN 18, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573