#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 20V-588

**Manufacturer Name:** General Motors, LLC

**Submission Date:** JAN 27, 2021 **NHTSA Recall No.:** 20V-588 **Manufacturer Recall No.:** A202307260



#### **Manufacturer Information:**

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet Road

MAIL CODE 480-210-2V WARREN MI

48093

Company phone: 586-596-1733

## **Population:**

Number of potentially involved: 3,677 Estimated percentage with defect: 5 %

#### **Vehicle Information:**

Vehicle 1: 2020-2020 Cadillac CT4

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information : Manufacturing records and supplier part trace data were used to identify potentially

affected vehicles.

28 Cadillac CT4 vehicles are included in this recall.

Production Dates: FEB 20, 2020 - MAR 06, 2020

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2020-2020 Cadillac CT5

Vehicle Type : Body Style : Power Train : NR

Descriptive Information : Manufacturing records and supplier part trace data were used to identify potentially

affected vehicles.

58 Cadillac CT5 vehicles are included in this recall.

Production Dates: FEB 20, 2020 - FEB 24, 2020

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3:	2021-2021 Chevrolet Trailblazer			
Vehicle Type :				
Body Style :				
Power Train :	NR			
Descriptive Information :	Manufacturing records and supplier part trace data were used to identify potentially affected vehicles.  1233 Chevrolet Trailblazer vehicles are included in this recall.			
Production Dates :	JAN 22, 2020 - JUN 12, 2020			
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential
Vehicle 4:	2020-2020 Che	vrolet Corvet	te	
Vehicle Type :				
Body Style :				
Power Train :				
Descriptive Information :	Manufacturing records and supplier part trace data were used to identify potentially			
•	affected vehicles.			
	676 Chevrolet Corvette vehicles are included in this recall.			
Production Dates ·	MAR 02, 2020 - JUN 26, 2020			
VIN Range 1:		NR	End: NR	☐ Not sequential
	208			
Vehicle 5:	2020-2021 Bui	ck Encore GX		
Vehicle Type :				
Body Style :				
Power Train :	NR			
Descriptive Information :	Manufacturing records and supplier part trace data were used to identify potentially affected vehicles.			
	Non-GX trimlines of the Buick Encore are not included in this recall.			
	1111 Buick Encore vehicles are included in this recall.			
Production Dates: JAN 30, 2020 - JUN 17, 2020				
VIN Range 1:		NR	End: NR	☐ Not sequential

Vehicle 6: 2020-2020 Cadillac XT4

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: Manufacturing records and supplier part trace data were used to identify potentially

affected vehicles.

571 Cadillac XT4 vehicles are included in this recall.

Production Dates: JAN 17, 2020 - FEB 25, 2020

## **Description of Defect:**

Description of the Defect: General Motors has decided that a defect which relates to motor vehicle safety

exists in certain 2020 model year Cadillac CT4, CT5 and XT4 vehicles, 2020 model year Chevrolet Corvette vehicles, 2020 – 2021 model year Buick Encore GX vehicles, and 2021 model year Chevrolet Trailblazer vehicles. Material used in a sensor connection in the electronic brake boost system in these vehicles may have been contaminated during the material supplier's production process. Contamination of this material may cause an interruption of

communication between the sensor and the brake boost system under certain

conditions.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If communication with the sensor is interrupted, electronic brake boost assist

could be lost. Extra pedal force will be required to slow and stop the vehicle,

increasing the risk of a crash.

Description of the Cause: During a limited production period, the supplier of the affected connector

material failed to perform required cleaning of tooling used to manufacture the

material, potentially introducing contamination.

Identification of Any Warning If electronic brake boost assist is lost, a warning light and message may appear

that can Occur: in the instrument panel and vehicle speed may be limited.

#### **Involved Components:**

Component Name 1: CYLINDER ASM-BRK MAS (W/P/B BOOS&ELEK BRK BOOS CON

Component Description: Electronic Brake Boost Module

Component Part Number: 84774537, 84784557, 84871303, 84722407, 6000426, 60004350

## **Supplier Identification:**

## **Component Manufacturer**

Name: Robert Bosch GmbH

Address: P.O. Box 1355

D-74003 D-74003 Hilbronn Foreign States

Country: Germany

### **Chronology:**

On June 30, 2020, GM opened an investigation into potential loss of brake boost assist in certain 2021 model year Chevrolet Trailblazer vehicles after a review of warranty data for the Korean market revealed several complaints of increased braking effort in those vehicles.

Together with the electronic brake boost system supplier, GM conducted a teardown and material composition analysis of returned warranty parts for these vehicles. The analysis revealed evidence of material contamination in a connector to the system's rotor position sensor (RPS). Testing was undertaken, which demonstrated such contamination could degrade the electrical connection between the RPS and the brake assist system, potentially causing loss of brake assist.

GM and the system supplier reviewed warranty claim data and the connector material supplier's production records. They discovered that, during a three day production window from December 16 to December 18, 2019, the connector material supplier failed to perform required cleaning of tooling used to manufacture the material where contamination was found. GM's investigator completed a read across to determine which vehicles may be affected.

On September 17, 2020, GM's Safety and Field Action Decision Authority decided to conduct a safety recall. GM is not aware of any injuries or accidents related to this condition.

## **Description of Remedy:**

Description of Remedy Program: Dealers will replace the electronic brake boost module.

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under

warranty, so reimbursement is not offered.

How Remedy Component Differs Replacement assemblies were manufactured outside of the supplier

from Recalled Component: production window affected by the contaminated electrical connectors in

the rotor position sensor.

Identify How/When Recall Condition By September 1, 2020, all affected electronic brake boost module was Corrected in Production: assemblies at GM plants had been assembled into vehicles or scrapped.

#### Recall Schedule:

Description of Recall Schedule: Interim customer notification was sent on November 9, 2020. This will

be a phased launch, executed under three GM bulletins, A202307261, A202307262, and A202307263. Owner letter mailings began on

December 9, 2020. The last phase of owner letters are estimated to mail

on February 27, 2021.

Planned Dealer Notification Date : SEP 24, 2020 - SEP 24, 2020 Planned Owner Notification Date : DEC 09, 2020 - FEB 27, 2021

\* NR - Not Reported