

Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



# IMPORTANT SAFETY RECALL

November 2020

This notice applies to your vehicle, **VIN:** \_\_\_\_\_

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2014-2016 model year Chevrolet Caprice Police Pursuit Vehicles (PPVs) and Chevrolet SS vehicles that were subject to NHTSA Recall No. 16V518 and may not have received a complete repair under the recall. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

## IMPORTANT

- Your vehicle is involved in GM safety recall N202312100.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

### Why is your vehicle being recalled?

The flexible steel cable that connects the driver's seat belt to the vehicle at the outside of the front driver seat can fatigue and separate over time if the steel seat belt cable repeatedly bends down against the seat edge as the driver enters and exits the vehicle. The covering on the cable may show visible signs, including tears, holes, or wear marks. In a crash, a fatigued cable could break, and may not properly restrain the driver, increasing the risk of injury to the occupant.

GM initiated a prior safety recall related to this condition in October 2016 (NHTSA Recall No. 16V518). As part of the remedy, dealers were instructed to install a new seat trim piece with a redesigned opening for improved cable routing. The seat trim in your vehicle may not have been replaced as specified.

### What will we do?

Your GM dealer will inspect the vehicle to determine whether the new seat trim was installed and, if necessary, replace the trim. Dealers will also inspect and, if necessary, replace the pretensioner cable assembly. This service will be performed for you at no charge. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual inspection and service correction time of approximately 55 minutes.

### What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

### Did you already pay for this repair?

Even though you may have previously had repairs for this condition, you will still need to take your vehicle to your dealer for additional repairs. If you have already paid for repairs for the recall condition, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170.

### Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 20V638.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Maryann L. Combs  
Vice President  
Global Vehicle Safety

Enclosure  
GM Recall: N202312100