



Mercedes-Benz

Campaign No. 2020110007, December 2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model GLA-Class (156 platform)**
Model Year 2019
Check Mounting of Engine Fuse Box

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2019 GLA-Class (156 platform) vehicles, the mounting of the engine compartment fuse box housing might not meet current production specifications. If the screw connection securing the engine compartment fuse box housing does not meet current production specifications, it could loosen over time and be subjected to vibrations. The vibrations could lead to excessive mechanical stress and damage to the fuses in the fuse box housing, causing contact interruption and preventing the availability of certain vehicle functions including engine operation, power steering assist, ESP system, and Active Brake Assist, which could increase the risk of a crash. An authorized Mercedes-Benz dealer, will check the mounting of the engine compartment fuse box on the affected vehicles and correct it, if necessary.

Prior to performing this Recall Campaign:

- **VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.**
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Approximately 48 vehicles are involved.

Order No. P-RC-2020110007

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Work procedure

1. Open hood.
2. Check all three threaded connections (**Figure 1**) for correct seating of the nuts and retighten with 6 **Nm** of torque.



Figure 1

Warranty Information

Operation: Correct torque of mounting nuts at control unit box (02-1031)

Damage Code	Operation Number	Labor Time (hrs.)
54 940 22 8	02-1031	0.2

i Note

Operation Number labor times are subject to change.