

Safety Recall: 2013-15 ILX and 2013 ILX Hybrid Driveshaft Failure

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2013-15	ILX	TBD	Check the iN VIN status for eligibility.
2013	ILX Hybrid	TBD	Check the iN VIN status for eligibility.

BACKGROUND

Due to improper manufacturing, the paint on the driveshaft may peel and chip over time, exposing the bare metal and potentially causing it to corrode. A corroded driveshaft can potentially break during high torque conditions rendering the vehicle unmoveable, or allow the vehicle to roll while in Park, which can increase the potential of a crash or injury.

If this temporary placeholder bulletin appears during an iN VIN status inquiry, the vehicle is subject to a safety recall. Any affected vehicles in your dealer inventory are on **STOP SALE** until further notice. Check for an iN message for further details.

Since the complete VIN information is in the process of being determined, the model listed under AFFECTED VEHICLES should be treated as a **potentially affected vehicle** at this time. Accordingly, American Honda is providing the verbiage below to facilitate service of these potentially affected vehicles. If a potentially affected vehicle arrives for service, you must advise them that their vehicle may be subject to a recall, and you must document that you advised them. The following suggested text should be included on the repair order. This information should be printed out completely any time service is conducted on a vehicle within the model/year range listed above. Once VIN specific information is available, the normal procedures under DOM 7.2.1 will apply for this recall.

Suggested verbiage to be included on the repair procedure:

“Client advised that:

The vehicle may be subject to one or more recalls affecting the driveshaft. The VIN information to identify the affected vehicles is currently unavailable. Once the affected VINs are identified, the registered owner of the vehicle will receive a notice to bring the vehicle in for replacement of the component.”

This bulletin will be updated once the VIN and Parts Information are available.

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.