



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 29, 2021

Charlie Zhang
One More Auto Parts Inc.
101 E Huntington Dr Ste 102
Arcadia, CA 91006

NEF-107KL
21E-058

Subject: Replacement Headlights are Too Bright/FMVSS 108

Dear Charlie Zhang:

This letter serves to acknowledge One More Auto Parts Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

LASFIT/LED HEADLIGHT BULB/9999

Mfr's Report Date: June 28, 2021

NHTSA Campaign Number: 21E-058

Components:

EXTERIOR LIGHTING:HEADLIGHTS:BULBS

Potential Number of Units Affected: 1,665

Problem Description:

One More Auto Part, Inc. is recalling certain Lasfit aftermarket headlight bulbs model TX002/9005FBA, TX002/9006FBA, TX001/H7FBA, EX-PLA9012FBA, TX001/9004FBA, TX001/9007FBA, TX002/H4FBA, TX002/H13FBA, sizes 9004, 9005, 9006, 9007 only sold through Amazon.com. The aftermarket headlight bulbs are too bright during the first ten minutes of use. As such these bulbs fail to comply with Federal Motor Vehicle Safety Standards (FMVSS) number 108, "Lamps, Reflective Devices, and Assoc. Equipment."

Consequence:

Excessive brightness can decrease the visibility for oncoming drivers, increasing the risk of a crash.

Remedy:

Dealers will provide a full refund or replace the bulbs, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact One More Auto Parts by email at recall2021@onemoreauto.com.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

As required in Part 573.6(c)(7), in the case of a noncompliance, please provide the test results and other information used to determine the existence of the noncompliance. Include the date of each test and observation that indicated that a noncompliance might or did exist.

AMENDED 573 REQUIRED.

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

One More Auto Parts Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is written in a cursive style with a checkmark at the end.

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement