

# Part 573 Safety Recall Report

# 21T-014

**Manufacturer Name :** Cooper Tire & Rubber Co.**Submission Date :** AUG 27, 2021**NHTSA Recall No. :** 21T-014**Manufacturer Recall No. :** 171**Manufacturer Information :**

Manufacturer Name : Cooper Tire &amp; Rubber Co.

Address : 701 Lima Avenue

Findlay OH 45840

Company phone : 4194206040

**Population :**

Number of potentially involved : 327

Estimated percentage with defect : 100 %

**Tire Information :**

Tire Brand 1 : Cooper

Tire Line : Evolution H/T

Tire Size : 245/70R16

**Descriptive Information :** The recall population for the subject tires with the incorrectly marked date code was based on production curing records. The subject recalled tires differ from those not included in the recall because the date code portion of the Tire Identification Number (TIN) is incorrectly molded as "1723" vs "2317" for those tires marked correctly.

Production Dates : JUN 04, 2017 - JUN 10, 2017

**TIN (Tire Identification Number)**

Plant ID	Size code	Optional Code	Begin M Code	End M Code
UT	9H	1J9	1723	1723

**Description of Noncompliance :**

**Description of the Noncompliance :** The subject tires date code portion of the Tire Identification Number (TIN) incorrectly states the week and year of manufacture on the intended outboard side: correct week and year of manufacture is 2317 and the subject tires are incorrectly marked 1723.

FMVSS 1 : 139 - New pneumatic radial tires for light vehicles

FMVSS 2 : 574 - Tire Identification &amp; Recordkeeping

**Description of the Safety Risk :** After the 17th week of 2023, a consumer who has one of these tires could believe it was manufactured in 2023 when it was manufactured in 2017. NHTSA believes this could be confusing to the consumer because Cooper Tire recommends that tires be replaced if 10 years have passed since the date of manufacture.

**Description of the Cause :** During the week of June 4, 2017, mold preparation personnel were cleaning

mold piece number 68693-2. During the course of cleaning, the serial week slug was inadvertently dislodged. A new slug was created which incorrectly transposed the 2-character week and the 2-character year. The new slug was then inserted into the mold and 327 tires were cured with the incorrect date code.

Identification of Any Warning that can Occur : Not applicable

## Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

On April 26, 2018, Cooper Tire was notified by a tire dealer in Cleveland, Ohio that it received a tire molded with serial week of "1723". Cooper Tire alerted the Quality Assurance Department which initiated a review of tire field reports and an internal investigation and a product shipping restriction.

The internal review revealed that the tire stamped "1723" was cured in mold piece number 68693-2 at Cooper's Texarkana facility. Mold #68693-2 was cleaned during the 23rd week of 2017. During this routine cleaning, the serial week/year slug was unintentionally removed and had to be replaced. A new slug was created which incorrectly transposed the 2-character week and the 2-character year and was inserted into the mold. After the incorrect slug was inserted into the mold, 327 tires were cured during that serial week.

There are no adjustments, personal injuries or property damage claims relating to the subject tires.

Cooper Tire submitted Part 573 Safety Recall Report 18T005 on May 4, 2018, and on May 21, 2018, filed a petition for decision for inconsequential noncompliance determination pursuant to 49 CFR 556. On August 23, 2021, we were informed by NHTSA that the petition was denied resulting in the determination that a recall was

required. NHTSA requested a new Part 573 Safety Recall Report be submitted.

## Description of Remedy :

Description of Remedy Program : All subject tires will be replaced by tires featuring a compliant date code portion of the TIN at no charge to the customer. Instructions to dealers will specify any tire removed under this recall to be rendered unsuitable for resale for installation on motor vehicles prior to returning to Cooper for credit. Customers will be notified by this action not later than October 1, 2021. The consumer notification letter will be sent to NHTSA for review and approval prior to being mailed. All recall tires returned to Cooper will be used by our recycler for various recycling purposes.

How Remedy Component Differs from Recalled Component : The remedy tires will contain a compliant date code portion of the TIN.

Identify How/When Recall Condition was Corrected in Production : The mold with the incorrect ordering of the serial week and year "1723" was removed from production on June 10, 2017, at the completion of the production run. The mold slug with the incorrectly ordered serial week and year date code was removed.

## Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : OCT 01, 2021 - OCT 31, 2021

Planned Owner Notification Date : OCT 01, 2021 - OCT 31, 2021

## Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported