OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-069

Manufacturer Name: Newmar Corporation

NHTSA Recall No.: 21V-069

Manufacturer Recall No.: 21V-018



Manufacturer Information:

Manufacturer Name: Newmar Corporation

Address: 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone: 574-773-7791

Population:

Number of potentially involved : 5 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2021-2021 Newmar Kountry Star Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information : On certain motorhomes built on a Freightliner Chassis, A single caliper-mounting bolt

may be under torqued. One of the six brake caliper mounting bolts on the driver side steer axle may be incorrectly torqued. This could result in surrounding caliper bolts to loosen. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

Kountry Star=4

Production Dates: AUG 03, 2020 - SEP 08, 2020

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2021-2021 Newmar Ventana

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: On certain motorhomes built on a Freightliner Chassis, A single caliper-mounting bolt

may be under torqued. One of the six brake caliper mounting bolts on the driver side steer axle may be incorrectly torqued. This could result in surrounding caliper bolts to loosen. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

Ventana= 1

Production Dates: AUG 03, 2020 - SEP 08, 2020

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: On certain motorhomes built on a Freightliner Chassis, A single caliper-

mounting bolt may be under torqued. One of the six brake caliper mounting bolts on the driver side steer axle may be incorrectly torqued. This could result in surrounding caliper bolts to loosen. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake

effectiveness could lead to a vehicle crash.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Reduced brake effectiveness could lead to a vehicle crash.

Description of the Cause: A single caliper-mounting bolt may be under torqued. One of the six brake

caliper mounting bolts on the driver side steer axle may be incorrectly torqued.

Τ

Identification of Any Warning NR

that can Occur:

Involved Components :

Component Name 1: NR
Component Description: NR

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Daimler Trucks North America LLC

Address: P.O. Box 3849

Portland Oregon 97208

Country: United States

Chronology:

On 02/05/2021, DTNA notified Newmar of a potiential safety defect. Today, 02/12/2021, Newmar is giving notice to NHTSA we are co-filing with DTNA FL-873.

Description of Remedy:

Description of Remedy Program : Potentially affected vehicles will be inspected and repaired as necessary.

Repairs will be performed by Daimler Trucks North America authorized

service facilities.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: On or before 04/13/2021, Newmar will send out Customer/Dealer

letters.

Planned Dealer Notification Date: APR 13, 2021 - APR 13, 2021 Planned Owner Notification Date: APR 13, 2021 - APR 13, 2021

* NR - Not Reported