Population:

Part 573 Safety Recall Report

Manufacturer Name :Autocar, LLCSubmission Date :SEP 17, 2021NHTSA Recall No. :21V-093Manufacturer Recall No. :ACX-2102 DC-2101

Manufacturer Information :

Manufacturer Name : Autocar, LLC Address : 551 S WASHINGTON STREET HAGERSTOWN IN 47346 Company phone : 7654895499

Vehicle Information :

Vehicle 1:	2019-2021 Autocar Xpeditor	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :	OTHER	
Power Train :	NR	
Descriptive Information :	All units equipped with MRS 7" display are included, Xpeditor and Legend products MY 2019 to 2021.	
Production Dates :	MAR 13, 2019 - DEC 07, 2020	
VIN Range 1 : Begin : 5VCACLEF4KC229795 End : 5VCACLAF2MC234843 📝 Not sequential		
Vehicle 2:	2021-2021 Autocar Legend	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :	OTHER	
Power Train :	NR	
Descriptive Information :	All units equipped with MRS 7" display are included, Xpeditor and Legend products	
-	MY 2019 to 2021.	
Production Dates :	JUL 30, 2020 - SEP 30, 2020	
VIN Range 1:	Begin : 5VCCCLEG0MC234061 End : 5VCCCLEH1MC234451 📝 Not sequential	

Description of Noncompliance :

Description of the
Noncompliance :The display may restart during operation and the warning icons (telltales) for
the Seat Belt, Low Air, Check Engine, ABS, Park Brake Applied, Turn Signal
Indicator, Fuel Level, Electrical Charge, Coolant Temperature and Oil Pressure
will not be visible until restart has completed.FMVSS 1 :101 - Control and displays
FMVSS 2 :Description of the Safety Risk :If the display restarts during operation, the driver will temporary not have

21V-093



Number of potentially involved : 870 Estimated percentage with defect : 5 %

Part 573 Safety Recall Report

21V-093

Description of the Safety Risk :visibility of the required warning icons, increasing the risk of personal injury,
property damage or a crash.Description of the Cause :A potential memory overload or software issue.Identification of Any Warning
that can Occur :None.

Involved Components :

Component Name 1 : MRS 7" Display

Component Description : Dash Display

Component Part Number: Autocar A1431060-001, MRS MC7-NSP0430

Supplier Identification :

Component Manufacturer

Name : MRS Electronic Address : 2149 Winners Circle Dayton Ohio 45404 Country : United States

Chronology :

December 2020 Autocar field service team reported information regarding an intermittent display restart in some units. An internal corrective action was generated at that time and an investigation began. January-February 2021 Autocar field service teams traveled to multiple up-fitter and customer locations to verify the electrical circuit integrity and re-program 205 suspect units. February 11, 2021, the field data was presented to Autocar management team and the decision was made to perform a voluntary safety recall.

Page 2

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Remedy :

Description of Remedy Program :	Autocar will voluntarily initiate an owner notification and recall of all affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter, which will describe the defect and provide instructions for scheduling the inspection/repair of the vehicle at no cost to the vehicle's owner and will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek
How Remedy Component Differs from Recalled Component :	reimbursement pursuant to Autocar's General Reimbursement Plan. The display will be replaced with a new part from a different supplier.
0	The MRS display was replaced with a new part from a different supplier, January 19, 2021. All of the MRS display inventory has been discarded.

Recall Schedule :

Description of Recall Schedule :	Customer and dealer notification will begin October 28, 2021 and end
	October 29, 2021.
Planned Dealer Notification Date :	OCT 28, 2021 - OCT 29, 2021
Planned Owner Notification Date :	OCT 28, 2021 - OCT 29, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573