#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 21V-109

Manufacturer Name: Volvo Car USA, LLC

Submission Date: MAR 05, 2021 NHTSA Recall No.: 21V-109 Manufacturer Recall No.: R10078



#### **Manufacturer Information:**

Manufacturer Name: Volvo Car USA, LLC

Address: 270 Three Point Drive

Ridgeville SC 29472

Company phone: 201-768-7300

## **Population:**

Number of potentially involved : 2,278 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2021-2022 VOLVO XC40 Recharge

Vehicle Type: LIGHT VEHICLES

Body Style: SUV

Power Train: HYBRID ELECTRIC

Descriptive Information: Concerned vehicles were certain 2021-2022 XC40 Recharge from start of production

to new software introduction February 24, 2021. A fault in the Battery Energy Control Module (BECM) micro-processor operating system causing a BECM micro-processor reset. Supplier's responsibility due to BECM software with a faulty micro-processor operating system. Volvo Cars centrally has not received any reports alleging injuries,

fatalities, or crashes related to this condition.

Production END Date should be 02/19/2021 NHTSA system would not accept use of

date 02/19/2021

Production Dates: MAR 13, 2020 - FEB 18, 2021

VIN Range 1: Begin: YV1XZEDVEM2390187 End: LYVXZEDAENL640019 ✓ Not sequential

### **Description of Defect:**

Description of the Defect: Volvo Cars investigations have identified that there is a risk that a micro-

processor reset in the Battery Energy Control Module (BECM) may cause the

High Voltage contactors to open during driving.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In a worst-case scenario during driving, without any initial warning, there

may be a risk that the high voltage system gets unintentionally disconnected. Worst case scenario is loss of propulsion during driving leading to increased

risk of crash and injury. Full steering and brake capability remain.

Volvo Cars centrally has not received any reports alleging injuries, fatalities,

or crashes related to this condition.

Description of the Cause: A fault in the BECM micro-processor operating system causing a BECM micro-

processor reset.

Supplier responsibility.

Identification of Any Warning Worst case scenario is loss of propulsion during driving. Full steering and

that can Occur: brake capability remain.

## **Involved Components:**

Component Name 1: BECM software with updated micro-processor operati

Component Description: BECM software with updated micro-processor operating system

Component Part Number: NR

## **Supplier Identification:**

## **Component Manufacturer**

Name: Lear Automatic Electronics

Address: No 5 Building, No. 509, Renging RD

Shanghai Foreign States 201201

Country: China

### **Chronology:**

A. Condition considered as Critical by CCMT\* 2021-02-19

B. Field Action decision by Volvo Car Corporation 2021-02-24

C. Condition detected by? (market VR\*\*, internal, inspection, testing)

Market

D. Number of VR with the condition, reported to Volvo Cars from NSC?

E. Total number of cars included in VRs concerning the condition?

F. Implementation date 2021-02-24

\*Critical Concern Management Team, \*\* vehicle reports

## **Description of Remedy:**

Description of Remedy Program: To remedy the concerned vehicles Volvo Cars needs to perform a Software

Upgrade at no charge to the customer.

An authorized Volvo retailer will update the vehicle software.

How Remedy Component Differs Concerned vehicles were certain 2021-2022 models as XC40 Recharge

from Recalled Component: electric vehicles which will receive the updated software update.

Identify How/When Recall Condition Concerned vehicles are XC40 Recharge from start of production to new

was Corrected in Production: software introduction February 24, 2021.

#### **Recall Schedule:**

Description of Recall Schedule: REMEDY NOTES

Planned Dealer Notification Date : FEB 24, 2021 - FEB 24, 2021 Planned Owner Notification Date : MAY 18, 2021 - MAY 18, 2021

\* NR - Not Reported