Part 573 Safety Recall Report

Manufacturer Name : LGS Industries, Inc. Submission Date : MAR 12, 2021 NHTSA Recall No.: 21V-175 Manufacturer Recall No.: 20210312SCU

Manufacturer Information :

Manufacturer Name : LGS Industries, Inc. Address: PO Box 339 **BRISTOL IN 46507-0339** Company phone : 574-848-5665

Vehicle Information :

Vehicle 1:	2021-2021 LGS Industries SCU
Vehicle Type :	TRAILERS
Body Style :	
Power Train :	NR
Descriptive Information :	The total number of model SCU affected by this recall, represent the total number of trailers built in this configuration. This model is the only type of trailer built under the brands LOOK, Pace American, Cargo Express, Formula and Impact, in this configuration that would require its being involved in the recall.
Production Dates :	NOV 01, 2019 - JAN 03, 2021
VIN Range 1:	Begin : 53BFTEA19MB004257 End : 53BLTEB25MT031489 Vot sequential

Description of Defect :

Description of the Defect :	A decal that warns of an asphyxiation danger was not installed inthe trailers affected by the recall
FMVSS 1 :	101 - Control and displays
FMVSS 2 :	NR
Description of the Safety Risk :	If the customer uses the bed and an internal combustion engine in the same confined area, asphyxiation and death could occur if the customer does not heed the warning on the decal.
Description of the Cause :	Oversight on the part of engineering did not include the decal in the bill of materials.
Identification of Any Warning that can Occur :	No warning. Decal is not present.

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573



21V-175

Population :

Number of potentially involved : 60 Estimated percentage with defect : 100 %

Part 573 Safety Recall Report

21V-175

Component Name 1: Asphyxiation Danger Decal

Component Description : warning decal

Component Part Number : N100-021

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

A review of the bill of materials by engineering for the affected trailers revealed that the decal was not included. Realizing this oversight, the recall process was immediately initiated.

Description of Remedy :

Description of Remedy Program :	Letters will be sent to our dealers and customers informing them of the recall and ask them to contact our customer service department. Once the customer service department has been contacted, a decal will be sent with instructions for the proper application and verification that the decal has been applied. Our dealers will be compensated for their time of 15 minutes once they have completed the necessary paperwork. Quarterly reports will be submitted to monitor the progress of the recall.		
How Remedy Component Differs from Recalled Component :	The remedy component and the recall component are the same item.		
	Any trailer that is in current production has been identified through a document inspection and will include the decal as part of the production process.		
Recall Schedule :			
Description of Recall Schedule : Information gathering for the affected trailers will begin immediately.			
Description of Recail Schedule.	Dealer and customer letters will be drafted and prepared to be set out. Revisions will be made to the letters and they will be sent.		
Planned Dealer Notification Date :	5		

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

21V-175

Planned Owner Notification Date : APR 19, 2021 - MAY 10, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573