OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 21V-258

**Manufacturer Name:** Newmar Corporation

NHTSA Recall No.: 21V-258
Manufacturer Recall No.: 21V-214



#### **Manufacturer Information:**

Manufacturer Name: Newmar Corporation

Address: 355 North Delaware Street

PO Box 30 Nappanee IN 46550

1 O box 30 Nappanee IN

Company phone: 574-773-7791

# **Population:**

Number of potentially involved: 19 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2021-2021 Newmar London Aire Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, the steering output shaft inside the steering column may be

too short and could disengage from the steering input shaft during a full telescope of the steering column/wheel. A disengagement of the steering output shaft from the steering input shaft could result in a loss of steering control increasing the risk of a

crash. London Aire=2

Production Dates: JAN 04, 2021 - MAR 16, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2021-2021 Newmar Dutch Star

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, the steering output shaft inside the steering column may be

too short and could disengage from the steering input shaft during a full telescope of the steering column/wheel. A disengagement of the steering output shaft from the steering input shaft could result in a loss of steering control increasing the risk of a

crash. Dutch Star=6

Production Dates: JAN 04, 2021 - MAR 16, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

FMVSS 1: NR FMVSS 2: NR

W 14 1 0		NT 4.			
	2021-2021 Newmar New Aire				
	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :					
Power Train :	NR				
	On certain motorhomes, the steering output shaft inside the steering column may be too short and could disengage from the steering input shaft during a full telescope of the steering column/wheel. A disengagement of the steering output shaft from the steering input shaft could result in a loss of steering control increasing the risk of a crash. New Aire=1				
Production Dates :	JAN 04, 2021 - N	MAR 16, 2021			
VIN Range 1:	Begin:	NR	End: N	R	☐ Not sequential
Vehicle 4:	2021-2021 Newmar Ventana				
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :					
Power Train :	NR				
Descriptive Information :	On certain motorhomes, the steering output shaft inside the steering column may be too short and could disengage from the steering input shaft during a full telescope of the steering column/wheel. A disengagement of the steering output shaft from the steering input shaft could result in a loss of steering control increasing the risk of a crash. Ventana=7				
<b>Production Dates:</b>	JAN 04, 2021 - N	MAR 16, 2021			
VIN Range 1:	Begin:	NR	End: N	R	■ Not sequential
Vehicle 5:	2021-2021 Newmar Mountain Aire				
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :					
Power Train :	NR				
Descriptive Information :	On certain motorhomes, the steering output shaft inside the steering column may be too short and could disengage from the steering input shaft during a full telescope of the steering column/wheel. A disengagement of the steering output shaft from the steering input shaft could result in a loss of steering control increasing the risk of a crash. Mountain Aire=3				
<b>Production Dates:</b>	JAN 04, 2021 - N	MAR 16, 2021			
VIN Range 1:		NR	End: N	R	■ Not sequential
					_
Description of Defect :					
Description of the Defect : A disengagement of the steering output shaft from the steering input shaft could result in a loss of steering control increasing the risk of a crash.					

Description of the Safety Risk: A disengagement of the steering output shaft from the steering input shaft

could result in a loss of steering control increasing the risk of a crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

# **Involved Components:**

Component Name 1: steering output shaft

Component Description: NR Component Part Number: NR

#### **Supplier Identification:**

### **Component Manufacturer**

Name: Spartan Chassis, Shyft Group

Address: 1000 Reynolds Road

Charlotte Michigan 48813

**Country: United States** 

#### **Chronology:**

On 04/07/2021, Newmar was made aware of a potential safety defect by the Shyft Group. Today, 04/13/2021, Newmar is giving notice of a safety defect on Spartan chassis.

#### **Description of Remedy:**

Description of Remedy Program: The Shyft Group will be conducting this recall in its entirety. The steering

output shaft will be inspected for the appropriate length. If the steering output shaft is determined to be shorter than required, the steering

column will be replaced at no charge to the customer.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

The information contained in this report was submitted pursuant to 49 CFR §573

#### **Recall Schedule:**

Description of Recall Schedule: On or before 06/11/2021 customer and dealer letters will be sent out.

Planned Dealer Notification Date : JUN 11, 2021 - JUN 11, 2021 Planned Owner Notification Date : JUN 11, 2021 - JUN 11, 2021

\* NR - Not Reported